

ASS. REC. BY:

REF:

TP / CS/TP 18008265 / Ksbor

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S113 9563C

Yr Regn:

04, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Chevrolet Epic

c.c

1991

Colour:

White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

70374P

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

K21LA 69RJB 124464

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

6

mm

R/Bal.

9

mm

L/Bal.

6

mm

L/Bal.

9

mm

D.O.A.

25/4/18

D.O.I.

4/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fr

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

H/S

H/S pass to Catherine

SHB 9563C - CCH/AXA/17017033 / M10032-1

DOF: 210317

C/L @ 4250/-

31/01/19

Confirmed H/S @ 4,250/- @ 3 days with Kenneth
(\$ 17,999.19 Red - 81%)

independent report

RECEIVED 31 JAN 2019

Date/Time, File Pass to?

31/01/19

1)

Type

Date/Time, File Return to?

2)

☐

: Prell. Report

☒

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

12x15

170+180

50

50

20

80

550

Report Format:

Independent

Lump Sum / I.B.I. (\$

4,250/- H/S

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/04/2018 11:19
Date Of Accident	25/04/2018 20:30
Exact Location Of Accident	DUNEARN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB9563C
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	OH CHYE SOON
NRIC No	S6839810Z
Date Of Birth	18/10/1968
Occupation	OUTDOOR
Date Of Driving Pass	04/07/2005
Driving Experience	12 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91287127
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 470A FERNVALE LINK #07-412
Postcode	791470
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180426/2110

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name OH CHYE SOON

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHB9563C

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pl's see attach police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180426/2110

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180426/2110

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/04/2018 16:31	Vide Report No.:	Station Diary No.:
--------------------------------------------	------------------	--------------------

Informant's Particulars

Name of Informant: OH CHYE SOON			Address: APT BLK 470A FERNVALE LINK #07-412 HDB-KANGKAR SINGAPORE 791470		
ID Type / ID No.: NRIC NO / S6839810Z			Contact No.: Home/Office: Mobile: 91287127		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 49	Date of Birth: 18/10/1968	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3,4,5 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 25/04/2018 20:30	Type of Location:
Location: Along Road 1 DUNEARN ROAD DUNEARN ROAD NEAR BINJAI PARK				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB9563C	TAXI					0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL		



**SINGAPORE
POLICE FORCE**



T/20180426/2110

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180426/2110

CONTINUATION OF REPORT

Driver			
Name	OH CHYE SOON		ID No. S6839810Z
Related Vehicle	NIL		Contact No. 91287127
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL		Class of Driving Licence & Expiry Date Class: 3,4,5 Date of Expiry: NIL
Date Treatment	25/04/2018		Date Discharge 26/04/2018
No. of Days granted Medical Leave	05	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION

I WAS TRAVELLING ON THE EXTREME LEFT LANE OF THE 3-LANE ROAD. THERE WAS A CAR THAT WAS SLIGHTLY INFRONT OF ME ON THE MIDDLE LANE. I DO NOT KNOW WHAT THE VEHICLE NUMBER OF THE CAR IS. THE CAR SUDDENLY TURNED LEFT AND HIT THE RIGHT SIDE OF MY VEHICLE. THE COLLISION CAUSED MY VEHICLE TO TURN TO THE LEFT AND MADE MY DRIVER DOOR CANNOT OPEN. AFTER THE ACCIDENT I FELT PAIN SO I CALLED FOR THE AMBULANCE. THE CAR MOVED FORWARD AND PARKED AT THE CALTEX INFRONT. HE MADE HIS WAY TO ME. WHILE I WAS TALKING ON THE PHONE, HE JUST WENT OFF. AMBULANCE CAME AND CONVEYED ME TO NUH WHERE I WAS HOSPITALISED FOR 1 DAY AND RECEIVED 5-DAYS MC.



**SINGAPORE
POLICE FORCE**



T/20180426/2110

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180426/2110

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
MUHAMMAD SYUKRI BIN ABU BAKAR

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt RAZIZ BIN TAHAR
Contact No.: 65476200

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
26/04/2018 16:31

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature: _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB9563C
Vehicle to be Exported:	Yes
Intended De-registration Date:	27 Apr 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1462220K
Chassis No.:	KL1LA69RJBB124464
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,189.00
Original Registration Date:	02 Apr 2013
First Registration Date:	02 Apr 2013
Transfer Count:	0
Actual ARF Paid:	\$14,189.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Apr 2021
PARF Rebate Amount:	\$9,932.00

Intended COE Rebate Details

COE Expiry Date:	01 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$64,990.00
COE Rebate Amount:	\$23,804.00
Total Rebate Amount:	\$33,736.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Apr 2018

OK

Trans-cab Auto Services Pte Ltd**AAD1804-271**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9563C

Not Authorised
1/1/2018

Vehicle No.:

SHB 9563C

Chassis No.:

KL1LA69RJB124464

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

25.4.2018

Third Party Insurer :

PART			LIST		
1	1	Front Bumper	\$	Bu 1,202.00	✓
2	1	Front Bumper Lower Absorber	\$	Sn 180.00	X
3	1	Front Bumper Reinforcement	\$	R 356.00	X
4	1	Front Bumper Retainer RH	\$	Dit 102.00	✓
5	1	Front Bumper Retainer LH	\$	Sn 102.00	X
6	1	Front Bumper Lower Grille	\$	Sn 78.00	X
7	1	Front Bumper Lower Stiffener	\$	R 134.37	X
8	1	Front Bumper Bracket LH	\$	R 10.00	X
9	1	Front Bumper Bracket RH	\$	R 10.00	X
10	1	Bumper Fog Lamp Cover RH	\$	Sn 32.40	X
11	1	Bumper Fog Lamp Cover LH	\$	Sn 32.40	X
12	1	Headlamp RH	\$	CM 816.00	✓
13	1	Headlamp RH inner panel	\$	R 611.16	X
14	1	Front Fender RH	\$	R 837.60	✓
15	1	Front Fender Liner RH	\$	Dit 47.00	✓
16	1	Front Fender Inner Wheel House Panel RH	\$	R 1,437.00	X
17	1	Front Shock Absorber Assy RH	\$	R 216.17	✓
18	1	Front Shock Absorber Top Mounting RH	\$	R 48.32	✓
19	1	Front Lower Arm RH	\$	R 283.00	✓
20	1	Front Knuckle Arm RH	\$	R 230.00	✓
21	1	Front Hub Unit	\$	R 376.00	✓
22	1	Front Disc Brake RH	\$	Sn 157.55	X
23	1	Front Strut Bar Bracket RH	\$	R 235.01	} X
24	1	Front Stabilizer Bar	\$	Sn 234.00	
25	1	Front Stabilizer Bar Link RH	\$	Sn 51.79	
26	1	Front Stabilizer Bar Bracket RH	\$	R 105.75	
27	1	Front Stabilizer Bar Bush RH	\$	Sn 66.00	
28	1	Front Beam A - Impact RH	\$	R 214.00	
29	1	Bonnet Panel	\$	R 1,250.00	✓

Trans-cab Auto Services Pte Ltd

AAD1804-271

No. 2, Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9563C

30	1	Bonnet under weatherstrip seal	\$	SH	105.00	}
31	1	Bonnet hinge RH	\$	H	36.00	
32	1	Bonnet hinge LH	\$	H	36.00	
33	1	Bonnet Moulding (Garnish A-Hood)	\$	SH	161.97	
34	1	Bonnet Door Switch (Switch A-Contact.Hood	\$	SH	11.00	
35	1	Bonnet lock	\$	H	60.00	
36	1	Bonnet cable	\$	SH	125.00	
37	1	Bonnet damper stay RH	\$	SH	125.00	
38	1	Bonnet damper stay LH	\$	SH	125.00	
39	1	Bonnet insulator	\$	SH	400.00	
40	1	Bonnet centre logo badge	\$	VA	60.00	
41	1	Horn Unit (Low Tone)	\$	SH	53.46	
42	1	Horn Unit (High Tone)	\$	SH	53.46	
43	1	Front Support Panel Assy	\$	H	1,222.32	
44	1	Front brace panel	\$	H	134.37	
45	1	Windscreen Washer Tank (Reservoir A-W/Shield)	\$	SH	62.00	}
46	1	Windscreen Washer Tank Motor (Pump Wswa)	\$	SH	51.00	
47	1	TANK, WIPER HOSE	\$	SH	21.00	
48	1	Radiator Assembly (Radiator A	\$	SH	618.00	
49	1	Front Door RH	\$	H	1,133.00	

TOTAL	\$	14,049.10
10%	\$	1,404.91
	\$	12,644.19

Specical Nett

1	1 Set	Front Fender Liner clip LH	\$	SH	30.00	✓
2	1 Set	Louver Cowl Top clip	\$	SH	30.00	X
3	1	Front right tyre rim	\$	L.P. SH	380.00	50SH
4	1	Front right tyre	\$	SH	300.00	60SH
5	2	Bonnet stopper	\$	SH	15.00	X
6	6	Bonnet under weatherstrip seal clips	\$	SH	30.00	X
7	10	Bonnet insulator clip	\$	SH	30.00	X

TOTAL	\$	815.00
--------------	-----------	---------------

Trans-cab Auto Services Pte Ltd

AAD1804-271

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9563C

TOTAL PARTS	\$	13,459.19
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	5001
Putty and spray painting of the affected portion.	\$	3,200.00	6001
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	440.00	an X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	an X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	an X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	1801
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	an X
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	an X

TOTAL	\$	8,790.00
--------------	-----------	-----------------

Over All Total	\$	22,249.19
-----------------------	-----------	------------------

Repair Days**10 DAYS**

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP18008265/Ksbe2		
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 01-02-2019		
		Code : TP378		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SHB 9563C	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		04/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET EPICA (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KL1LA69RJBB124464	Colour	WHITE / RED	
Odometer	703749	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GITI	6 mm	
L/H Front Tyre	195/65 R15	GITI	6 mm	
R/H Rear Tyre	195/65 R15	GITI	9 mm	
L/H Rear Tyre	195/65 R15	GITI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2018	Inspection Date	04/05/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9563C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	1,202.00	1,202.00
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	356.00	-
1	FRONT BUMPER RETAINER RH	DISTORTED	102.00	102.00
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	-
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	10.00	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	10.00	-
1	BUMPER FOG LAMP COVER RH	SERVICEABLE	32.40	-
1	BUMPER FOG LAMP COVER LH	SERVICEABLE	32.40	-
1	HEADLAMP RH	CRACKED	816.00	816.00
1	HEADLAMP RH INNER PANEL	TO REPAIR SEE LABOUR	611.16	-
1	FRONT FENDER RH	BENT	837.60	837.60
1	FRONT FENDER LINER RH	DISTORTED	47.00	47.00
1	FRONT FENDER INNER WHEEL HOUSE PANEL RH	TO REPAIR SEE LABOUR	1,437.00	-
1	FRONT SHOCK ABSORBER ASSY RH	BENT	216.17	216.17
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	BENT	48.32	48.32
1	FRONT LOWER ARM RH	BENT	283.00	283.00
1	FRONT KNUCKLE ARM RH	BENT	230.00	230.00
1	FRONT HUB UNIT	BENT	376.00	376.00
1	FRONT DISC BRAKE RH	SERVICEABLE	157.55	-
1	FRONT STRUT BAR BRACKET RH	TO REPAIR SEE LABOUR	235.01	-
1	FRONT STABILIZER BAR	SERVICEABLE	234.00	-
1	FRONT STABILIZER BAR LINK RH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR BRACKET RH	TO REPAIR SEE LABOUR	105.75	-
1	FRONT STABILIZER BAR BUSH RH	SERVICEABLE	66.00	-
1	FRONT BEAM A - IMPACT RH	TO REPAIR SEE LABOUR	214.00	-

Report Ref No. CS/TP18008265/Ksbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET PANEL	TO REPAIR SEE LABOUR	1,250.00	-
1	BONNET UNDER WEATHERSTRIP SEAL	SERVICEABLE	105.00	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET MOULDING (GARNISH A-HOOD)	SERVICEABLE	161.97	-
1	BONNET DOOR SWITCH (SWITCH A-CONTACT.HOOD)	SERVICEABLE	11.00	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	60.00	-
1	BONNET CABLE	SERVICEABLE	125.00	-
1	BONNET DAMPER STAY RH	SERVICEABLE	125.00	-
1	BONNET DAMPER STAY LH	SERVICEABLE	125.00	-
1	BONNET INSULATOR	SERVICEABLE	400.00	-
1	BONNET CENTRE LOGO BADGE	NOT NECESSARY	60.00	-
1	HORN UNIT (LOW TONE)	SERVICEABLE	53.46	-
1	HORN UNIT (HIGH TONE)	SERVICEABLE	53.46	-
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	1,222.32	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	134.37	-
1	WINDSCREEN WASHER TANK (RESERVOIR A-W/SHIELD)	SERVICEABLE	62.00	-
1	WINDSCREEN WASHER TANK MOTOR (PUMP WSWA)	SERVICEABLE	51.00	-
1	TANK, WIPER HOSE	SERVICEABLE	21.00	-
1	RADIATOR ASSEMBLY (RADIATOR A	SERVICEABLE	618.00	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,133.00	-
	LESS 10% DISCOUNT		-1,404.91	-415.81
			12,644.19	3,742.28
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT FENDER LINER CLIP LH (SN)	NECESSARY	30.00	30.00
1	SET LOUVER COWL TOP CLIP (SN)	NOT NECESSARY	30.00	-
1	FRONT RIGHT TYRE RIM (SN) (LOCAL REPAIR)	DENTED	380.00	50.00
1	FRONT RIGHT TYRE (SN) (60%)	PUNCTURE	300.00	180.00
2	BONNET STOPPER (SN)	NOT NECESSARY	15.00	-
6	BONNET UNDER WEATHERSTRIP SEAL CLIPS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/TP18008265/Ksbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	BONNET INSULATOR CLIP (SN)	NOT NECESSARY	30.00	-
			815.00	260.00
	LABOUR			
	TO TRANSFER OF BONNET FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT BUMPER LOWER STIFFENER, FRONT BUMPER BRACKET LH, FRONT BUMPER BRACKET RH, HEADLAMP RH INNER PANEL, FRONT FENDER INNER WHEEL HOUSE PANEL RH, FRONT STRUT BAR BRACKET RH, FRONT STABILIZER BAR BRACKET RH, FRONT BEAM A - IMPACT RH, BONNET PANEL, BONNET HINGE RH, BONNET HINGE LH, BONNET LOCK, FRONT SUPPORT PANEL ASSY, }		3,500.00	500.00
	FRONT BRACE PANEL AND FRONT DOOR RH. }		-	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,200.00	600.00
	TO REMOVE AND REFIT FRONT AND REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	440.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHERS, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAFE PARTS, FINAL CHECKING AND TESTING.		380.00	180.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			8,790.00	1,300.00
GRAND TOTAL			22,249.19	5,302.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CS/TP18008265/Ksbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.