

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 04/05/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : FOONG CHIN CHEE
: AXA INSURANCE PTE LTD

Certificate No : 2100428619-02

Accident Date : 02/05/2018

Vehicle No : SGL-2898-S

Make & Model : HONDA CITYVTEC CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BOOTLID	365.20	bt ✓
1	REAR BOOTLID EMBLEM CENTRE	44.10	acc ✓
1	REAR BOOTLID EMBLEM V-TEC	55.20	acc ✓
1	REAR BOOTLID EMBLEM CITY	24.50	acc ✓
1	REAR BOOTLID LAMP LH	194.50	?
1	REAR BOOTLID LAMP RH	194.50	?
1	REAR BOOTLID INNER TRIM	140.50	X
1	REAR BOOTLID RUBBER	87.90	?
1	REAR BOOTLID LOCK	64.40	?

Date : 04/05/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : FOONG CHIN CHEE

: AXA INSURANCE PTE LTD

Certificate No : 2100428619-02

Accident Date : 02/05/2018

Vehicle No : SGL-2898-S

Make & Model : HONDA CITYVTEC CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR LAMP OUTER LH	275.60	cut ✓
1	REAR LAMP OUTER RH	275.60	cut ✓
6	REAR LAMP OUTER CLIP	21.00	✓
1	REAR BUMPER	441.40	✓
10	REAR BUMPER CLIP	39.00	✓
1	REAR BUMPER SIDE RETAINER LH	14.90	✓
1	REAR BUMPER SIDE RETAINER RH	14.90	✓
1	REAR BUMPER INNER BRACKET LH	10.00	✓
1	REAR BUMPER INNER BRACKET RH	10.00	✓
1	REAR END PANEL	419.60	?

Date : 04/05/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : FOONG CHIN CHEE

: AXA INSURANCE PTE LTD

Certificate No : 2100428619-02

Accident Date : 02/05/2018

Vehicle No : SGL-2898-S

Make & Model : HONDA CITYVTEC CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR END PANEL TOP GARNISH	80.50	?
1	SPARE TYRE PANEL	RESTORE	
1	SPARE TYRE BOARD	70.80	x
	Sub Total	2844.10	
	Discount 20% On Parts	(568.82)	
	Special Nett Item		
1	REAR BOOTLID SPOILER	450.00	eng ✓
1	REAR BUMPER SPOILER	400.00	de ✓
1	REAR NUMBER PLATE	35.00	ht ✓
1	REVERSE SENSOR	200.00	ntw ✓

Date : 04/05/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : FOONG CHIN CHEE

: AXA INSURANCE PTE LTD

Certificate No : 2100428619-02

Accident Date : 02/05/2018

Vehicle No : SGL-2898-S

Make & Model : HONDA CITYVTEC CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	END PANEL SEALANT	50.00	P
1	REAR BUMPER PROTECTOR LH	60.00	ne
1	REAR BUMPER PROTECTOR RH	60.00	ne
	Sub Total	1255.00	
<u>Labour & Misc</u>			
	LABOUR TO CARRY OUT REAR REPAIR	700.00	600
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	30
	TO SPRAY PAINTING ON REAR AFFECTED AREA	700.00	600
	SPRAY RUST PROOF ON AFFECTED AREA	60.00	40

Date : 04/05/2018

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : FOONG CHIN CHEE

: AXA INSURANCE PTE LTD

Certificate No : 2100428619-02

Accident Date : 02/05/2018

Vehicle No : SGL-2898-S

Make & Model : HONDA CITYVTEC CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO REMOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS	100.00	50.
	TO REMOVE & RE-INSTALL SPARE COMPARTMENT TRIMS	100.00	50.
	TO DETACH & RENEW REVERSE SENSOR	60.00	30
	Sub Total	1755.00	

Remarks:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUB TOTAL

GST 7.0 % 369.97

TOTAL 5,655.25

Surveyor's name:

Tanpin 97495744 'wp'

Principal's name: FOONG CHIN CHEE

Survey Date & Time: 04/05/18 @ 1130

Review after repair 5 days

Sum @ lkkauto.com

PAGE : 5