



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 02.05.2018

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE: ESTIMATE COST OF REPAIR TO VEHICLE 5LN8360S TOYOTA AXIO HYBRID 1.5 (2016)

To Supply

1) 1pc	Right rear door	\$	1,048.50	67
2) 1pc	Rear bumper	\$	700.00	RX
3) 1pc	Rear bumper clip	\$	30.00	x
4) 1pc	Rear bumper right side retainer	\$	60.00	?

Sub total parts	\$	1,838.50
Less: 25% discount	\$	(459.62)
	\$	1,378.88

L/charges

1)	To tuff kote.	\$	50.00	30.
2)	To transfer right rear door handle, trim board & mechanism parts.	\$	100.00	60.
3)	To remove rear bumper & right rear door. Knock & repair right rear fender. Replace rear bumper & right rear door. Adjust rear bumper, right rear fender & right rear door.	\$	800.00	600
4)	To putty, respray painting right rear door inlet & outer, right rear fender & rear bumper. To polish.	\$	850.00	600

Sub total L/charges	\$	1,800.00
Estimated Total	\$	3,178.88

Tanpin 93495749
3/5/18 @ 1200
WP
Resurvey after repair
sw @ 11am on
4 days