

INS. CASE OWNER:

CC 4 / ASM1800

LKK:
IDAC:

43708

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

1-6-18

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

6,748.88

Loss of Rental (LOR):

S\$

585.xx

(5

days)

Loss of Use (LOU):

S\$

-

(5

x 5

days)

Loss of Income (LOI):

S\$

250

(50

x 5

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

7,591.37

Global Sum S\$: 7,590.xx

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7,590.xx

Name 1:

COMFORTDELGR0 ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

RECEIVED 29 JUN 2018

26-6-18 @ 111 PM SPOKEN TO MS.

XIAO QVIN, CONFIRM
ACC. DETAILS, AGREED
& AWARE NCD ISSUE.
CONFIRM TO PAY EXCESS.

To request TP video.

1/6/18 OMR. Sent out 1st letter

- OLD REVERSED -

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6363 6260 Facsimile + 65 6220 6756

Workshops

58 Leong Drive Singapore 500699

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

32041 Road Singapore 600199

24 Serangoon Road Singapore 758156

7 Sungei Kadut Way Singapore 728781

6 Delu Avenue 1 Singapore 630337

Date/Time: 04.05.2018 15:25

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO: 305156573

OMER

REGN NO

SHB2191M

MILEAGE

CITYCAB PTE LTD

7010070

MAKE

HYUNDAI

FUEL

OMER NO

383 SIN MING DRIVE
Singapore SINGAPORE 575717

E.....1/2.....F

65551188

MODEL

1-40

04.05.2018 12:55

(R)

(O)

YR OF MANU

25.08.2016

TARGET DATE

(P)

CHASSIS CODE

RHHLB41UMGU093536

COMPLETION DATE/TIME:

JUNT CARD NO.

JOB DESCRIPTION

cident Date: 04.05.2018

TURE: 3P 04.05.18

NO

LABOR CODE

DESCRIPTION

KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Judgement Slip

Exit Pass

o.: SHB2191M

LIMITS

Vehicle No.:

SHB2191M

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 2191M

MAKE :

MODEL : HYUNDAI i40

AXA-cp(p)

DATE 4/5/2018

(Fri)

Lot - c8

1700

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 1,526.00
	Bonnet Hinge (LH/RH) X		\$ 91.30	\$ 182.60
	Bonnet Lock X			\$ 50.90
	Bonnet Insulator X			\$ 50.88
	Bonnet Insulator Clips X			\$ 73.92
	Radiator Grille			\$ 1,480.00
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Bracket Top (LH/RH) ?		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) ?		\$ 24.60	\$ 49.20
	Headlamp Support Top Cover ?			\$ 398.00
	Headlamp Support Panel Assy ?			\$ 1,067.50
	Headlamp (LH/RH)		\$ 1,388.00	\$ 2,776.00
	Radiator ?			\$ 850.20
	Radiator Fan Blade, Cowling, Motor Assy ?			\$ 792.95
	Radiator Bracket (RH/LH) ?		\$ 6.50	\$ 13.00
	Radiator Guard ?		\$ 35.00	\$ 70.00
	Horn Unit (LH/RH) ?		\$ 86.75	\$ 173.50
	Front Fender (LH/RH) ?		\$ 619.00	\$ 1,238.00
	Air Duct ?			\$ 206.05
	Aircon Condenser ?			\$ 1,137.35
	Inter Cooler ?			\$ 921.90
	Inter Cooler Mounting (2 PCS) ?			\$ 25.90
	SUB TOTAL			\$ 14,849.15
	LESS 20%			\$ 2,969.83
	DISCOUNTED TOTAL			\$ 11,879.32
	Labour Charge			
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Towing Fees			\$ 60.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 2,860.00
	ESTIMATE TOTAL			\$ 14,739.32
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL LABOUR

Signature:

ESTIMATE TOTAL

Kaharudin

7/5/18 1120h

307.

P/P Before Paint p/h

400

\$ 1,500.00

\$ 1,000.00

\$ 50.00

\$ 100.00

\$ 60.00

\$ 150.00

\$ 2,860.00

\$ 14,739.32

20

20

?

x

Our Job Ref No : 305156573
Date : 10/05/18

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN ANG

Fax :

Vehicle Reg No. : SHB2191M Date of Accident : 04-May-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA --- XD4422J
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$5,467.36
 - (b) Labour Charges \$840.00
 - Total for Part-By-Part Repair Cost \$6,307.36**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 10/5/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	*****			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305156573
 REGN NO : SHB2191M
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 25.08.2016
 DATE/TIME IN : 04.05.2018 12:55
 ACCIDENT DATE : 04.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0572-G	BONNET	1	1,526.00	20.00	1,220.80
0002 04-01-0103-2164-G	RADIATOR GRILLE	1	1,480.00	20.00	1,184.00
0003 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76
0004 04-01-0103-0781-A	HEADLAMP LH	1	1,388.00	20.00	1,110.40
0005 04-01-0103-0782-A	HEADLAMP RH	1	1,388.00	20.00	1,110.40

SUB-TOTAL : 5,467.36

JOB NATURE

0000 L	PANEL BEATING	400.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00

SUB-TOTAL : 840.00


COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305156573
REGN NO : SHB2191M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 04.05.2018 12:55
ACCIDENT DATE : 04.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 6,307.36


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :
AUTHORISED : YES / NO

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 2191M

MAKE :

MODEL : HYUNDAI i40

DATE 4/5/2018

AXA-cp(p) (Fri) TS
Lot - c8 1700

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 1,526.00
	Bonnet Hinge (LH/RH) X su		\$ 91.30	\$ 182.60
	Bonnet Lock X su			\$ 50.90
	Bonnet Insulator X su			\$ 50.88
	Bonnet Insulator Clips X su			\$ 73.92
	Radiator Grille			\$ 1,480.00
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Sponge X su			\$ 142.20
	Front Bumper Reinforcement X su			\$ 526.10
	Front Bumper Bracket Top (LH/RH) X su	\$	22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) X su	\$	24.60	\$ 49.20
	Headlamp Support Top Cover X su			\$ 398.00
	Headlamp Support Panel Assy X su			\$ 1,067.50
	Headlamp (LH/RH)	\$	1,388.00	\$ 2,776.00
	Radiator X su			\$ 850.20
	Radiator Fan Blade, Cowling, Motor Assy X su			\$ 792.95
	Radiator Bracket (RH/LH) X su	\$	6.50	\$ 13.00
	Radiator Guard X su	\$	35.00	\$ 70.00
	Horn Unit (LH/RH) X su	\$	86.75	\$ 173.50
	Front Fender (LH/RH) X su	\$	619.00	\$ 1,238.00
	Air Duct X su			\$ 206.05
	Aircon Condenser X su			\$ 1,137.35
	Inter Cooler X su			\$ 921.90
	Inter Cooler Mounting (2 PCS) X su			\$ 25.90
	SUB TOTAL			\$ 14,849.15
	LESS 20%			\$ 2,969.83
	DISCOUNTED TOTAL			\$ 11,879.32
	Labour Charge			
	Panel Beating			\$ 1,500.00 X su
	Spray Painting Charge			\$ 1,000.00 X su
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 100.00 20
	Towing Fees			\$ 60.00 X su
	Remove/Refix Aircon & Refill Gas			\$ 150.00 X su
	TOTAL LABOUR			\$ 2,860.00
	ESTIMATE TOTAL			\$ 14,739.32
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims on "Without Prejudice" basis
- No liability for labour allowed
- Supplies and materials to be resurveyed and is subject to confirmation from the Insurance Company

Acknowledged by: _____
Signature: _____
Date: _____

Kahar 11/11/12

7/5/12 1120h
30g.

P/P Before Paint p/LH



Service Request Details

Claim

S8M00G6C

Reference

None 

Loss Date

May 4, 2018

Request Date

May 7, 2018

Calvin

Due Date

May 14, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHB2191M

Make

TPVD HYUNDAI

Service Address

...

Primary Contact/Insured

HONTRADE ENTERPRISE PTE LTD
487 SIMS AVENUE, 387559, Singapore
65471626

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

GIA NOT REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

01 June, 2018

HONTRADE ENTERPRISE PTE LTD
487 SIMS AVENUE
SINGAPORE 387559

Dear Sir,

OUR REF : CC4/ASM18008276/K1ja3 / S8M00G6C
YOUR REF : XD 4422J

**ACCIDENT INVOLVING XD 4422J & SHB 2191M ALONG/AT EXIT GANTRY OF
CHONG PANG VISTA BLK 150-161**

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to joyirene@lkkauto.com or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

Your NCD (No Claim Discount) will be reduced by 30% (20% for motorcycle/commercial vehicles) if a claim is made under your policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6841 2409 if you have any further enquiries.

Yours sincerely,
Claim Department

This is a computer generated letter and no signature is required.

CC : AXA INSURANCE PTE LTD



Re:IA FOR QUANTUM MANDATE UPLOADED

Type

🔗 Question

Message

LIAB CLEAR FOR DS, PLS PROCEED FOR SETTLEMENT NOT EXCEEDING\$7,700.00 (ALL-IN)

Reply

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	XD 4422J (Insd veh)	Model:	HYUNDAI
	SHB 2191M (TP veh)		I40 1.7 CRDI F/L AT ABS
Date of Accident:	04/05/2018		AIRBAG 4DR

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	15,771.07
Final Repair Cost	:	\$	6,748.88
Loss of Token Sum	:	\$	250.00
Rental (if any)	:	\$	585.00
LTA / GIA Search Fee	:	\$	7.49

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum (GLOBAL SUM)	:	\$ 7,590.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____100_____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	COMFORTDELGRO ENGINEERING PTE LTD	: \$ 7,590.00

NUR SHAQILAH BTE ABDOL
WAHAB

05/07/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S8M00G6C	Vehicle Information	
Reference		Incident Vehicle	SHB2191M
CC4/ASM18008276/K11a3s Date		Registration #	TPVD HYUNDAI
May 4, 2018	Request Date	Make	I40
May 7, 2018	Due Date	Model	Primary Contact/Insured
May 7, 2019	Vendor Name		HONTRADE ENTERPRISE PTE LTD
LKK AUTO CONSULTANTS PTE Loss LTD (TP)	Type of		487 SIMS AVENUE, 387559, Singapore 65471626
Third Party Vehicle Damage	Services		Claim Handler

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Ltr to Insured -non reporting.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 1, 2018
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 1, 2018
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 1, 2018
Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 1, 2018
TP GIA/ ESTI.msg	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	May 7, 2018

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Service Request Details

Claim	S8M00G6C	Vehicle Information	
Reference CC4/ASM18008276/K11jas Date 		Incident Vehicle	SHB2191M
		Registration #	TPVD HYUNDAI
		Make	
		Service Address	
May 4, 2018	Request Date	Model	I40
May 7, 2018	Due Date	Primary Contact/Insured	
May 7, 2019	Vendor Name	HONTRADE ENTERPRISE PTE LTD	
LKK AUTO CONSULTANTS PTE Loss LTD (TP)	Type of	487 SIMS AVENUE, 387559, Singapore	
		65471626	
Third Party Vehicle Damage	Services	Claim Handler	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SHB2191M

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

08/25/2016



Mileage

200515

Age of Vehicle

1

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT...

CATEGORY

Driver Name

ASSESSMENT INFO...

2016

FNOL INFORMATI...

LIM LYE SOON

CATEGORY

Make

POST SURVEY INF...

CATEGORY	Engine No
POLICY INFORMAT...	
ASSESSMENT INFO...	D4FDGU670636
CATEGORY	Engine Capacity
POLICY INFORMAT...	
ASSESSMENT INFO...	1685 cc
CATEGORY	Sum Insured
POLICY INFORMAT...	
ASSESSMENT INFO...	0
CATEGORY	Market Value
POLICY INFORMAT...	
ASSESSMENT INFO...	0

FNOL INFORMATI...	0
POST SURVEY INF...	
CATEGORY	Driver License #
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	License Type
FNOL INFORMATI...	
POST SURVEY INF...	▼
CATEGORY	License Issue Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy
CATEGORY	License Expiration Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy
CATEGORY	Address

POST SURVEY INF...

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

HANKOOK 7mm

Rear left side

HANKOOK 7mm

Front right side

HANKOOK 7mm

Rear right side

HANKOOK 7mm

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts			
Add		Approve		Deny		EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
			1	1		BONNET			Dented	1526	20		1220.8						
			2	2		BONNET HINGE (L/H/RH)			Serviceable	0	20		0						
			3	1		BONNET LOCK			Serviceable	0	20		0						
			4	1		BONNET INSULATOR			Serviceable	0	20		0						
			5	10		BONNET INSULATOR CLIPS			Serviceable	0	20		0						
			6	1		RADIATOR GRILLE			Cracked	1480	20		1184						
			7	1		FRONT BUMPER COVER			Deformed	1052.2	20		841.76						
			8	1		FRONT BUMPER SPONGE			Serviceable	0	20		0						
			9	1		FRONT BUMPER REINFORCEMENT			Serviceable	0	20		0						
			10	2		FRONT BUMPER BRACKET TOP (L/H/RH)			Serviceable	0	20		0						

Add

Approve

Deny

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	1		PANEL BEATING.	400	0	0	Reviewing	
	2		SPRAY PAINTING CHARGE.	400	0	0	Reviewing	
	3		WIRING CHARGE.	20	0	0	Reviewing	
	4		TUFF KOTE.	20	0	0	Reviewing	
	5		TOWING FEES.	0	0	0	Reviewing	
	6		REMOVE / REFIX AIRCON & REFILL GAS.	0	0	0	Reviewing	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR	Reviewing		3	

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$6,307.36	Claim Amount	\$6,307.36	

CATEGORY

ESTIMATE

REVISED AMOUNT

Labour

\$840.00

\$840.00

Submit for Review