

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 46729  
Date Estimated : 25/04/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Ang Eng Guan  
32 Segar Road  
#17-21

- ACCOUNT - 148376  
Great American Insurance Company  
3 Temasek Avenue  
#16-01 Centennial Tower  
Singapore 039190

Singapore 677722

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKM4848X	C994560	30/01/2013	740iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace bonnet and attachments, LH support include making good the front bumper and knocking out dents caused by the accident	2125.00	-	2,125.00	
To respray front bumper and bonnet	2102.00		2,102.00	
To carry out body cavity preservation (Per panel).	100.00		100.00	
To replace LH LED technology headlight include programming and conducting tests for proper function	451.00		451.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET FLAT HEADED 6.5X14.3 *	4.30	2.00		8.60
BONNET	2,854.00	1.00		2,854.00
EMBLEM GROMMET	0.80	2.00		1.60
BMW EMBLEM	69.50	1.00		69.50
LH SPACER *	7.55	1.00		7.55
LH SUPPORT	128.45	1.00		128.45
LH HEADLIGHT WITH LED TECHNOLOGY	4,871.40	1.00		4,871.40
# LABEL COOLANT *	23.80	1.00		23.80

### # SUPPLEMENTARY ITEMS

Total Labour :	5,078.00
Total Parts :	7,964.90
Total Labour & Parts :	13,042.90
Deduction for Excess :	
Total Repair Costs less Excess:	13,042.90
GST @7%:	913.00
Grand Total :	13,955.90