

#SS. REC. BY:

REF:

CS/ICS18008381/Kqbez

Special Instruction:

Surveyor
Muhaimin

Kinanth

ASSIGNMENT (Office)

From (Person):

Janice Koh

of

ICS

Date/Time:

07052018 201pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDD 8992R

Insured:

SJR 5080Y

at Workshop m/s

Motor Image

Tel:

9090 3323

of

19 Toa Payoh Lorong 8

Policy No:

Claim No:

Dm/c 18001724

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04052018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

08052018

H.O.D. Endorsement:

Date/Time:

07052018 201pm

Person Contacted:

Mr. Kuan

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SDD 8992R - CC3 / 71110015795 / Rn1f2v2
	SJR 5080Y - x
26/10	810578.04 Cabins & (Red to 7980.48, 43%/-)

DUA: 030810

REF: TCS

ASSIGNMENT

From:

Date: 08052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SDD 8592R

at Workshop m/s:

Motor Image

of:

19 Toa Payon Lorong 8

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09

days

Res: Yes or No

Lum Sum:

1-B.1

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

9/5 file pass to Catherine

RECEIVED 07 NOV 2018

Veh No:

SDD 8992 R

Yr Regn:

08 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Legacy

Colour:

M. P. White

Sp. Reading

29015

Eng/No:

C/No:

JFIVM 4K55G 00 2555

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F:

R:

225/45R18

BS / SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

8 mm

R/Bal:

8 mm

L/Bal:

8 mm

L/Bal:

8 mm

D.O.A.

4/5/18

D.O.I.

8/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

L/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?



: Preli. Report

1: 05/11/2018



: Final Report

Date/Time: File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Other:

TOTAL

450

10

460

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

10578.04

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 7 May, 2018 2:01 PM
To: Kuan Wei Loong; ASSIGNMENTS@LKKAUTO.COM
Cc: Sayedinah; Daniel Lim; Daniel Jude; ECICS Claims
Subject: RE: SDD8992R-3RD PARTY CLAIM-DIRECT ASIA-TP(SJR5080Y)ECICS-LIABILITY STATUS-SURVEY-07/05/2018-CAR NON DRIVABLE
Attachments: SDD8992R GIA REPORT.PDF; SDD8992R ESTIMATE.PDF

Without Prejudice

Dear Wei Loong

Thank you for your email.
We will appoint LKK for the PRI.

Aside to LKK

Please assist to arrange TP PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Kuan Wei Loong [mailto:weiloong@motorimage.net]
Sent: Monday, 7 May, 2018 12:01 PM
To: ECICS Claims
Cc: Sayedinah; Daniel Lim; Daniel Jude
Subject: RE: SDD8992R-3RD PARTY CLAIM-DIRECT ASIA-TP(SJR5080Y)ECICS-LIABILITY STATUS-SURVEY-07/05/2018-CAR NON DRIVABLE
Importance: High

Hi Claims Team,

Attached is estimate.

Thank You,

Best Regards
Kuan Wei Loong
Claims Advisor
Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255
HP:90903323
Email:weiloong@motorimage.net
Website:www.tanchong.com :: www.motorimage.net


From: Kuan Wei Loong
Sent: Saturday, May 5, 2018 9:49 AM
To: claims@ecics.com.sg
Cc: Sayedinah <sayedinah@motorimage.net>; Daniel Lim <daniellim@motorimage.net>; Daniel Jude <danieljude@motorimage.net>
Subject: SDD8992R-3RD PARTY CLAIM-DIRECT ASIA-TP(SJR5080Y)ECICS-LIABILITY STATUS-SURVEY-07/05/2018-CAR NON DRIVABLE
Importance: High

Hi Claims Team,

Kindly advise liability status and survey of the above mentioned vehicle.
(07/05/2018 – CAR NON DRIVERBLE)
Estimate will attached soon.

Thank You,

Best Regards
Kuan Wei Loong
Claims Advisor
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:90903323
Email:weiloong@motorimage.net
Website:www.tanchong.com :: www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/05/2018 15:42
Date Of Accident	04/05/2018 13:20
Exact Location Of Accident	CTE TOWARDS SOUTH BUKIT TIMAH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDD8992R
Insured/Policyholder	
Name Of Registered Owner	MAH KWAI FONG VINCENT
NRIC No	S1425462E
Email Address	VINMKF@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91006382
Alternative Phone No	HOME-62818886

Vehicle Particulars

Manufacturer	SUBARU
Model	LEGACY-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT / 00404628
Cover Note Number	

Driver

Name of Driver	MAH KWAI FONG VINCENT
NRIC No	S1425462E
Date Of Birth	05/12/1960
Occupation	INDOOR
Date Of Driving Pass	20/12/1980
Driving Experience	37 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91006382
Fax Number	
Contact Number	HOME-62818886
Email Address	VINMKF@GMAIL.COM

Address	APT BLK 421 SERANGOON CENTRAL #06-382 S(550421)
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	AFTER RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO DOCUMENT.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR5080Y
Vehicle Make/Model/Colour	MITSUBISHI / LANCER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JAVE JASMINE LIM TAY MIN
NRIC/Passport Number	S9049959I
Contact Number	87829826
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving towards south at CTE, when a car A hit the brakes, I managed to stay behind. However car C could not stop on time and hit my car B from the rear.

Car A - SLG 5870T

Car B - SDD 8992R (my car)

Car C - SJR 5080Y

Car D - SFR 285U

DECLARATION

(We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 08/05/18

1412 hrs.

(Signature, Date and Time)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

[Signature]

Reporting Centre Personnel's Signature

Name:

DANIEL JUDÉ

NRIC/FIN No.: S900151&D

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 04/5/18

1412 hrs.

(Name, Signature, Date, Time)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: DANIEL JOE

NRIC/PIN No: S90015180

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0758/2018
DATE : 05-MAY-2018

ECICS LIMITED

S()
TEL :
FAX :

OWNER'S NAME : MAH KWAI FONG VINCENT
ADDRESS : BLK 421 SERANGOON CENTRAL
#06-382
S(550421)
TELEPHONE NO : 91006382

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT / 00404628
VEHICLE NO : SDD8992R
MODEL CODE : VM4BK25
MODEL/YEAR : LEVORG 1.6GT-S AWD CVT
ENGINE NO : FB16A917221
CHASSIS NO : JF1VM4K55GG002555
MILEAGE : 1 KM
DATE IN : 05/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 05/05/2018

Print Date : 05/05/2018
Print Time : 10:14:22

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDD8992R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM ECIGS LOCATION:BUKIT TIMAH EXIT DATE:04/05/2018 TIME:1320HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER,HOOD AND PANEL	1680.00	840/-
4	ZZ/003	RESPRAY FRONT BUMPER,HOOD AND PANEL	1260.00	840/-
5	ZZ/004	REPAIR/REPLACE REAR BUMPER,TAIGATE,WHEEL PAN, BUMPER BEAM/FOAM AND PANEL	2800.00	1960/-
6	ZZ/005	RESPRAY REAR BUMPER,TAIGATE AND PANEL	1260.00	✓
7	ZZ/006	DISMENTLE/REFIX UNDERCARRIAGE REAR CENTER/LH/RH TO FACILITATE REPAIR	900.00	nn X
8	ZZ/007	REMOVE/REFIX EXHAUST	150.00	nn X
9	ZZ/008	TO CONDUCT WATER SEEPAGE TEST	100.00	50/-
10	ZZ/009	TRANSFER TAILGATE MECHANISM	150.00	✓
11	ZZ/011	REMOVE/REFIX CARPET,SEAT TO FACILITATE REPAIR	400.00	200/-
12	ZZ/012	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	120/-
13	ZZ/013	REMOVE/INSTALL REAR WINDSCREEN	300.00	250/-
14	ZZ/014	TO REMOVE/REFIX FUEL TANK	200.00	nn X
15	ZZ/015	TO CONDUCT REAR LIGHTING TEST	50.00	25/-
16	ZZ/016	TO CONDUCT FRONT AND REAR PROTECTANT COATING	1000.00	300/-
17	ZZ/017	TO CONDUCT REAR ANTI-RUST COATING	580.00	290/-
18	ZZ/018	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	nn ✓
19	ZZ/019	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	nn ✓
20	ZZ/020	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	nn X
21	ZZ/021	SUNDRIES	100.00	50/-
22	ZZ/10	WHEEL ALIGNMENT	200.00	nn X

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDD8992R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
TOTAL LABOUR CHARGES			11875.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDD8992R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	FLOOR PAN R R CP WGN	52129VA0109P	360.00	✓		
2	SKIRT COMPL R WGN	52401VA0019P	252.00	✓		
3	BUMPER PUNCHING FWGN	28P2 57702VA030	540.00	✓	✓	
4	BUMPER FACE R WGN	57704VA031	540.00	✓		
5	ENR ABSORB FOAM	57705VA000	57.60	✓		
6	ENR ABSORB PL UPR	57705VA020	64.80	✓		
7	BRKT UPR CP RH	57707VA050	14.40	✓		
8	BRKT UPR CP LH	57707VA060	14.40	✓		
9	BRKT CORNER R WGNRH	57707VA090	18.00	✓		
10	BRKT CORNER R WGNLH	57707VA100	18.00	✓		
11	BRKT SD R WGN RH	57707VA130	21.60	✓		
12	BRKT SD R WGN LH	57707VA140	21.60	✓		
13	BRKT SD F WGN RH	57707VA150	7.20	✓		
14	BRKT SD F WGN LH	57707VA160	7.20	✓		
15	BEAM COMPL R EU	57711FJ1029P	190.80	✓		
16	BEAM COMPL F EU	57711VA0009P	252.00	✓		
17	COVER HOOK R WGN	57731VA180NN	7.20	✓		
18	COVER FOG F WGN ERH	57731VA220	54.00	✓		
19	COVER FOG F WGN ELH	57731VA230	54.00	✓		
20	PANEL COMPL R GAT	60809VA0009P	813.30	✓		
21	GLASS ASSY R G	63019VA010	799.20	✓		
22	LATCH&ACT ASSY RG	63032VA000	216.00	✓		
23	STRIKER R/G	63264AG100	21.60	✓		
24	WSTR DR R G	63516VA000	100.80	✓		
25	DAM RUBBER	65245VA100	7.20	✓		

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
26	REFLEX AY RH	84281FG000	21.60	X		
27	REFLEX ASSY LH	84281FG010	21.60	X		
28	FOG DRL ASSY F	CBU-1.6 84503FJ000	850.00	?		
29	LENS & BODY COMPLERH	84912VA041	425.00	X		
30	LENS & BODY COMPLELH	84912VA051	425.00	X		
31	NOZZLE H L WASHERRH	USE VA000 86636VA001	82.80	X		
32	NOZZLE H L WASHERLH	86636VA011	82.80	X		
33	NOZZLE COVER ASSYRH	86636VA020E4	47.60	X		
34	NOZZLE COVER ASSYLH	86636VA030W6	47.60	X		
35	GARNISH OUT SB AY	91111VA040NN	208.80	?		
36	GARNISH MLD SB AY6	91111VA070	158.40	?		
37	GRILLE ASSY F WGNESP	91121VA091	417.60	?		
38	ORNAMENT ASSY F SIX	91174SA181	68.40	?		
39	PROTECTOR UPR	91713VA001	21.60	?		
40	PROTECTOR B	91713VA060	2.20	?		
41	LETTER MK R	93079VA060	39.60			
42	LETTER MK R	93079VA080	82.80			
43	EDGE FLOOR R ASSY	95073VA000VH	22.70			
44	FRONT NUMBER PLATE	WM001			45.00	
45	REAR NUMBER PLATE	WM002			45.00	
SUB TOTAL			7479.00	0.00	90.00	0.00
LESS DISCOUNT (NETT-20 %)			1495.80	0.00	0.00	0.00
GRAND TOTAL			5983.20	0.00	90.00	0.00
OVERALL TOTAL			6073.20			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
------	-------------------	--------------	------	------	--------	----------------

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDD8992R

TOTAL LABOUR CHARGES	11875.00
TOTAL SPARE PARTS CHARGES	6073.20
GRAND TOTAL	17948.20 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

Not whorish
Penny 1-B1
B4 pain
9 days

Kenneth
17P 96910683
Kenneth.kay@lkkauto.com

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1875
18558.52



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SDD-8992-K

Surveyor: _____

DESCRIPTION	PART NO	AMOUNT
1 TRIM. PANEL REAR CATR-COMMR	94320VA00VH	\$198.00 X
2 BRACKET FRONT BUMPER CORNER RH	57707V9000	\$39.90 CM
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		

15/5/2012
LKK ACD/MB



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SDD-8992-R

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

1 RESPRAY - REAR FLOOR PAN

\$ 420.00 ✓

2 _____

3 _____

4 _____

5 _____

6 _____

7 _____

8 _____

9 _____

10 _____

11 _____

12 _____

MotorImage

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0758/2018
DATE : 05-MAY-2018

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
S(038987)
TEL : 6337 4779
FAX : 6338 9267

OWNER'S NAME : MAH KWAI FONG VINCENT
ADDRESS : BLK 421 SERANGOON CENTRAL
#06-382
S(550421)
TELEPHONE NO : 91006382

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT / 00404628
VEHICLE NO : SDD8992R
MODEL CODE : VM48K25
MODEL/YEAR : LEVORG 1.6GT-S AMD CVT
ENGINE NO : FB16A917221
CHASSIS NO : JF1VM4K55GG002555
MILEAGE : 29016 KM
DATE IN : 05/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 04/05/2018

Print Date : 23/05/2018
Print Time : 17:13:00

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDD8992R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) (SJR5080Y - ECICS)		
2	ZZ/001	CONDUCT TP CLAIM ECICS LOCATION:BUKIT TIMAH EXIT DATE:04/05/2018 TIME:1320HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER,HOOD AND PANEL	1680.00	840.00
4	ZZ/003	RESPRAY FRONT BUMPER,HOOD AND PANEL	1260.00	840.00
5	ZZ/004	REPAIR/REPLACE REAR BUMPER,TAIGATE,WHEEL PAN, BUMPER BEAM/FOAM AND PANEL	2800.00	1960.00
6	ZZ/005	RESPRAY REAR BUMPER,TAIGATE AND PANEL	1260.00	1260.00
7	ZZ/006	DISMENTLE/REFIX UNDERCARRIAGE REAR CENTER/LH/RH TO FACILITATE REPAIR	900.00	.00
8	ZZ/007	REMOVE/REFIX EXHAUST	150.00	.00
9	ZZ/008	TO CONDUCT WATER SEEPAGE TEST	100.00	50.00
10	ZZ/009	TRANSFER TAILGATE MECHANISM	150.00	150.00
11	ZZ/011	REMOVE/REFIX CARPET,SEAT TO FACILITATE REPAIR	400.00	200.00
12	ZZ/012	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	120.00
13	ZZ/013	REMOVE/INSTALL REAR WINDSCREEN	300.00	250.00
14	ZZ/014	TO REMOVE/REFIX FUEL TANK	200.00	.00
15	ZZ/015	TO CONDUCT REAR LIGHTING TEST	50.00	25.00
16	ZZ/016	TO CONDUCT FRONT AND REAR PROTECTANT COATING	1000.00	300.00
17	ZZ/017	TO CONDUCT REAR ANTI-RUST COATING	580.00	290.00
18	ZZ/018	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	300.00
19	ZZ/019	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	145.00
20	ZZ/020	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	.00
21	ZZ/021	SUNDRIES	100.00	50.00
22	ZZ/022	RESPRAY REAR FLOOR PAN (SUPP)	420.00	420.00

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDO8992R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
23	ZZ/10	WHEEL ALIGNMENT	200.00	.00
TOTAL LABOUR CHARGES			12295.00	7200.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDD8992R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	FLOOR PAN R R CP WGN	52129VA0109P	360.00			X
2	SKIRT COMPL R WGN	52401VA0019P	252.00			OK /
3	BUMPER PUNCHING FWGN	2@P2 57702VA030	540.00			OK /
4	BUMPER FACE R WGN	57704VA031	540.00			OK /
5	ENR ABSORB FOAM	57705VA000	57.60			OK /
6	ENR ABSORB PL UPR	57705VA020	64.80			X
7	BRKT CORNER F RH (SUPP)	57707VA000	39.90			OK /
8	BRKT UPR CP RH	57707VA050	14.40			X
9	BRKT UPR CP LH	57707VA060	14.40			X
10	BRKT CORNER R WGNRH	57707VA090	18.00			OK /
11	BRKT CORNER R WGNLH	57707VA100	18.00			X
12	BRKT SD R WGN RH	57707VA130	21.60			X
13	BRKT SD R WGN LH	57707VA140	21.60			X
14	BRKT SD F WGN RH	57707VA150	7.20			X
15	BRKT SD F WGN LH	57707VA160	7.20			X
16	BEAM COMPL R EU	57711FJ1029P	190.80			OK /
17	BEAM COMPL F EU	57711VA0009P	252.00			X
18	COVER HOOK R WGN	57731VA180NN	7.20			OK /
19	COVER FOG F WGN ERH	57731VA220	54.00			X
20	COVER FOG F WGN ELH	57731VA230	54.00			X
21	PANEL COMPL R GAT	60809VA0009P	813.30			OK /
22	GLASS ASSY R G	63019VA010	799.20			OK /
23	LATCH&ACT ASSY RG	63032VA000	216.00			OK /
24	STRIKER R/G	63264AG100	21.60			OK /
25	WSTR DR R G	63516VA000	100.80			OK /

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDD8992R

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 DAM RUBBER	65245VA100	7.20			OK ✓
27 REFLEX AY RH	84281FG000	21.60			X
28 REFLEX ASSY LH	84281FG010	21.60			X
29 FOG DRL ASSY F	CBU-1.6 84503FJ000	850.00			X
30 LENS & BODY COMPLETE	84912VA041	425.00			X
31 LENS & BODY COMPLETE	84912VA051	425.00			X
32 NOZZLE H L WASHERRH	USE VA000 86636VA001	82.80			X
33 NOZZLE H L WASHERLH	86636VA011	82.80			X
34 NOZZLE COVER ASSYRH	86636VA020E4	47.60			X
35 NOZZLE COVER ASSYLH	86636VA030W6	47.60			X
36 GARNISH OUT SB AY	91111VA040NN	208.80			X
37 GARNISH MLD SB AY6	91111VA070	158.40			X
38 GRILLE ASSY F WCNESP	91121VA091	417.60			OK ✓
39 ORNAMENT ASSY F SLX	91174SA181	68.40			X
40 PROTECTOR UPR	91713VA001	21.60			X
41 PROTECTOR B	91713VA060	2.20			X
42 LETTER MK R	93079VA060	39.60			OK ✓
43 LETTER MK R	93079VA080	82.80			OK ✓
44 EDGE FLOOR R ASSY	95073VA000VH	22.70			OK ✓
45 FRONT NUMBER PLATE	WM001			45.00	OK ✓
46 REAR NUMBER PLATE	WM002			45.00	X
SUB TOTAL		4166.30	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)		833.26	0.00	0.00	0.00
GRAND TOTAL		3333.04	0.00	45.00	0.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDD8992R

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
		NETT	LIST	S/NETT	S/LIST REMARKS
OVERALL TOTAL		3378.04			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SDD8992R

NETT ITEM	4166.30
LESS 20 %	-833.26
NETT AMOUNT	3333.04

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	45.00
---------------------	-------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	7200.00
TOTAL SPARE PARTS CHARGES	3378.04

TOTAL CHARGES	10578.04
ADD 7 % GST	740.46

GRAND TOTAL	11318.50
-------------	----------

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2018 13:19 Edit Reg		07 May 2018 00:00 Edit Adj Rpt	\$S\$10,578.04 Edit Estimates	\$S\$10,578.04 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: EMAL@EMAIL.COM									
Main Claimant: MAH KWAI FONG VINCENT , ID: S1425462E									
Vehicle Reg. No.: SDD8992R		Date of Loss: 04/05/2018 13:00 - :59 [20 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / DMPC1800172H		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SJR5080Y		Policy No. (Claimant):							
		Excess:							
Repairer: Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038101									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 / 6303 0178 ... [Handled by Janice Goh - 6303 0182]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/05/2018]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDD8992R (DMPC1800172H)
[SJR5080Y]

TP

MAH KWAI FONG VINCENT

May 4 2018 1:00PM

[-]

Motor Image Enterprises Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	26/10/18 09:57	General View						Load JPG	☒	
2	26/10/18 09:57	General View						Load JPG	☒	
3	26/10/18 09:57	General View						Load JPG	☒	
4	26/10/18 09:57	General View						Load JPG	☒	
5	26/10/18 09:57	General View						Load JPG	☒	
6	26/10/18 09:57	General View						Load JPG	☒	
7	26/10/18 09:57	General View						Load JPG	☒	
8	26/10/18 09:57	General View						Load JPG	☒	
9	26/10/18 09:57	General View						Load JPG	☒	
10	26/10/18 09:57	General View						Load JPG	☒	
11	26/10/18 09:57	General View						Load JPG	☒	
12	26/10/18 09:57	General View						Load JPG	☒	
13	26/10/18 09:57	General View						Load JPG	☒	
14	26/10/18 09:57	General View						Load JPG	☒	
15	26/10/18 09:57	General View						Load JPG	☒	
16	26/10/18 09:57	General View						Load JPG	☒	
17	26/10/18 09:57	General View						Load JPG	☒	
18	26/10/18 09:57	General View						Load JPG	☒	
19	26/10/18 09:57	General View						Load JPG	☒	
20	26/10/18 09:57	General View						Load JPG	☒	
21	26/10/18 09:57	General View						Load JPG	☒	
22	26/10/18 09:57	General View						Load JPG	☒	
23	26/10/18 09:57	General View						Load JPG	☒	
24	26/10/18 09:57	General View						Load JPG	☒	
25	26/10/18 09:57	General View						Load JPG	☒	
26	26/10/18 09:57	Odometer Reading						Load JPG	☒	
27	26/10/18 09:57	Chassis Number						Load JPG	☒	
28	26/10/18 09:58	Reinspection Photo						Load JPG	☒	
29	26/10/18 09:58	Reinspection Photo						Load JPG	☒	
30	26/10/18 09:58	Reinspection Photo						Load JPG	☒	
31	26/10/18 09:58	Reinspection Photo						Load JPG	☒	
Documentation							1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/11/18 13:39	Supplementary						Load PDF	☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18008281/KQBE2
Date: 19/11/2018

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No: SDD8992R Insured Vehicle No: SJR5080Y
Date of Loss: 04/05/2018 Nature of Claim: TP Claim No: DMPC1800172H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDD8992R Engine No: FB16A917221
Make & Model: SUBARU LEVORG, 1.6 (A) Chassis No: JF1VM4K55GG002555
Reg. Date: 29/08/2016 (Man. Year: 2016) Odometer: 29015 km
Colour: Metallic Pearl White
Engine Capacity: 1600 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,808.52	3,873.04	2,935.48	43.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,750.00	6,705.00	5,045.00	42.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,558.52	10,578.04	7,980.48	43.00
+ GST 7.00/7.00% (S\$)	1,299.10	740.46	558.64	43.00
Nett Amount (S\$)	19,857.62	11,318.50	8,539.12	43.00

INSPECTION

Date of Assignment: 07/05/2018
Date Inspected: 08/05/2018 Inspected At: Motor Image Enterprises Pte Ltd (Toa Payoh)
19 Lorong 8 Toa Payoh
Singapore 319255
Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Nov 2018)	
Parts:	N/A	SUBARU LEVORG 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDD8992R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR - 2 EYES	Dented	300.00 FS	*300.00 FS
2	1		*REAR TINTED FILM	Necessary	145.00 FS	*145.00 FS
3	1		*SUNDRIES	Necessary	100.00 F	*50.00 F
4	1		*FLOOR PAN R R CP WGN	Repair	360.00 FN	*- FN
5	1		*SKIRT COMPL R WGN	Bent	252.00 FN	*252.00 FN
6	1		*BUMPER PUNCHING FWGN	Distorted	540.00 FN	*540.00 FN
7	1		*BUMPER FACE R WGN	Bent	540.00 FN	*540.00 FN
8	1		*ENR ABSORB FOAM	Bent	57.60 FN	*57.60 FN
9	1		*ENR ABSORB PL UPR	Repair	64.80 FN	*- FN
10	1		*BRKT UPR CP RH	Repair	14.40 FN	*- FN
11	1		*BRKT UPR CP LH	Repair	14.40 FN	*- FN
12	1		*BRKT CORNER R WGNRH	Distorted	18.00 FN	*18.00 FN
13	1		*BRKT CORNER R WGNLH	Serviceable	18.00 FN	*- FN
14	1		*BRKT SD R WGN RH	Repair	21.60 FN	*- FN
15	1		*BRKT SD R WGN LH	Repair	21.60 FN	*- FN
16	1		*BRKT SD F WGN RH	Repair	7.20 FN	*- FN
17	1		*BRKT SD F WGN LH	Repair	7.20 FN	*- FN
18	1		*BEAM COMPL R EU	Bent	190.80 FN	*190.80 FN
19	1		*BEAM COMPL F EU	Repair	252.00 FN	*- FN
20	1		*COVER HOOK R WGN	Dented	7.20 FN	*7.20 FN
21	1		*COVER FOG F WGN ERH	Serviceable	54.00 FN	*- FN
22	1		*COVER FOG F WGN ELH	Serviceable	54.00 FN	*- FN
23	1		*PANEL COMPL R GAT	Bent	813.30 FN	*813.30 FN
24	1		*GLASS ASSY R G	Necessary	799.20 FN	*799.20 FN
25	1		*LATCH&ACT ASSY RG	Dented	216.00 FN	*216.00 FN
26	1		*STRIKER R/G	Distorted	21.60 FN	*21.60 FN
27	1		*WSTR DR R G	Cut	100.80 FN	*100.80 FN
28	1		*DAM RUBBER	Necessary	7.20 FN	*7.20 FN
29	1		*REFLEX AY RH	Serviceable	21.60 FN	*- FN
30	1		*REFLEX ASSY LH	Serviceable	21.60 FN	*- FN
31	1		*FOG DRL ASSY F	Serviceable	850.00 FN	*- FN
32	1		*LENS & BODY COMPLERH	Serviceable	425.00 FN	*- FN
33	1		*LENS & BODY COMPLELH	Serviceable	425.00 FN	*- FN
34	1		*NOZZLE H L WASHERRH	Serviceable	82.80 FN	*- FN
35	1		*NOZZLE H L WASHERLH	Serviceable	82.80 FN	*- FN
36	1		*NOZZLE COVER ASSYRH	Serviceable	47.60 FN	*- FN
37	1		*NOZZLE COVER ASSYLH	Serviceable	47.60 FN	*- FN
38	1		*GARNISH OUT SB AY	Serviceable	208.80 FN	*- FN
39	1		*GARNISH MLD SB AY6	Serviceable	158.40 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*GRILLE ASSY F WGNESP	Dented	417.60 FN	*417.60 FN
41	1		*ORNAMENT ASSY F SIX	Serviceable	68.40 FN	*- FN
42	1		*PROTECTOR UPR	Serviceable	21.60 FN	*- FN
43	1		*PROTECTOR B	Serviceable	2.20 FN	*- FN
44	1		*LETTER MK R	Necessary	39.60 FN	*39.60 FN
45	1		*LETTER MK R	Necessary	82.80 FN	*82.80 FN
46	1		*EDGE FLOOR R ASSY	Necessary	22.70 FN	*22.70 FN
47	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
48	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
49	1		*TRIM PANEL REAR GATE COVER	Serviceable	198.00 FN	*- FN
50	1		*BRACKET FRONT BUMPER CORNER RH	Cracked	39.90 FN	*39.90 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	8,351.90	4,706.30
- Nett Item Discount on N Items 20.00/20.00% (S\$)	1,543.38	833.26
Total Parts (S\$)	6,808.52	3,873.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR / REPLACE FRONT BUMPER, HOOD AND PANEL	New	1,680.00	840.00
2	RESPRAY FRONT BUMPER, HOOD AND PANEL	New	1,260.00	840.00
3	REPAIR / REPLACE REAR BUMPER, TAILGATE, WHEEL PAN, BUMPER BEAM / FOAM AND PANEL	New	2,800.00	1,960.00
4	RESPRAY REAR BUMPER, TAILGATE AND PANEL	New	1,260.00	1,260.00
5	DISMENTLE / REFIX UNDERCARRIAGE REAR CENTER / LH / RH TO FACILITATE REPAIR	New	900.00	0.00
6	REMOVE / REFIX EXHAUST	New	150.00	0.00
7	TO CONDUCT WATER SEEPAGE TEST	New	100.00	50.00
8	REMOVE / REFIX CARPET, SEAT TO FACILITATE REPAIR	New	400.00	200.00
9	REMOVE / REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	New	150.00	120.00
10	REMOVE / INSTALL REAR WINDSCREEN	New	300.00	250.00
11	TO REMOVE / REFIX FUEL TANK	New	200.00	0.00
12	TO CONDUCT REAR LIGHTING TEST	New	50.00	25.00
13	TO CONDUCT FRONT AND REAR PROTECTANT COATING	New	1,000.00	300.00
14	TO CONDUCT REAR ANTI-RUST COATING	New	580.00	290.00
15	REMOVE / REFIX FRONT HEADLAMP WASHER AND PIPING	New	150.00	0.00
16	WHEEL ALIGNMENT	New	200.00	0.00
17	RESPRAY REAR FLOOR PAN	New	420.00	420.00
18	TRANSFER TAILGATE MECHANISM	New	150.00	150.00
Gross Labour Cost (S\$)			11,750.00	6,705.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >