

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKU658L
Accident Date : 02-May-2018

Our Ref : 218081 (AXA) / CHAN

HUI SHOON CAR RENTAL
BLK 1 SIN MING IND.ESTATE
#01-125
Singapore 575636

No. : 05774

Date : 03-May-2018

PAGE : 1

*Not available
L1Png @ ?
Resurvey after painting*

ESTIMATED COST OF REPAIR FOR TOYOTA WISH 1.8CVT SGF8686D

=====

1 pc Tail gate
1 pc Tail gate logo
1 pc Tail gate glass moulding
1 pc Tail gate inner lock
1 pc Tail gate rubber
1 pc Rear bumper fascia
2 pcs Rear bumper bracket
2 pcs Rear bumper side retainer
1 pc Rear end panel -inner
1 pc Rear end panel -outer
1 pc End panel top garnish
1 pc Rear n/s bumper reflector

Ry 1,175.90 ✓
ma 49.70 ✓
ma 125.30 ✓
361.60 ?
sm 302.60 X
Ry 491.90 ✓
@ S\$ 48.50 97.00 ?
@ S\$ 89.90 *ma* 179.80 ✓
99.60 ?
453.90 ?
253.10 ?
sm 52.40 X

3,642.80
Less 25% : 910.70

5 days

1 pc Rear w/s glass sealant
1 pc Rear bumper reverse sensor(set

ma 2,732.10
ma 40.00 60.00 sn
shat 200.00 300.00 sn

To remove & refix rear windscreen
glass and conduct water leak test.

120/
150.00

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *60/*

To apply undersealing

100.00 *60/*

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKU 658L

Page : 2

To putty and spray replaced parts

6000
900.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

6000
800.00

Total : -----
S\$ 5,162.10
=====

Singapore Dollars Five Thousand One Hundred and
Sixty Two and Cents Ten Only