

OD/AXA Insurance



Reporting Centre
Workshop
Windscreen
Spraypainting

5 Soon Lee Street, #01-60 Pioneer Point, Singapore 627607
5 Soon Lee Street, #01-62 Pioneer Point, Singapore 627607
5 Soon Lee Street, #01-41 Pioneer Point, Singapore 627607
1 Soon Lee Street, #06-41 Pioneer Centre, Singapore 627605



DATE: 4/5/2018

REPAIR DETAILS	
REFERENCE	
Vehicle Reg No.	: SGQ3438D
Make & Model	: HONDA AIRWAVE 1.5 A
Chassis No.	: GJ11115193
Engine No.	: L15A5118799
Manufactured Year	: 2006
Labour	: REPAIRER'S
TP Vehicle Reg No.	: SLB4726K
DOA & Location	: 29/04/2018 CTE (BEFORE BRADDELL EXIT)
Our Ref	: SGQ3438D / ANG CHAI GEOK

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price	List price - 20%
1	1	HEADLAMP RH		\$ 625.80	am
2	1	HEADLAMP LH		\$ 625.80	am
3	1	BONNET		\$ 750.00	bt
4	1	BONNET CHROME		\$ 240.90	dis
5	1	BONNET HINGE RH		\$ 29.40	Ry
6	1	BONNET HINGE LH		\$ 29.40	Ry
7	1	BONNET LOCK		\$ 70.00	bt
8	1	FENDER LH		\$ 525.00	Ry
9	1	FENDER RH		\$ 525.00	Ry
10	1	FRT SUPPORT		\$ 550.00	bt
11	1	HEADLAMP BRACKET RH		\$ 48.30	new
12	1	HEADLAMP BRACKET LH		\$ 48.30	new
13	1	GRILLE		\$ 265.80	am
14	1	GRILLE BASE		\$ 235.00	am
15	1	GRILLE LOGO		\$ 32.00	am
16	1	RADIATOR		\$ 1,450.50	? photo
17	1	CONDENSAR		\$ 880.00	bt
18	1	FANCROWL ASSY		\$ 110.00	?
19	1	FRT BUMPER		\$ 1,050.00	de
20	1	BUMPER RETAINER RH		\$ 22.50	new
21	1	BUMPER RETAINER LH		\$ 22.50	new
22	10	BUMPER CLIPS		\$ 38.00	new
23	1	BUMPER BRACKET RH		\$ 48.30	new
24	1	BUMPER BRACKET LH		\$ 48.30	new
25	1	SPOILER		\$ 145.00	X
26	1	REINFORCEMENT		\$ 320.80	bt
27	1	BUMPER LOWER GRILLE		\$ 220.50	am
28	1	SPARE TANK		\$ 48.30	?
29	1	BONNET INSULATOR		\$ 145.20	de
30	10	BONNET INSULATOR CLIPS		\$ 38.00	new
31	1	ENGINE LOWER COVER		\$ 70.40	X
32	1	BUMPER LOWER RUBBER		\$ 29.40	de
33	1	WHEEL ARC DUST COVER RH		\$ 46.50	?
34	1	AIRDUCT		\$ 58.40	X

Sub-Total (S\$) \$ 9,393.30
 Margin on LN Items (S\$) \$ -
 Sub-Total (S\$) \$ 9,393.30

LABOUR

No.	Description	Price
1	LABOUR	\$ 1,400.00 800
2	SPRAYPAINTING	\$ 1,400.00 800
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 40.00 30
4	REMOVE AND REPLACE AIR-CON RADIATOR AND TOP UP COOLANT	\$ 200.00 100
5	REMOVE AND REPLACE AIR-CON CONDENSER, PIPES AND VACUUM AIR-CON SYSTEM AND REFILL GAS	\$ 200.00 100 } 120
6	REMOVE AND REINSTALL AIR-CON SYSTEM AND BLOWER UNIT	\$ 200.00 x
7	ANTI-RUST COATING	\$ 100.00 40
8	REMOVE AND REPLACE SPARE TANK FIXTURE AND ATTACHMENT	\$ 100.00 x
Total Labour (S\$)		\$ 3,640.00

MISCELLANEOUS ITEMS

No.	Description	Price
1	NO. PLATE W/ COVER	\$ 45.00 lt ✓
Total Miscellaneous Items (S\$)		\$ 45.00

Total Parts (S\$)	\$ 9,393.30
Total Labour (S\$)	\$ 3,640.00
Total Miscellaneous (S\$)	\$ 45.00
Total (S\$)	\$ 13,078.30
Lumpsum 20% (S\$)	\$ 2,615.66
Total (S\$)	\$ 10,462.64
GST (7%) (S\$)	\$ 732.38
Grand Total (S\$)	\$ 11,195.02

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 9749 5749
 Ex \$ 800
 Revert, Not Approve
 6 days.
 Lumpsum
 Resurvey after repair.