



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

### ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR SIM SOO YONG TERENCE  4 SPRINGSIDE GREEN Singapore 786929 SINGAPORE 786929  Contact No Mobile: 98262820	Cust No/Name	/MR SIM SOO YONG TERENCE
	Reg No/Reg Date	SLQ3726M / 06/07/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH004743
	Engine No	3A92UDT3815
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	20/04/2018/ 17:55	TLC	442 / CocoLu	24641

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER, REAR FENDER RH, REAR LAMPHOUSING RH				2200 2750.00
E PNT98000 TO SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, LAMPHOUSING RH				1050 1680.00
E PNT88000 TO REMOVE & INSTALL PARKING SENSOR				80 100.00
A 54900099 TO CHECK WIRING & ELECTRICAL SYSTEM				20.00
A 54900099 TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				200.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY TO APPLY SEALANT FOR ACCIDENT PORTION				80.00
M SUNDRY Sundry				20.00
M FACE,RR BUMPER	1.00	740.00	00.00	740.00
M BRACKET,RR BUMPER,RH	1.00	27.00	00.00	27.00
M PANEL,QTR,OTR RH	1.00	756.00	00.00	756.00
M PANEL,RR COMB LAMP HSG,RH	1.00	60.00	00.00	60.00
M LAMP ASSY,COMB,RR RH	1.00	332.00	00.00	332.00

SURVEYOR NAME: Taufik 97495749.SURVEYOR SIGNATURE: TaufikDATE: 17/5/18 01255REMARKS: Resurvey before paint - WP  
7-8 days.sun@lkanauto.comLKK Auto Consultants hence notify  
the Repairer of the following:

- Confirm & accepted by
- To resurvey before spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Authorized signatory and company stamp

	Nett	6,885.00
7% GST on	6885.00	481.95
Total Payable		7,366.95

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.