

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT18001751	Page	1
	8 SHENTON WAY	Date	: 27. Apr 2018		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: NG SIN HAI		
Registration No	: EV16E	Engine No	: R20A15700004		
Chassis No	: JHLRE2850BC200003	Date Time	: 27. Apr 2018 4:07:52 PM		
Model	: CRV 2.0L 2011 MODEL SUNROOF	Surveyor Name	:		
Owner's Name	: LEE KAH HONG TEDDY	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:LEE KAH HONG TEDDY						
	OWNER INSURER:AXA INSURANCE S'PORE PTE LTD						
	ACC DATE:27/04/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:AXA INSURANCE S'PORE PTE LTD						
	TP VEH:						
RS-TMP3040L	VPC 4PCS REAR SENSORS	1 ?	320.00		320.00	22.40	342.40
04715-SWA-A00ZZ	FACEREAR BUMPER	1 de	436.50	25	327.37	22.92	350.29
33505-SWA-J01	REFLECTORR.RR.	1 at	20.50	25	15.37	1.08	16.45
33555-SWA-J01	REFLECTORL.RR.	1 X	20.50	25	15.37	1.08	16.45
71502-SWA-A00	FACEREAR BUMPER LOWER	1 de	367.90	25	275.92	19.31	295.23
71593-SWA-A01	SPACERR.RR.BUMPER	1 all	17.30	25	12.97	0.91	13.88
71598-SWA-A01	SPACERL.RR.BUMPER	1 all	17.30	25	12.97	0.91	13.88
91505-S9A-003	CLIP ABUMPER	14 all	3.90	25	40.95	2.87	43.82
91506-S9A-003	CLIP BBUMPER	2 all	2.40	25	3.60	0.25	3.85
68100-SWA-U00ZZ	TAILGATE COMP	1 RY	974.80	25	731.10	51.18	782.28
74440-SWA-003	W/STRIPTAILGATE	1 X	140.00	25	105.00	7.35	112.35
74810-SWA-A01	SWITCHTAILGATE OPENER	1 X	98.70	25	74.02	5.18	79.20
74895-SWA-A01ZJ	GARNISHTAILGATE LOWER	1 de	381.80	25	286.35	20.04	306.39
04731-SAA-000	RUBBER, W/SHIELD	1 X	24.20	25	18.15	1.27	19.42
04733-SWA-000	RUBBERREAR WINDSHIELD	1 X	49.50	25	37.12	2.60	39.72
76707-STK-000	SEALA	1 X	6.40	25	4.80	0.34	5.14
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2 X	60.00		120.00	8.40	128.40
66100-SWA-300ZZ	PANELREAR	1 RY	543.70	25	407.77	28.54	436.31
					Sum Item	2808.83	196.63
							3,005.46
BOSUN	SUNDRIES	1 30	100.00		100.00	7.00	107.00



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT18001751	Page	2
	: 8 SHENTON WAY	Date	: 27. Apr 2018		
	: #27-01 AXA TOWER	Customer No.	: WZA006		
	: SINGAPORE 068811	Svc Advisor	: NG SIN HAI		
Registration No	: EV16E	Engine No	: R20A15700004		
Chassis No	: JHLRE2850BC200003	Date Time	: 27. Apr 2018 4:07:52 PM		
Model	: CRV 2.0L 2011 MODEL SUNROOF	Surveyor Name	:		
Owner's Name	: LEE KAH HONG TEDDY	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓	180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00	✗	80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓	180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	✗	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	✗	560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00	✗	560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	✗	100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL.	1	5000.00	1120	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00	900	3500.00	245.00	3745.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00	✗	450.00	31.50	481.50
BKB001R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00	✗	380.00	26.60	406.60
Sum Labor					11650.00	815.50	12,465.50

Survey By	Taufik 9749549				
Date & Time	10/5/18 @ 1500	Total Amount	14,458.83	1,012.13	15,470.96
Excess		Total (Inclusive of GST)			15,470.96
Status					
Signature					

WP
4 days
Resurvey before paint.
sur@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Printed on 10/5/2018 10:32:21 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)