

22/03/2002

ASS. REC. BY:

REF:

CS3/CTU 8008292/Gzuber

Special Instruction:

Surveyor
Meriman

GIA

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTL

Date/Time:

03052018 218pm

Estimated Cost:

Bill to:

~~OD~~ / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PBJ 8257Y

Insured:

SJU 6649X

at Workshop m/s

Equator Brotherhood

Tel:

9011 3391

of

25 Kaki Bukit Rd 4 #03-79

Policy No:

DMPCSN 301613700

Claim No:

SNM13102242C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28042018

CA / REV / REP. / REV 24 HRS wpi

08052018

H.O.D. Endorsement:

Date/Time:

07052018 3:33pm

Person Contacted:

Wille

Vehicle

IN / OUT

Date/Time

Action/Instruction

(X) Estimate

Call wksp from 03052018 until 07052018 just pickup

No GIA

Survey


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: FBJ 8257Y Yr Regn: No record
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: KTM C.C. -
 Colour: white A/C: Insured / Std / NI / NA
 Sp.Reading: 48233 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 110 / 70 ZR17
 R: 150 / 60 ZR17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 28042018 D.O.I. 10052018 @ 5:00 PM
 Survey held at: Equator Brother hwd. Spur
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$2000 - \$3000</u>

Date/Time, File Pass to? : Preli. Report : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____
 Report Format: PRS -
 Lump Sum / I.B.I: (\$ _____)
 Days Of Repair: 3
 Resurvey No. of Trip: -
 Add Fee: : Site Insp (\$ _____)) \$ + RS. SI
 : Interview (\$ _____)) Photos
 : Tech. Invs (\$ _____)) Others
 : Weekend (\$ _____))
 Survey Fee: 150
 TOTAL 150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 May 2018		03 May 2018 14:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	CHEN KENBIN		
Vehicle Reg. No.:	FBJ8257Y	Date of Loss:	28/04/2018 00:00 - :59
Claim Type:	TP / SNM18D02242C02	Policy/Cover Note No.:	DMPCSN3016131700
Vehicle Reg. No. (Insured):	SJU6645X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/05/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
<input type="checkbox"/> ALL ASSOCIATED TASKS			
View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 May 2018		03 May 2018 14:18 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: CHEN KENBIN									
Vehicle Reg. No.: FBJ8257Y		Date of Loss: 28/04/2018 00:00 - :59							
Claim Type: TP / SNM18D02242C02		Policy/Cover Note No.: DMPCSN3016131700							
Vehicle Reg. No. (Insured): SJU6645X		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/05/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBJ8257Y (SNM18D02242C02)**
[SJU6645X]
TP
CHEN KENBIN
Apr 28 2018 12:00AM
[-]
Equator Brotherhood

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/05/18 14:17	PRS	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 11:39	LKKPhotosIn6-1.pdf	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118008292/GZ4BE2

Date: 25/09/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3016131700
Claimant Vehicle No :	FBJ8257Y	Insured Vehicle No :	SJU6645X
Date of Loss:	28/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D02242C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ8257Y	Engine No:	HIDDEN
Make & Model:	KTM RC 200, 200cc	Chassis No:	HIDDEN
Reg. Date:	(Man. Year:)	Odometer:	48233 km
Colour:	White	Engine Capacity:	0 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70Z R17	Rear Tyre Size:	150/60Z R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	03/05/2018	Inspected At:	Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb Singapore 417800
Date Inspected:	10/05/2018		
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 25 Sep 2018)
Parts:	N/A KTM RC 200 200cc (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBJ8257Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >