

ASS. REC. BY:

REF:

OS / ASM 18008297 / Kuber

Special Instructions:

Surveyor:

Kenneth

ASSIGNMENT (Office)

Smart Claim

From (Person):

Kitty Teo

of

ASM

Date/Time:

07/05/2018 11:10am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 452K

Insured:

at Workshop to/s

K Kim Hin

Tel:

6452 7018

of

160 Sin Ming Drive #02-18

Policy No:

Claim No:

S8M00F05

Sum Insured:

Excess:

NIL

Make of Veh:

(Client's Record)

D.O.A.

28/04/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

07/05/2018 11:20am

Person Contacted:

Shuman

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

Fire Investigation

SLX 452K - X

08/5/18 @ 1.44pm revert to Kitty Teo via Smart Claim.

Check any modification - Hatzel.

10/5/18 @ 9am - Received From Dealer.

14/5/18 @ 5.58pm 2nd revert to Kitty Teo via Smart Claim.

09/6/18 @ 7.43pm Informed Kitty that WIP asking L3 @ 28K which exceeds margin of

ASS. REC. BY:

REF:

ADD/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

Consistent? : Yes or No

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Est. Repairs:

11 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLX 452K

Yr Regn:

07.10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lexus RX 450h c.c.

Colour:

M.D. Grey

Sp. Reading

8898

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

JTJBC11A402412792

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/60R18

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/TOYO/YOKO or

Front

R/Bal.

2

mm

Rear

R/Bal.

3

mm

L/Bal.

2

mm

L/Bal.

3

mm

D.O.A.

28/4/18

D.O.I.

7/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The veh caught fire. The cover of the UIC / Chassis frame / Body Structure affected due to collision.

Probably due to short circuit at the FR Rlt down wiring.

13/6/18 @ 5.00pm K. H. H. informed that E. H. H. accepted & able to undertake 13 B2K. not more than

19/6/18 @ 11.58am Informant Sandra C/A at 13 B2K & Exs BNL by email. (as marker is repair letter from WHP)

02/11/18 @ 11.15am confirmed with Simon 13 B2K, 11 days. (Ref 617573, 441-)

RECEIVED 19 NOV 2018

Date/Time, File Pass to?

☐

: Prel. Report

11/9/14 main

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

11

Resurvey No. of Trip:

1

Survey Fee:

300

Transportation:

S + RS: \$

Photos

Others: Pre-approval

TOTAL

170.00

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Smart Claim

Lump Sum / L.B.I. (\$

22000



Service Request Details

Claim

S8M00FO5

Reference

None 

Loss Date

April 28, 2018

Request Date

May 7, 2018

Due Date

May 14, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Fire

Investigation

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLX452K

Make

LEXUS

Service Address

160 Sin Ming Drive, #, . . 575722

Primary Contact/Insured

HIRANPAL SINGH S/O PREM SINGH
526 MILTONIA CLOSE, #01-19, 768107, Singapore
81574624

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS NIL

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 7 November 2018 11:15 AM
To: Simon; survey@kkimhin.com.sg
Cc: SUR
Subject: RE: FINALISE OF VEHICLE SLX 452K (DOA: 28/04/2018)

Dear Simon,

WITHOUT PREJUDICE

Confirm Lump Sum \$22,000.00 before excess NIL & GST and 11 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon <simon@kkimhin.com.sg>
Sent: Tuesday, 9 October 2018 12:15 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; survey@kkimhin.com.sg
Subject: Re: FINALISE OF VEHICLE SLX 452K (DOA: 28/04/2018)

Hi,

I am waiting for your confirmation.

Lump Sum \$22k.

If confirm, I will submit to account side to settle the final bill.

Regards

Simon

From: Shiau Chan (LKKAuto)
Sent: Tuesday, October 09, 2018 11:46 AM
To: survey@kkimhin.com.sg ; simon@kkimhin.com.sg
Subject: FINALISE OF VEHICLE SLX 452K (DOA: 28/04/2018)

Dear Meng Huat,

Kindly advise the status of SLX 452K.

If done for repair, kindly provide us the final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



SINGAPORE CIVIL DEFENCE FORCE
91 UBI AVENUE 4
SINGAPORE 408827
TELEPHONE: 6280 0000
GST REG NO: MG-8400000-5

TAX INVOICE/RECEIPT

Name : DENISE TAY
Address : 51 UBI AVE 1
#01-25
Singapore 408933

Receipt No : 5258469931606856103633
Date/Time : 09/05/2018 14:20
eService ID : FR2018050902204

S/No	Payment Mode	Description	Reference No	Net Amount	GST (7% GST)	Gross Amount
1	Credit Card	Fire Report	FR2018050902204	170.00	0.00	170.00
					Total Amount (SGD)	170.00

REMARKS:

Date and Time [28/04/2018 15:30] - Location of Fire [CHANGI GOLF CLUB CARPARK]

Note: This is a computer generated receipt. No signature is required. Receipt is void if payment is dishonoured.



Fire Report Application

Your request for the Fire Report has been confirmed and the amount of SGD170.00 will be deducted from your account. You will receive the report within 8 working days upon completion of investigations. Please quote the following transaction number when making enquiries.


[Download Tax Invoice/Receipt](#)

Transaction Number: FR2018050902204

Date/Time: 09/05/2018 14:20

INCIDENT DETAILS						
Date and Time	28/04/2018 15:30					
Location of Fire	CHANGI GOLF CLUB CARPARK					
Fire Involved	MOTOR CAR SLX 452K					
REQUESTOR DETAILS						
Requestor Type	Insurance Companies					
Requestor ID Type	Singapore Pink	Requestor ID	S8724548I			
Name of Applicant	DENISE TAY					
Company Name	LKK AUTO CONSULTANT					
Company UEN						
Company Reference Number	CS/ASM18008297/Kqb					
CONTACT DETAILS						
Mode of Collection	Email					
Main Contact No.	62563561	Office No.				
Handphone No.		Fax No.				
Email Address	sur@lkkauto.com					
Address	Block No.	51	Floor No.	01	Unit No.	25
	Street Name	UBI AVE 1				
	Building Name		Postal Code	408933		
PAYMENT DETAILS						
Payment Mode	Credit/Debit Card					
EP Reference No.	5258469931606856103633					
PSI Reference No.	4b775777-6b96-4be1-93ba-96848e736b28					
Total Fees	SGD170.00					

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 19 June 2018 11:58 AM
To: 'service@kkimhin.com.sg'
Cc: SUR; 'Simon'; 'Survey KKH'; admin1@kkimhin.com.sg; sandrakhong@gmail.com
Subject: RE: ESTIMATE OF SLX 452K

Dear Sandra,

As instructed by our client, please proceed to repair the insured vehicle **SLX 452K** at repair cost not more than **\$22,000.00 on Lump Sum basis (Excess NIL)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: service@kkimhin.com.sg [mailto:service@kkimhin.com.sg]
Sent: Tuesday, 19 June 2018 11:52 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Simon' <simon@kkimhin.com.sg>; 'Survey KKH' <survey@kkimhin.com.sg>; admin1@kkimhin.com.sg; sandrakhong@gmail.com
Subject: RE: ESTIMATE OF SLX 452K

Enclosed lump sum repair letter.

Thanks & Regards

Sandra

6452 7018

K. Kim Hin Auto Pte Ltd

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, June 19, 2018 10:40 AM
To: Simon; service@kkimhin.com.sg; 'Survey KKH'
Cc: SUR
Subject: RE: ESTIMATE OF SLX 452K

Dear Sandra/Simon,

As spoken with you earlier.

Kindly send us the Lump Sum Repair Letter as you are able to undertake the repair cost at Lump Sum \$22K.



K. Kim Hin will repair

Type

🔗 Question

Message

Hi Shiau Chan, K. Kim Hin has informed us that they are able to undertake repairs at \$22k lump sum. Please get the lump sum authorization letter from workshop and proceed to authorise.

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564313

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/05/18

Survey Details:

Date of loss	28-Apr-18
Date of appointment	7-May-18
Date of survey	7-May-18
Location of survey	K KIM HIN

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLX 452K
Make and Model	TOYOTA LEXUS RX450H
Date of registration	14/7/2010
Excess	NIL
Market Value	\$ 60,000.00
Part Rebate	\$ 33,389.00
Nett Loss	\$ 26,611.00

Repair details:

Initial Estimate	\$ 39,523.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 21,573.00
Check items (estimate)	\$ 14,150.00
Labour	\$ 2,380.00
Total	\$ 38,103.00
Lump Sum(if applicable)	\$

Number of days for repair	<u>11</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62565561 FAX : (065) 62564315

Remarks:

PENDING FOR INVESTIGATION.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 08/05/18

Survey Details:

Date of loss	28-Apr-18
Date of appointment	7-May-18
Date of survey	7-May-18
Location of survey	K KIM HIN

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLX 452K
Make and Model	TOYOTA LEXUS RX450H
Date of registration	14/7/2010
Excess	NIL
Market Value	\$ 60,000.00
Parf Rebate	\$ 33,389.00
Nett Loss	\$ 26,611.00

Repair details:

Initial Estimate	\$ 5,016.00	(SN+LABOUR)
------------------	-------------	-------------

Proposed/Revised repair cost:

Parts	\$ 86.00	(SN only)
Check items (estimate)	\$ 1,130.00	(SN+LABOUR)
Labour	\$ 2,380.00	
Total	\$ 3,596.00	
Lump Sum(if applicable)	\$	

Number of days for repair	<u>11</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

PENDING FOR PARTS PRICES. PENDING FOR
INVESTIGATION.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6471D
Vehicle Details	
Vehicle No.:	SLX452K
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS RX450H
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	2GRJ249868
Chassis No.:	JTJBC11A402412792
Maximum Power Output:	220.0 kW (295 bhp)
Open Market Value:	\$69,509.00
Original Registration Date:	14 Jul 2010
First Registration Date:	14 Jul 2010
Transfer Count:	1
Actual ARF Paid:	\$41,706.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2020
PARF Rebate Amount:	\$25,023.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jul 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$39,002.00
COE Rebate Amount:	\$8,366.00
Total Rebate Amount:	\$33,389.00

The information contained herein is correct as at 30 Apr 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

May 16 Infiniti Q50 2.0T Premium 1 Owner Agent Maint



Frontier Infiniti Q50 Agent
Serviced (Warranted) Low Mileage!
Down Call Now To View
Shine Connect [Contact](#)

PRIME MOTOR & LEASING
EDEN FONG CHIEF ENTERPRISES PTE LTD GROUP OF COMPANIES
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

4 vehicles

Lexus RX450h

[Advanced Search](#)

Model	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Lexus RX450h	Any	Any	2009	Any	Any	Any	Available
	Lexus RX450h Hybrid Fuel Type: Petrol-Electric Fuel Efficient Hybrid Lexus 450. New Battery Changed. Accident Free. Trade In Welcome. High Loan Available. Arrange For Viewing Now. Posted: 02-May-2018 Tags: 2009 Lexus RX450h, Lexus RX450h, Lexus, RX450h, Used Lexus	\$43,500	\$15,140 /yr	06-Nov-2009	3,456 cc	-	SUV	Available
	Lexus RX450h Hybrid Fuel Type: Petrol-Electric Careful Car Owner With A Lot Of High End Audio Add Ons, Clean And Neat Interior Leather, 100% Accident Free, Vehicle Service And Maintained Regularly, Extended Warranty Can Be Arrange For Peace Of Min... Starise Automobile Posted: 28-Apr-2018 Tags: 2009 Lexus RX450h, Lexus RX450h, Lexus, RX450h, Used Lexus	\$43,800	\$18,170 /yr	13-Aug-2009	3,456 cc	80,000 km	SUV	Available
	Lexus RX450h Hybrid Fuel Type: Petrol-Electric CHEAPEST In The Market! Brand New Paintwork And Brand New Leather Upholstery, Stain-Resistant Leather Seats! Like New Car! Car Serviced Regularly, Excellent Condition, View To Appreciate. Posted: 06-Apr-2018 Tags: 2009 Lexus RX450h, Lexus RX450h, Lexus, RX450h, Used Lexus	\$48,800	\$20,570 /yr	17-Sep-2009	3,456 cc	120,000 km	SUV	Available
	Lexus RX450h Hybrid Fuel Type: Petrol-Electric Well Maintained By Meticulous Owner, Excellent Condition, Beautiful Paintwork. Lexus Flagship Model, Powerful And Efficient Luxury SUV, Please Feel Free To Call Our Friendly Sales Consultants Now For ... Car Lingual Posted: 12-Mar-2018 Tags: 2009 Lexus RX450h, Lexus RX450h, Lexus, RX450h, Used Lexus	\$47,800	\$23,590 /yr	30-Jun-2009	3,456 cc	104,000 km	SUV	Available

Save this search criteria, to get email alerts whenever a match is found.

Model Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Article](#) [Forum](#) [Resources](#)


sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CQE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Lexus RX450h, Lexus RX450h Singapore, used Lexus RX450h Singapore, used Lexus RX450h, used vehicles Singapore or even buy used Lexus RX450h Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CQE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[Join Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.



inchcapepreowned.com.sg

VIEW CERTIFIED CARS

TOYOTA
Preferred

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Promos! Best Deal! Fast Selling! Hurry! Down Now!



Flexible Loan Trade In & Sell
Welcome! 120% Deposit Refund
For Long-term Loan
Classic Credit - Quick!

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Sort by Date Posted

20 results/page

1 vehicles

Lexus RX450h

Advanced Search

Search Selection

Lexus RX450h

Any

Any

2011

Any

Any

Any

Available



Lexus RX450h Hybrid

\$81,800

\$16,810 /yr

19-Dec-2011

3,456 cc

-

SUV

Available

Fuel Type: Petrol-Electric

Hurry! Beautiful SUV With Ultra Spacious, Powerful And Very Comfortable Seating. Benchmark Of Luxury In SUV Sector. Selling With 3 Digits Plate Number, Flexible Loan, Flexible Loan And High Trade In A...

Classic Credit Pte Ltd

Posted: 04-May-2018 Tags: 2011 Lexus RX450h, Lexus RX450h, Lexus, RX450h, Used Lexus

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Home

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Article

Forum

Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Lexus RX450h, Lexus RX450h Singapore, used Lexus RX450h Singapore, used Lexus RX450h, used vehicles Singapore or even buy used Lexus RX450h Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2018 10:54
Date Of Accident	28/04/2018 15:30
Exact Location Of Accident	CHANGI GOLF CLUB CARPARK — 3pm
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX452K
Insured/Policyholder	
Name Of Registered Owner	HIRANPAL SINGH S/O PREM SINGH
NRIC No	S8236471D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81574624
Alternative Phone No	OFFICE-81574624

Vehicle Particulars

Manufacturer	TOYOTA
Model	LEXUS-3.5 RX450 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA342609
Cover Note Number	

Driver

Name of Driver	PREM SINGH
NRIC No	S0175352E
Date Of Birth	05/02/1953
Occupation	INDOOR
Date Of Driving Pass	26/01/1971
Driving Experience	47 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96838906
Fax Number	
Contact Number	
EMail Address	PREMSS@SINGNET.COM.SG

Address	526 MILTONIA CLOSE #01-19
Postcode	768107
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *Shuman*
NRIC/FIN No: *3014/2018 @ 1003111*



SKETCH PLAN

CP Entrance

security post

Fire

A = 81x452K

Change Golf Club CO

At about 4:00 pm while I was on the golf course the club staff came to look for me to inform me that my car was full of smoke. He drove me to my car in the clubhouse. When I arrived in the Clubhouse, I saw the fireman has smashed the door window (driver seat) and doused the smoke with water. I opened my car door and they pour ^{more} ~~water~~ water on the side of the door.

I/We declare the foregoing particulars are true in every respect:

Company Chop (if applicable)

Date & Time:

NRIC/FIN No.

30/4/19 @
10-15 AM



This is a computer generated Fire Report. No signature is required.

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : GA342609
Accident Date : 28-Apr-2018

Our Ref : 180294 / SHUMAN

HIRANPAL SINGH S/O PREM SINGH (MR)
C/O AXA INSURANCE PRIVATE LIMITED
8 SHENTON WAY
#24-01 AXA TOWER
Singapore 068811

No. : 29753

Date : 07-May-2018

PAGE : 1

Not Notarized
Purmy B4pain

ESTIMATED COST OF REPAIR FOR LEXUS RX450H 3456cc (2010) SLX452K

=====

1 pc o/s front door *B -* *(B) Bunt*
1 pc o/s front door glass *Shattered -*
1 pc o/s front door glass run *B -*
channel
1 pc o/s front door glass run *B -*
channel lower frame
1 pc o/s front door glass regulator *B -*
1 pc o/s front door glass regulator *B -*
motor
1 pc o/s front door glass top *B -*
chrome moulding
12 pcs o/s front door glass top *m -*
chrome moulding rivet
1 pc o/s front door glass bottom *B -*
chrome moulding
1 pc o/s front door glass frame *B -*
front moulding
1 pc o/s front door glass frame *B -*
rear moulding
1 pc o/s front door top inner *B -*
garnish
2 pcs o/s front door top inner *m -*
garnish clips
1 pc o/s front door hinges - top *?*
1 pc o/s front door hinges - bottom *?*
1 pc o/s front door checker *?*
1 pc o/s front door checker cover *B -*
1 pc o/s front door weatherstrip *B -*

Con't Page 2 ...



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : GA342609

Our Ref : 180294

Page : 2

No. : 29753

- 1 pc o/s front door frame B
- weatherstrip
- 4 pcs o/s front door stopper B
- 1 pc o/s front door protection B
- plastic cover
- 1 pc o/s front door mirror install ?
- hole cover
- 1 pc o/s front door inner trim B
- board
- 1 pc o/s front door inner trim B
- board bracket
- 1 pc o/s front door inner trim B
- board pocket trim
- 15 pcs o/s front door inner trim M
- board clips
- 1 pc o/s front door inner trim B
- board lamp
- 1 pc o/s front door inner trim B
- board top moulding
- 1 pc o/s front door top speaker B
- small
- 1 pc o/s front door top speaker ?
- grille
- 1 pc o/s front door bottom speaker ?
- big
- 1 pc o/s front door bottom speaker ?
- grille
- 1 pc o/s front door lock M
- 1 pc o/s front door inner handle B
- 1 pc o/s front door inner handle B
- screw cover
- 1 pc o/s front door inner handle B
- cabl-lock
- 1 pc o/s front door inner handle ?
- cabl-remote
- 1 pc o/s front door outer handle B
- 1 pc o/s front door outer handle M
- seal
- 1 pc o/s front door outer handle

Con't Page 3

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : GA342609
Our Ref : 180294

Page : 3
No. : 29753

- 1 pc side cover *B-*
- 1 pc o/s front door outer handle *mu*
- side cover seal
- 1 pc o/s front door outer handle *1*
- base
- 1 pc o/s front door outer handle *1*
- rod
- 1 pc o/s front door seat memory *1*
- switch
- 1 pc o/s front door mirror control *B-*
- switch assy
- 1 pc o/s front door mirror control *B-*
- switch top trim
- 1 pc o/s front door power windows *B-*
- master switch
- 1 pc o/s front door power windows *B-*
- master switch top trim
- 1 pc o/s front door lock cylinder *1*
- set
- 1 pc o/s front door wireharness *1*
- 1 pc o/s front door step garnish *1*
- 1 pc front A-Pillar inner trim (lh) *1*
- 1 pc front A-Pillar inner trim (rh) *B-*
- 1 pc B-Pillar inner trim-top (lh) *1*
- 1 pc B-Pillar inner trim-top (rh) *B-*
- 1 pc pillar inner trim-bottom (lh) *1*
- 1 pc pillar inner trim-bottom (rh) *1*
- 1 pc C-Pillar inner trim-top (lh) *1*
- 1 pc C-Pillar inner trim-top (rh) *1*
- 1 pc o/s roof top airbag *B-*
- 1 pc o/s roof top airbag *B-*
- wireharness
- 1 pc roof top inner trim lining *B-*
- 1 pc roof top inner silencer pad *1*
- front
- 1 pc roof top inner silencer pad *1*
- No. 1
- 3 pcs roof top inner silencer pad *1*
- No. 2

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : GA342609
Our Ref : 180294

Page : 4
No. : 29753

1 pc interior lamp centre - main B-
1 pc driver roof visor B-
1 pc driver roof visor bracket ?
1 pc driver roof visor bracket ?
cover
1 pc driver roof visor holder ?
1 pc driver roof visor interior B-
lamp
1 pc driver roof visor interior ?
lamp wireharness
1 pc front roof top handle (lh) ?
1 pc front roof top handle (rh) B-
1 pc rear roof top handle (lh) ?
1 pc rear roof top handle (rh) ?
1 pc rear roof top coat hook (lh) ?
1 pc rear roof top coat hook (rh) ?
1 pc air con blower ?
1 pc air con cooling coil ?
1 pc air con filter ?
1 pc front windscreen glass B-
1 pc front windscreen glass m-
moulding
1 pc floor panel carpet ?
1 pc antenna cord assy - No. 1 ?
1 pc antenna cord assy - No. 2 ?
1 pc rear washer hose - No. 1
1 pc rear washer hose joint - No. 2 ?
1 pc rear washer hose - No. 2 ?
1 pc rear washer hose joint - No. 3 ?
1 pc rear washer hose - No. 3 ?
1 pc dashboard B-
1 pc driver seat belt B-
1 pc driver seat headrest B-
1 pc driver seat cushion cover B-
1 pc driver seat back cover B-
1 pc o/s front door heat insulation
1 pc front windscreen glass sealant

150.00 sn ?
m 40.00 sn ✓

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : GA342609

Our Ref : 180294

Page : 5

No. : 29753

1 pc front windscreen glass damping
seal
1 pc front windscreen glass solar
film
1 pc ERP bracket

M 20.00 sn ✓

250.00 sn ?

M 26.00 sn ✓

To tow accident vehicle to workshop
by normal towing

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

500
800.00

To remove and renew front wind-
screen glass and conduct water
leak test.

100.00 ✓

To remove aircon condenser, pipes
and driers. Vacuum and recharge gas

100.00 ✓

To remove and renew front
instrument panel assy, to rewiring
and transfer instrument fittings.

280.00 250

To remove and renew air bag sensors
seat belts assy, to rewiring and
re-setting program

300.00 250

To remove door's fittings

100.00 60

To remove and renew door glass.
Vacuum and clean up glass-splinter.

80.00 50

To putty and respray on affected
portions.

1,600.00 800

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : GA342609
Our Ref : 180294

Page : 6
No. : 29753

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

15d
280.00

To remove and refit front seat assy
trim board and carpet to facilitate
repairing works

160.00 12d

To remove and renew floor carpet

280.00 ?

To remove and refit interior
fittings such as carpet, seats and
interior fitting and send for
chemical wash.

450.00 ?

Total : S\$ 5,016.00
=====

Singapore Dollars Five Thousand and Sixteen Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : GA342609
Accident Date : 28-Apr-2018

No. : 29753

Date : 07-May-2018

Our Ref : 180294 / SHUMAN

PAGE : 1

HIRANPAL SINGH S/O PREM SINGH (MR)
C/O AXA INSURANCE PRIVATE LIMITED
8 SHENTON WAY
#24-01 AXA TOWER
Singapore 068811

*Not Authorized
1-B-1
Resurvey B4 pain*

ESTIMATED COST OF REPAIR FOR LEXUS RX450H 3456cc (2010) SLX452K

1 pc	o/s front door ✓		460.00	c	B
1 pc	o/s front door glass ✓		300.00	c	Shattered
1 pc	o/s front door glass run channel		80.00	c	B
1 pc	o/s front door glass run channel lower frame		120.00	c	B
1 pc	o/s front door glass regulator ✓		125.00	c	B
1 pc	o/s front door glass regulator motor ✓		215.00	c	B
1 pc	o/s front door glass top chrome moulding ✓		195.00	c	B
12 pcs	o/s front door glass top chrome moulding rivet ✓ @ S\$ 2.50		30.00	c	acc
1 pc	o/s front door glass bottom chrome moulding ✓		85.00	c	B
1 pc	o/s front door glass frame front moulding ✓		70.00	c	B
1 pc	o/s front door glass frame rear moulding ✓		70.00	c	B
1 pc	o/s front door top inner garnish ✓		65.00	c	B
2 pcs	o/s front door top inner garnish clips ✓ @ S\$ 3.00		6.00	c	acc
1 pc	o/s front door hinges - top ?		40.00	c	X B
1 pc	o/s front door hinges - bottom ?		40.00	c	X B
1 pc	o/s front door checker ?		115.00	c	X

LKK Auto Consultant - ends notify the Repairer of the following:

- To resurvey before/after body painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dam(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : GA342609
Our Ref : 180294

Page : 2
No. : 29753

1 pc	o/s front door checker cover ✓	35.00	c B
1 pc	o/s front door weatherstrip ✓	120.00	c B
1 pc	o/s front door frame ✓ weatherstrip	140.00	c B
4 pcs	o/s front door stopper ✓ ✓ @ S\$ 5.00	20.00	c B
1 pc	o/s front door protection plastic cover	60.00	c B
1 pc	o/s front door mirror install ? hole cover	60.00	c ? ✓
1 pc	o/s front door inner trim ✓ board	2,600.00	c B
1 pc	o/s front door inner trim ✓ board bracket	145.00	c B
1 pc	o/s front door inner trim ✓ board pocket trim	170.00	c B
15 pcs	o/s front door inner trim ✓ @ S\$ 3.00 board clips	45.00	c rec
1 pc	o/s front door inner trim ✓ board lamp	65.00	c B
1 pc	o/s front door inner trim ✓ board top moulding	181.00	c B
1 pc	o/s front door top speaker ✓ - small	260.00	c B
1 pc	o/s front door top speaker ? grille	50.00	c ?
1 pc	o/s front door bottom speaker ? - big	350.00	c ?
1 pc	o/s front door bottom speaker ? grille	50.00	c ?
1 pc	o/s front door lock ✓	500.00	c Tn
1 pc	o/s front door inner handle ✓	340.00	c B
1 pc	o/s front door inner handle ✓ screw cover	20.00	c B
1 pc	o/s front door inner handle ✓ cable-lock	50.00	c B
1 pc	o/s front door inner handle ? cable-remote	50.00	c X

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : GA342609
Our Ref : 180294

Page : 3
No. : 29753

1 pc	o/s front door outer handle ✓	360.00	c B
1 pc	o/s front door outer handle seal ✓	10.00	c rec
1 pc	o/s front door outer handle side cover ✓	30.00	c B
1 pc	o/s front door outer handle side cover seal ✓	10.00	c rec
1 pc	o/s front door outer handle base ?	B 480.00	c ?
1 pc	o/s front door outer handle rod ?	B 90.00	c ?
1 pc	o/s front door seat memory switch ?	B 340.00	c ✓
1 pc	o/s front door mirror control switch assy ✓	270.00	c B
1 pc	o/s front door mirror control switch top trim ✓	120.00	c B
1 pc	o/s front door power windows master switch ✓	170.00	c B
1 pc	o/s front door power windows master switch top trim ✓	110.00	c B
1 pc	o/s front door lock cylinder set ?	B 180.00	c ?
1 pc	o/s front door wireharness ?	B 900.00	c ✓
1 pc	o/s front door step garnish ?	180.00	c X
1 pc	front A-Pillar inner trim (lh) ?	240.00	c X
1 pc	front A-Pillar inner trim (rh) ✓	240.00	c B
1 pc	B-Pillar inner trim-top (lh) ?	B 265.00	c ✓
1 pc	B-Pillar inner trim-top (rh) ✓	265.00	c B
1 pc	pillar inner trim-bottom (lh) ?	290.00	c X
1 pc	pillar inner trim-bottom (rh) ?	290.00	c X
1 pc	C-Pillar inner trim-top (lh) ?	270.00	c X
1 pc	C-Pillar inner trim-top (rh) ?	270.00	c X
1 pc	o/s roof top airbag ✓	1,700.00	c B
1 pc	o/s roof top airbag wireharness ✓	500.00	c B
1 pc	roof top inner trim lining ✓	3,120.00	c B

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : GA342609
Our Ref : 180294

Page : 4
No. : 29753

1 pc	roof top inner silencer pad ?	180.00	c	X
	- front			
1 pc	roof top inner silencer pad ?	180.00	c	X
	- No. 1			
3 pcs	roof top inner silencer pad ? @ S\$180.00	540.00	c	X
	- No. 2			
1 pc	interior lamp centre - main	175.00	c	B
1 pc	driver roof visor	345.00	c	B
1 pc	driver roof visor bracket ?	35.00	c	X
1 pc	driver roof visor bracket ?	30.00	c	X
	cover			
1 pc	driver roof visor holder ?	45.00	c	B
1 pc	driver roof visor interior lamp	140.00	c	B
1 pc	driver roof visor interior lamp wireharness	500.00	c	B
1 pc	front roof top handle (lh) ?	150.00	c	B
1 pc	front roof top handle (rh) ?	150.00	c	B
1 pc	rear roof top handle (lh) ?	150.00	c	X
1 pc	rear roof top handle (rh) ?	150.00	c	X
1 pc	rear roof top coat hook (lh) ?	30.00	c	X
1 pc	rear roof top coat hook (rh) ?	30.00	c	X
1 pc	air con blower ?	1,700.00	c	X
1 pc	air con cooling coil ?	3,160.00	c	X
1 pc	air con filter ?	60.00	c	X
1 pc	front windscreen glass	1,700.00	c	B
1 pc	front windscreen glass moulding	130.00	c	acc
1 pc	floor panel carpet ?	990.00	c	
1 pc	antenna cord assy - No. 1 ?	180.00	c	
1 pc	antenna cord assy - No. 2 ?	180.00	c	
1 pc	rear washer hose - No. 1 ?	50.00	c	
1 pc	rear washer hose joint - No. 2 ?	30.00	c	
1 pc	rear washer hose - No. 2 ?	30.00	c	
1 pc	rear washer hose joint - No. 3 ?	30.00	c	
1 pc	rear washer hose - No. 3 ?	40.00	c	
1 pc	dashboard	2,100.00	c	B

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : GA342609
Our Ref : 180294

Page : 5
No. : 29753

1 pc driver seat belt	1,600.00 c B
1 pc driver seat headrest	270.00 c b
1 pc driver seat cushion cover	700.00 c b
1 pc driver seat back cover	700.00 c b
1 pc o/s front door heat insulation	sn 150.00 sn X
1 pc front windscreen glass sealant	✓ 40.00 sn inc
1 pc front windscreen glass damping seal	✓ 20.00 sn inc
1 pc front windscreen glass solar film	sn 250.00 sn X
1 pc ERP bracket	✓ 26.00 sn inc
To tow accident vehicle to workshop by normal towing	
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	
	500 800.00
To remove and renew front windscreen glass and conduct water leak test.	
	100.00
To remove aircon condenser, pipes and driers. Vaccum and recharge gas	
	100.00
To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.	
	250 280.00
To remove and renew air bag sensors seat belts assy, to rewiring and re-setting program	
	250 300.00
To remove door's fittings	
	GO 100.00

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : GA342609
Our Ref : 180294

Page : 6
No. : 29753

To remove and renew door glass.
Vacuum and clean up glass-splinter.

50 80.00

To putty and respray on affected
portions.

1,600.00 300

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

280.00 150

To remove and refit front seat assy
trim board and carpet to facilitate
repairing works

160.00 120

To remove and renew floor carpet

un 280.00 X

To remove and refit interior
fittings such as carpet, seats and
interior fitting and send for
chemical wash.

450.00 200

Total : S\$39,523.00

Singapore Dollars Thirty Nine Thousand Five Hundred
and Twenty Three Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18008297/Kqbe2

8 SHENTON WAY #24-01

AXA TOWERSINGAPORE 068811

Date : 19-11-2018



ATTN : KITTY TEO

Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLX 452K
Policy No.	GA342609	Coverage (\$)	0.00
Claim No.	S8MD0FO5	Excess (\$)	0.00
Assign From	KITTY TEO	Assign Date	07/05/2018

2. Vehicle Particulars & Condition

Make & Model	LEXUS RX450H (A)	c.c	3456
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTJBC11A402412792	Colour	METALLIC DARK GREY
Odometer	88988	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/60 R18	BRIDGESTONE	2 mm
L/H Front Tyre	235/60 R18	BRIDGESTONE	2 mm
R/H Rear Tyre	235/60 R18	BRIDGESTONE	3 mm
L/H Rear Tyre	235/60 R18	BRIDGESTONE	3 mm

4. Description of Damages

THE VEHICLE CAUGHT FIRE.THE CAUSE OF FIRE PROBABLY DUE TO SHORT CIRCUIT AT THE FRONT RH DOOR WIRING.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/04/2018	Inspection Date	07/05/2018
Survey held at	160 SIN MING DRIVE #02-18		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$60,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 452K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S FRONT DOOR (CONSISTENT)	BURNT	460.00	460.00
1	O/S FRONT DOOR GLASS (CONSISTENT)	SHATTERED	300.00	300.00
1	O/S FRONT DOOR GLASS RUN CHANNEL (CONSISTENT)	BURNT	80.00	80.00
1	O/S FRONT DOOR GLASS RUN CHANNEL LOWER FRAME (CONSISTENT)	BURNT	120.00	120.00
1	O/S FRONT DOOR GLASS REGULATOR (CONSISTENT)	BURNT	125.00	125.00
1	O/S FRONT DOOR GLASS REGULATOR MOTOR (CONSISTENT)	BURNT	215.00	215.00
1	O/S FRONT DOOR GLASS TOP CHROME MOULDING (CONSISTENT)	BURNT	195.00	195.00
12	O/S FRONT DOOR GLASS TOP CHROME MOULDING RIVET @\$2.50 (CONSISTENT)	NECESSARY	30.00	30.00
1	O/S FRONT DOOR GLASS BOTTOM CHROME MOULDING (CONSISTENT)	BURNT	85.00	85.00
1	O/S FRONT DOOR GLASS FRAME FRONT MOULDING (CONSISTENT)	BURNT	70.00	70.00
1	O/S FRONT DOOR GLASS FRAME REAR MOULDING (CONSISTENT)	BURNT	70.00	70.00
1	O/S FRONT DOOR TOP INNER GARNISH (CONSISTENT)	BURNT	65.00	65.00
2	O/S FRONT DOOR TOP INNER GARNISH CLIPS @\$3.00 (CONSISTENT)	NECESSARY	6.00	6.00
1	O/S FRONT DOOR HINGES - TOP (CONSISTENT)	TO REPAIR SEE LABOUR	40.00	-
1	O/S FRONT DOOR HINGES - BOTTOM (CONSISTENT)	TO REPAIR SEE LABOUR	40.00	-
1	O/S FRONT DOOR CHECKER (CONSISTENT)	SERVICEABLE	115.00	-
1	O/S FRONT DOOR CHECKER COVER (CONSISTENT)	BURNT	35.00	35.00
1	O/S FRONT DOOR WEATHERSTRIP (CONSISTENT)	BURNT	120.00	120.00
1	O/S FRONT DOOR FRAME WEATHERSTRIP (CONSISTENT)	BURNT	140.00	140.00
4	O/S FRONT DOOR STOPPER @\$5.00 (CONSISTENT)	BURNT	20.00	20.00
1	O/S FRONT DOOR PROTECTION PLASTIC COVER (CONSISTENT)	BURNT	60.00	60.00
1	O/S FRONT DOOR MIRROR INSTALL HOLE COVER (CONSISTENT)	BURNT	60.00	60.00

Report Ref No. CS/ASM18008297/Kqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	O/S FRONT DOOR INNER TRIM BOARD (CONSISTENT)	BURNT	2,600.00	2,600.00
1	O/S FRONT DOOR INNER TRIM BOARD BRACKET (CONSISTENT)	BURNT	145.00	145.00
1	O/S FRONT DOOR INNER TRIM BOARD POCKET TRIM (CONSISTENT)	BURNT	170.00	170.00
15	O/S FRONT DOOR INNER TRIM BOARD CLIPS @\$3.00 (CONSISTENT)	NECESSARY	45.00	45.00
1	O/S FRONT DOOR INNER TRIM BOARD LAMP (CONSISTENT)	BURNT	65.00	65.00
1	O/S FRONT DOOR INNER TRIM BOARD TOP MOULDING (CONSISTENT)	BURNT	181.00	181.00
1	O/S FRONT DOOR TOP SPEAKER - SMALL (CONSISTENT)	BURNT	260.00	260.00
1	O/S FRONT DOOR TOP SPEAKER GRILLE (CONSISTENT)	BURNT	50.00	50.00
1	O/S FRONT DOOR BOTTOM SPEAKER - BIG (CONSISTENT)	BURNT	350.00	350.00
1	O/S FRONT DOOR BOTTOM SPEAKER GRILLE (CONSISTENT)	BURNT	50.00	50.00
1	O/S FRONT DOOR LOCK (CONSISTENT)	TORN	500.00	500.00
1	O/S FRONT DOOR INNER HANDLE (CONSISTENT)	BURNT	340.00	340.00
1	O/S FRONT DOOR INNER HANDLE SCREW COVER (CONSISTENT)	BURNT	20.00	20.00
1	O/S FRONT DOOR INNER HANDLE CABLE - LOCK (CONSISTENT)	BURNT	50.00	50.00
1	O/S FRONT DOOR INNER HANDLE CABLE - REMOTE (CONSISTENT)	SERVICEABLE	50.00	-
1	O/S FRONT DOOR OUTER HANDLE (CONSISTENT)	BURNT	360.00	360.00
1	O/S FRONT DOOR OUTER HANDLE SEAL (CONSISTENT)	NECESSARY	10.00	10.00
1	O/S FRONT DOOR OUTER HANDLE SIDE COVER (CONSISTENT)	BURNT	30.00	30.00
1	O/S FRONT DOOR OUTER HANDLE SIDE COVER SEAL (CONSISTENT)	NECESSARY	10.00	10.00
1	O/S FRONT DOOR OUTER HANDLE BASE (CONSISTENT)	BURNT	480.00	480.00
1	O/S FRONT DOOR OUTER HANDLE ROD (CONSISTENT)	BURNT	90.00	90.00
1	O/S FRONT DOOR SEAT MEMORY SWITCH (CONSISTENT)	BURNT	340.00	340.00
1	O/S FRONT DOOR MIRROR CONTROL SWITCH ASSY (CONSISTENT)	BURNT	270.00	270.00

Report Ref No. CS/ASM18008297/Kqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	O/S FRONT DOOR MIRROR CONTROL SWITCH TOP TRIM (CONSISTENT)	BURNT	120.00	120.00
1	O/S FRONT DOOR POWER WINDOWS MASTER SWICTH (CONSISTENT)	BURNT	170.00	170.00
1	O/S FRONT DOOR POWER WINDOWS MASTER SWITCH TOP TRIM (CONSISTENT)	BURNT	110.00	110.00
1	SET O/S FRONT DOOR LOCK CYLINDER (CONSISTENT)	BURNT	180.00	180.00
1	O/S FRONT DOOR WIREHARNESS (CONSISTENT)	BURNT	900.00	900.00
1	O/S FRONT DOOR STEP GARNISH (CONSISTENT)	SERVICEABLE	180.00	-
1	FRONT A-PILLAR INNER TRIM (LH) (CONSISTENT)	SERVICEABLE	240.00	-
1	FRONT A-PILLAR INNER TRIM (RH) (CONSISTENT)	BURNT	240.00	240.00
1	B-PILLAR INNER TRIM-TOP (LH) (CONSISTENT)	BURNT	265.00	265.00
1	B-PILLAR INNER TRIM-TOP (RH) (CONSISTENT)	BURNT	265.00	265.00
1	PILLAR INNER TRIM - BOTTOM (LH) (CONSISTENT)	SERVICEABLE	290.00	-
1	PILLAR INNER TRIM - BOTTOM (RH) (CONSISTENT)	SERVICEABLE	290.00	-
1	C-PILLAR INNER TRIM-TOP (LH) (CONSISTENT)	SERVICEABLE	270.00	-
1	C-PILLAR INNER TRIM-TOP (RH) (CONSISTENT)	SERVICEABLE	270.00	-
1	O/S ROOF TOP AIRBAG (CONSISTENT)	BURNT	1,700.00	1,700.00
1	O/S ROOF TOP AIRBAG WIREHARNESS (CONSISTENT)	BURNT	500.00	500.00
1	ROOF TOP INNER TRIM LINING (CONSISTENT)	BURNT	3,120.00	3,120.00
1	ROOF TOP INNER SILENCER PAD - FRONT (CONSISTENT)	SERVICEABLE	180.00	-
1	ROOF TOP INNER SILENCER PAD - NO.1 (CONSISTENT)	SERVICEABLE	180.00	-
3	ROOF TOP INNER SILENCER PAD - NO.2 @\$180.00 (CONSISTENT)	SERVICEABLE	540.00	-
1	INTERIOR LAMP CENTRE - MAIN (CONSISTENT)	BURNT	175.00	175.00
1	DRIVER ROOF VISOR (CONSISTENT)	BURNT	345.00	345.00
1	DRIVER ROOF VISOR BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	35.00	-
1	DRIVER ROOF VISOR BRACKET COVER (CONSISTENT)	TO REPAIR SEE LABOUR	30.00	-
1	DRIVER ROOF VISOR HOLDER (CONSISTENT)	BURNT	45.00	45.00
1	DRIVER ROOF VISOR INTERIOR LAMP (CONSISTENT)	BURNT	140.00	140.00
1	DRIVER ROOF VISOR INTERIOR LAMP WIREHARNESS (CONSISTENT)	BURNT	500.00	500.00
1	FRONT ROOF TOP HANDLE (LH) (CONSISTENT)	BURNT	150.00	150.00

Report Ref No. CS/ASM18008297/Kqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT ROOF TOP HANDLE (RH) (CONSISTENT)	BURNT	150.00	150.00
1	REAR ROOF TOP HANDLE (LH) (CONSISTENT)	SERVICEABLE	150.00	-
1	REAR ROOF TOP HANDLE (RH) (CONSISTENT)	SERVICEABLE	150.00	-
1	REAR ROOF TOP COAT HOOK (LH) (CONSISTENT)	SERVICEABLE	30.00	-
1	REAR ROOF TOP COAT HOOK (RH) (CONSISTENT)	SERVICEABLE	30.00	-
1	AIR CON BLOWER (CONSISTENT)	SERVICEABLE	1,700.00	-
1	AIR CON COOLING COIL (CONSISTENT)	SERVICEABLE	3,160.00	-
1	AIR CON FILTER (CONSISTENT)	SERVICEABLE	60.00	-
1	FRONT WINDSCREEN GLASS (CONSISTENT)	BURNT	1,700.00	1,700.00
1	FRONT WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	130.00	130.00
1	FLOOR PANEL CARPET (CONSISTENT)	SERVICEABLE	990.00	-
1	ANTENNA CORD ASSY - NO.1 (CONSISTENT)	SERVICEABLE	180.00	-
1	ANTENNA CORD ASSY - NO.2 (CONSISTENT)	SERVICEABLE	180.00	-
1	REAR WASHER HOSE - NO.1 (CONSISTENT)	SERVICEABLE	50.00	-
1	REAR WASHER HOSE JOINT - NO.2 (CONSISTENT)	SERVICEABLE	30.00	-
1	REAR WASHER HOSE - NO.02 (CONSISTENT)	SERVICEABLE	30.00	-
1	REAR WASHER HOSE JOINT - NO.3 (CONSISTENT)	SERVICEABLE	30.00	-
1	REAR WASHER HOSE - NO.3 (CONSISTENT)	SERVICEABLE	40.00	-
1	DASHBOARD (CONSISTENT)	BURNT	2,100.00	2,100.00
1	DRIVER SEAT BELT (CONSISTENT)	BURNT	1,600.00	1,600.00
1	DRIVER SEAT HEADREST (CONSISTENT)	BURNT	270.00	270.00
1	DRIVER SEAT CUSHION COVER (CONSISTENT)	BURNT	700.00	700.00
1	DRIVER SEAT BACK COVER (CONSISTENT)	BURNT	700.00	700.00
			34,507.00	24,947.00
	<u>SPECIAL NETT ITEMS</u>			
1	O/S FRONT DOOR HEAT INSULATION (SN) (CONSISTENT)	SERVICEABLE	150.00	-
1	FRONT WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT WINDSCREEN GLASS DAMPING SEAL (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	FRONT WINDSCREEN GLASS SOLAR FILM (SN) (CONSISTENT)	SERVICEABLE	250.00	-

Report Ref No. CS/ASM18008297/Kqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ERP BRACKET (SN) (CONSISTENT)	NECESSARY	26.00	26.00
			486.00	86.00
	LABOUR			
	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY NORMAL TOWING. (NPA)		-	-
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF O/S FRONT DOOR HINGES - TOP, O/S FRONT DOOR HINGES - BOTTOM, DRIVER ROOF VISOR BRACKET AND DRIVER ROOF VISOR BRACKET COVER.		800.00	500.00
	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		100.00	100.00
	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.		100.00	100.00
	TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING AND TRANSFER INSTRUMENT FITTINGS.		280.00	250.00
	TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELTS ASSY, TO REWIRING AND RE-SETTING PROGRAM.		300.00	250.00
	TO REMOVE DOOR'S FITTINGS.		100.00	60.00
	TO REMOVE AND RENEW DOOR GLASS. VACUUM AND CLEAN UP GLASS-SPLINTER.		80.00	50.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		1,600.00	800.00
	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.		280.00	150.00
	TO REMOVE AND REFIT FRONT SEAT ASSY TRIM BOARD AND CARPET TO FACILITATE REPAIRING WORKS.		160.00	120.00
	TO REMOVE AND RENEW FLOOR CARPET.	NOT NECESSARY	280.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS SUCH AS CARPET, SEATS AND INTERIOR FITTING AND SEND FOR CHEMICAL WASH.		450.00	200.00
			4,530.00	2,580.00
GRAND TOTAL			39,523.00	27,613.00

Report Ref No. CS/ASM18008297/Kqbe2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			22,000.00
---	--	--	-----------

Report Ref No. CS/ASM18008297/Kqbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.