

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

KENNY GROCERY
23 ENG KONG TERRACE
SINGAPORE 598995

DATE	4/5/2018
VEHICLE NO:	GY 9537 U
MAKE:	TOYOTA
MODEL:	HIACE

TP FWD
Ashes

JTFHS02P40002d 687

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	FRONT BUMPER <i>Distorted</i>	584.25	584.25 ✓
1 PC	BUMPER SIDE BRACKET <i>new</i>	173.58	173.58 ✓
1 PC	HEADLAMP L/H <i>cracked</i>	656.20	656.20 ✓
1 PC <i>Side Radiator</i>	INTERCOOLER <i>cracked</i>	1,436.10	1,436.10 1255 ✓
1 SET	WIRE HARDNESS (DOOR) <i>cracked</i>	442.58	442.58 ✓
1 SET	WIRE HARDNESS (CONNECTED TO DOOR HARDNESS) <i>crushed</i>	2,252.30	2,252.30 ✓
1 PC	STEP PANEL <i>Distorted</i>	153.97	153.97 ✓
1 PC	DOOR PILLAR <i>Distorted</i>	625.89	625.89 ✓
1 PC	FRONT DOOR <i>Distorted</i>	1,348.90	1,348.90 ✓
1 PC	DOOR WEATHER STRIP <i>cut</i>	195.87	195.87 ✓
1 PC	DOOR PILLAR RUBBER <i>cut</i>	121.25	121.25 ✓
1 PC	POWER WINDOW GEAR <i>cut</i>	298.58	298.58 ✓
1 PC	POWER WINDOW MOTOR <i>cut</i>	551.60	551.60 ✓
1 PC	DOOR HINGE - TOP <i>Best</i>	98.10	98.10 ✓
1 PC	DOOR HINGE - LOWER <i>Best</i>	98.10	98.10 ✓
1 PC	DOOR CHECKER <i>cut</i>	175.60	175.60 ✓
1 PC	DOOR INNER LOCK <i>cut</i>	375.65	375.65 ✓
1 PC	DOOR TRIM <i>cut</i>	422.67	422.67 ✓
	----- SUBTOTAL		10,011.19
LESS 25%	----- LESS 25%	-25.00%	-2,502.80
-	TOWING SERVICE	150.00	150.00 80 ✓
1 PC	BODY LETTERING	35.00	35.00 ✓
-	TO DISMOUNT AND MOUNT DASHBOARD TO FACILITATE REPAIR WORK	450.00	450.00 220 ✓
-	TO REMOVE AND REFIX FRONT WINDSCREEN	250.00	250.00 120 ✓
-	TO DISMOUNT AND MOUNT FRONT UNDER CARRIAGE TO FACILITATE REPAIR WORK	450.00	450.00 ✓
-	TO TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR.	150.00	150.00 80 ✓
-	TO REPLACE DOOR PILLAR / STEP PANEL AND RESTORE FLOORBOARD INCLUDE KNOCKING, CUTTING AND WELDING.	1,800.00	1,800.00 1400 ✓
-	TO REPLACE, INSTALL AND ALIGN ABOVE ITEMS TO SYMMETRICAL SPEC.		
-	TO SPRAY PAINT DOOR, STEP PANEL, FLOOR BOARD PANEL AND DOOR PILLAR	1,200.00	1,200.00 800 ✓
-	TO SUPPLY AND TUFF KOTE ON AFFECTED PORTION	250.00	250.00 80 ✓

Tel: 6745 5783 Fax: 6744 9582

Email: sinhweemotor@gmail.com

Website: www.sinhweemotor.com

TOTAL

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

KENNY GROCERY
23 ENG KONG TERRACE
SINGAPORE 598995

DATE	4/5/2018
VEHICLE NO:	GY 9537 U
MAKE:	TOYOTA
MODEL:	HIACE

QUANTITY	DESCRIPTION	UNIT	AMOUNT
----------	-------------	------	--------

TO CARRY OUT WIRE CHECKING ON AFFECTED PARTS

150.00

150.00 *80*

2865

Adrian L

r/s 07/05/18

Supplementary: 813.56.

total: 10667.63

r/s 8.5K

12 Days

LKK Auto Consultancy certify the Repairer of the vehicle • To resurvey before repair • To display damaged parts • Parts prices are shown • Third party survey on "justice" basis • No illegal modification(s) is a • Supplementary items must be approved and is subject to final approval of the Company Acknowledged by Repairer Signature: Date:

Tel: 6745 5783 Fax: 6744 9582
Email: sinhweemotor@gmail.com
Website: www.sinhweemotor.com

TOTAL \$12,393.39

SIN HWEE MOTOR PTE LTD

SUPPLEMENTARY

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

KENNY GROCERY -

DATE	8/5/2018
VEHICLE NO:	GY 9537 U
MAKE:	TOYOTA
MODEL:	HIACE

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	RADIATOR FAN ASSY (BLADE, COWING AND MOTOR) <i>cut</i>	1,601.30	1,601.30 <i>492</i>
1 PC	DOOR PILLAR INNER <i>distorted</i>	297.35	297.35 ✓
1 PC	RADIATOR LOWER BRACKET <i>Be+</i>	98.10	98.10 ✓
1 PC	STEP PANEL INNER <i>Distorted</i>	197.30	197.30 ✓
	----- SUBTOTAL		2,194.05
LESS 25%	----- LESS 25%	-25.00%	-548.51

1084.75

813.56

Tel: 6745 5783 Fax: 6744 9582
Email: sinhweemotor@gmail.com
Website: www.sinhweemotor.com

TOTAL \$1,645.54