

ASS. REC. BY:

REF: CS/MSG18008315/Tlrbnz Special Instruction:

Supervisor
melvin

ASSIGNMENT (Office)

From (Person): Catherine Thia of MSLH Date/Time: 07052018 2:43pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKQ 7624J Insured: SKW 8186T

at Workshop m/s Performance Tel: 6319 0174

of 303 Alexandra Rd

Policy No: 24039800Qmx Claim No: 557536

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 04052018
(Client's Record)

CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: _____

Date/Time: 07052018 2:54pm Person Contacted: Caroline Vehicle IN / OUT IN

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>SKQ 7624J - X</u>
	<u>SKW 8186T - X</u>
	<u>Confirm \$2035.00 , 3 days (Pd: \$2657.75, 57%)</u>

Signature

T. Anglin

REF:

MSIG

ASSIGNMENT

From:

Date: 30/05/2018

Veh No:

SKQ 7624J

Yr Regn:

2014, Dec

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

Truck / Trailer or

To Inspect Vehicle No:

SKQ 7624J

Make:

BMW 428i cc. 1997

at Workshop m/s

Performance

Colour:

Grey

A/C: Insured / Std / NI / NA

of

303 Alexandra Rd

Sp. Reading:

52750

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Chua


Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 255 / 30R20

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rport:

Consistent? : Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

D.O.I.

30/5/18 @ 1050

Lump Sum:

%

3 Val.: Yes or No

Survey held at

pmc

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

Chua

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 29 AUG 2018

Date/Time. File Pass to?

: Preli. Report

Days Of Repair: 3

1) typist

: Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time. File Return to?

Transportation

150

10

Add Fee:

Site Insp. (\$

) \$ + RS \$

Interview (\$

) Photos

Tech. Invs (\$

) Others

Weekend (\$

)

Report Format: TP

Lump Sum / I.B.I: (\$

2035.00

TOTAL:

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 May 2018		07 May 2018 14:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	TIAN XI SHIRLEY, ID: S6874242J		
Main Claimant:	TAN WEI HANN, ID: S7144837A		
Vehicle Reg. No.:	SKQ7624J	Date of Loss:	04/05/2018 18:00 - :59 [40 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 557536	Policy/Cover Note No.:	29029800QMX Coverage: 30/10/2017 - 29/04/2019
Vehicle Reg. No. (Insured):	SKW8186T	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/05/2018]		
Driver/Custodian (Insured):	TIAN XI SHIRLEY (), NRIC: S6874242J		
Adj Asg. Remarks:	TP agreed on SJE - assign LKK Auto Consultants		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS			
		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 29 Aug 2018

Preliminary Advice

Insured Vehicle No	: SKW8186T	Accident Date	: 04/05/2018
TP Vehicle No	: SKQ7624J	Assignment Date	: 07/05/2018
Make	: BMW 428I	Est. Duration of Repair	: 3.00
Date of Inspection	: 30/05/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,692.75
Revised Amount	:S\$	2,035.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,035.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Janice Lee (LKKAuto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, June 21, 2018 3:42 PM
To: SUR; Taufikh (LKKAuto)
Subject: FINAL REPORT / SKQ7624J
Attachments: Final Report SKQ7624J.pdf; Final Report SKQ7624J_2.pdf

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 1,974.00

Total Parts : 61.00

Total Labour & Parts : 2,035.00

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

“This electronic mail content and any accompanying attachments (“the Message”) is intended only for the named addressee (“the Recipient”) and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies (“Sime Darby”) and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/05/2018 11:31
Date Of Accident	04/05/2018 18:45
Exact Location Of Accident	JUNCTION OF DYSON ROAD AND WHITLEY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ7624J
Insured/Policyholder	
Name Of Registered Owner	TAN WEI HANN
NRIC No	S7144837A
Email Address	WEIHANN.TAN@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97809964
Alternative Phone No	OTHERS-97809964

Vehicle Particulars

Manufacturer	BMW
Model	428IA GC
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 27826397 SMP
Cover Note Number	

Driver

Name of Driver	TAN WEI HANN
NRIC No	S7144837A
Date Of Birth	09/12/1971
Occupation	INDOOR
Date Of Driving Pass	04/10/1995
Driving Experience	22 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97809964
Fax Number	
Contact Number	OTHERS-97809964
Email Address	WEIHANN.TAN@YAHOO.COM.SG

Address 23 ENG KONG DRIVE SINGAPORE
 Postcode 599351
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : QUEK SU LYNN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

Details of Witness 1

Name QUEK SU LYNN
 Phone Number 98388110
 Email Address SULYNNQUEK@GMAIL.COM

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKW8186T
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver SHIRLEY TIAN XI
 NRIC/Passport Number S6874242J
 Contact Number 92323201

Address

APT BLK 87 ZION ROAD #16-170 SINGAPORE

Postcode

160087

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
(Date & Time: ..)

Driver's Signature
(If driver is not the policyholder)
(Date & Time: ..)

Reporting Centre Personnel's Signature
Name: ..
(IRC/FR No.): ..

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While waiting to turn into Whitley Road (at the junction of Dyson Road and Whitley Road), my car was stationary when suddenly a car hit my car in the rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time:
5 May 13 / 11.14am

n/a
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
SIC/ID No: @ 111Ahr
5/5/2018

BMW Dealer:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

30/5/2018
Murni
Survey & Repair



GST REG. NO : M2 - 0020081 - X

ESTIMATE

07 MAY 2018

Estimate No. : **b1 46843** Page No. : 1 of 1
Date Estimated : **05/05/2018**
Prepared By : **Chua Kee Sin**

<p>- ESTIMATE REPAIR FOR - Tan Wei Hann (Chen Weihan) 23 Eng Kong Drive Singapore 599351</p>	<p>- ACCOUNT - 40000 Cash Sales - Service Singapore</p>
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ7624J	D571968	26/12/2014	428IA GC	0

DESCRIPTION	VALUE		
Replace rear bumper and remove attachment etc include knock on accident dent	850 1,275.00		
Spray painting rear bumper	934 1,038.00		
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00		
Sundries.	? nec 40.00		
Total Labour 1: 2,530.00			
DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER CARRIER ECE	1	432.90	432.90
REAR BUMPER CENTRE GUIDE	1	55.40	55.40
LEFT PROTECT	1	5.25	5.25
RIGHT PROTEC	1	7.00	7.00
TRIM PANEL BUMPER REAR BOTTOM (M)	1	212.50	R 212.50
REINFORCEMENT BUMPER REAR BOTTOM (M)	1	80.25	WR 80.25
FLAP TOWING EYE PRIMED (M)	1	42.20	R 42.20
REAR BUMPER PANEL PRIMED (M/PDC)	1	1,264.30	R 1,264.30
SET MOUNTS PDC SENSOR REAR (M)	1	62.95	WR 62.95
Total Parts :			2,162.75

and lightings at the rear section for proper function. hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 30/5/18 0105 Excess S\$ _____
Surveyor's Name Tan Jhu Sign Tan Jhu
Surveyor's Tel 97495424 Authorised Yes / No _____
Authorised Date 05/05/18 Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
Surveyor's E-mail tanjhu@hkauto.com 03 days

Labour 1	2,530.00
Parts	2,162.75
Labour 2	0.00
Excess	0.00
Total GST @ 7%	328.49
Grand Total	5,021.24

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY ****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46843
Date Estimated : 05/05/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Tan Wei Hann (Chen Weihan)
23 Eng Kong Drive

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 599351

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKQ7624J	D571968	26/12/2014	428IA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
COVER	61.00	1.00		61.00 <i>mis</i>

Total Labour :	
Total Parts :	61.00
Total Labour & Parts :	61.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46843
Date Estimated : 05/05/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Tan Wei Hann (Chen Weihan)
23 Eng Kong Drive

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 599351

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	ORIGINAL PRICE	DISC. %	NETT	
SKQ7624J	D571968	26/12/2014	428IA GC	0				
DESCRIPTION								
To make good the rear bumper include replacement of damaged part and knocking out dents caused by the accident					850.00		850.00	
To spray paint rear bumper					934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.					150.00		150.00	
Sundries.					40.00		40.00	
DESCRIPTION					UNIT PRICE	QTY	DISC. %	NETT
COVER					61.00	1.00		61.00

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	61.00
Total Labour & Parts :	2,035.00
Deduction for Excess :	
Total Repair Costs less Excess:	2,035.00
GST @7%:	142.45
Grand Total :	2,177.45

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008305/T1RBN2

Date: 30/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29029800QMX
Claimant Vehicle No :	SKQ7624J	Insured Vehicle No :	SKW8186T
Date of Loss:	04/05/2018	Nature of Claim:	TP
		Claim No:	557536

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ7624J	Engine No:	B5750878N20B20A
Make & Model:	BMW 428I, 2.0 Gran Coupe (F36) (A)	Chassis No:	WBA4A52090D571968
Reg. Date:	26/12/2014 (Man. Year: 2014)	Odometer:	52750 km
Colour:	Grey		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/30R20	Rear Tyre Size:	255/30R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,263.75	101.00	2,162.75	95.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,753.75	2,035.00	2,718.75	57.19
+ GST 7.00/7.00% (S\$)	332.76	142.45	190.31	57.19
Nett Amount (S\$)	5,086.51	2,177.45	2,909.06	57.19

INSPECTION

Date of Assignment:	07/05/2018	
Date Inspected:	30/05/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2018)
Parts: 143	BMW 428I 2.0 Gran Coupe (F36) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ7624J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER CARRIER ECE	Not Necessary	432.90 FS	*- FS
2	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	55.40 FS	*- FS
3	1		*LEFT PROTECT	Not Necessary	5.25 FS	*- FS
4	1		*RIGHT PROTEC	Not Necessary	7.00 FS	*- FS
5	1		*TRIM PANEL BUMPER REAR BOTTOM (M)	Repair	212.50 FS	*- FS
6	1		*REINFORCEMENT BUMPER REAR BOTTOM M	Not Necessary	80.25 FS	*- FS
7	1		*FLAP TOWING EYE PRIMED (M)	Repair	42.20 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED (M/PDC)	Repair	1,264.30 FS	*- FS
9	1		*SET MOUNTS PDC SENSOR REAR (M)	Not Necessary	62.95 FS	*- FS
10	1		*COVER	Missing	61.00 FS	*61.00 FS
11	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
Total Parts (\$\$)					2,263.75	101.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	1,275.00	850.00
2	SPRAY PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >