

Trans-cab Auto Services Pte Ltd

AAD1804-303

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 338K

*Not Authorized
Recovery B4 paint*

Vehicle No.:	SHD 338K
Chassis No.:	WDD2120012B223642
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E220 CDI
Date of Accident :	30.4.2018
Third Party Insurer :	III

		PART		LIST
1	1	Front Fender RH	\$	<i>R</i> 2,900.00 X
2	1	Front Fender LEDGE RH	\$	<i>SL</i> 108.00 X
3	1	Front Door <i>RH</i>	\$	<i>B</i> 3,680.00 ✓
4	1	Front Door mirror assy <i>RH</i>	\$	<i>SL</i> 1,750.00 X
5	1	Front Door LEDGE RH	\$	<i>un</i> 360.00 X
6	1	Front Door outer handle seal front	\$	<i>SL</i> 406.22 X
7	1	Front Door hinge - top <i>RH</i>	\$	<i>R</i> 236.00 X
8	1	Front Door hinge bottom <i>RH</i>	\$	<i>R</i> 236.00 X
9	1	Front Door check / arrestor <i>RH</i>	\$	<i>SL</i> 168.00 X
10	1	Rocker Panel <i>RH</i>	\$	<i>R</i> 1,870.00 X
11	1	Rear Door <i>RH</i>	\$	<i>B</i> 3,680.00 ✓
12	1	Rear Door LEDGE <i>RH</i>	\$	<i>un</i> 340.00 X
13	1	Rear Door outer handle seal front RH	\$	<i>SL</i> 406.22 X
14	1	Rear Door hinge bottom RH	\$	<i>R</i> 236.00 X
15	1	Rear Door hinge top RH	\$	<i>R</i> 236.00 X
16	1	Rear Fender <i>RH</i>	\$	<i>B</i> 3,620.00 ✓
17	1	Rear lamp	\$	<i>R</i> 1,040.00 X
18	1	Rear Bumper	\$	<i>R</i> 2,760.00 X
19	1	Rear Bumper Side Retainer Bracket	\$	<i>SL</i> 176.00 X
			\$	24,208.44
TOTAL			\$	2,420.84
10%			\$	21,787.60

Trans-cab Auto Services Pte Ltd

AAD1804-303

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 338K**Special Nett**

1SET	Rear Bumper Fastener Clip	\$	na 120.00 X
1SET	Rocker panel Fastener Clip	\$	na 80.00 X
1	Door corporate sticker	\$	na 160.00 X
1SET	Door LEDGE Clip FTR LH	\$	na 120.00 X
1SET	Door LEDGE Clip RR LH	\$	na 120.00 60.00
2	Rear Windscreen selant	\$	na 160.00 X
1	Windscreen Moulding	\$	na 240.00 X
1	Rear Tyre RH	\$	sn 400.00 X
1	Rear Alloy Rim RH	\$	sn 1,000.00 X

TOTAL	\$	1,700.00
--------------	-----------	-----------------

TOTAL PARTS	\$	12,593.80
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,500.00	900
To Rust-Proofing Of The Affected Areas.	\$	170.00	90
To Check Electrical Lighting Concerned.	\$	170.00	30
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	380.00	} 120
To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test.	\$	170.00	
To Check Steering Geometry And Computer Wheel Alignment.	\$	220.00	X

Trans-cab Auto Services Pte Ltd

AAD1804-303

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 338K

Putty And Spray Painting Of The Affected Portion.	\$	3,200.00 <i>8801</i>
To Transfer Of Door Fittings, Attachment And Perform Water Seepage Test.	\$	170.00 <i>1201</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 <i>1201</i>

TOTAL \$ **8,150.00**

Over All Total \$ **20,743.80**

REPAIR DAYS (PART-BY-PART)

10-DAYS

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: