

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/LC/CHI/0756/2018
DATE : 04-MAY-2018

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#05-00
IOB BUILDING S(049711)
TEL : 63476100
FAX : 62244174

OWNER'S NAME : CHEONG YI MEI GILLINA
ADDRESS : 66 TANAH MERAH KECHIL AVENUE
#10-32
S(465532)
TELEPHONE NO : 9656 9293

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100440183
VEHICLE NO : SDY26Y
MODEL CODE : BS9AKLC
MODEL/YEAR : OUTBACK 2.5I-S AWD CVT
ENGINE NO : FB25Y091185
CHASSIS NO : JF2BS9KC2FG015106
MILEAGE : 1 KM
DATE IN : 04/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 04/05/2018

Print Date : 04/05/2018
Print Time : 12:19:12

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDY26Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM INDIA LOCATION:ECP TERDS AIRPORT DATE:03/05/2018 TIME:1845HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER,PANEL AND TAILGATE	1680.00	11201
4	ZZ/003	RESPRAY REAR BUMPER,PANEL AND TAILGATE	1260.00	✓
5	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	100.00	501
6	ZZ/005	TRANSFER REAR TAILGATE MACHANISM	~ 150.00	X
7	ZZ/006	REMOVE/INSTALL REAR WINDSCREEN	~ 300.00	X
8	ZZ/007	TO CONDUCT REAR LIGHTING TEST	50.00	301
9	ZZ/008	TO CONDUCT REAR PROTECTANT COATING	500.00	2501
10	ZZ/009	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	?
11	ZZ/011	SUNDRIES	100.00	201
12	ZZ/10	TO SUPPLY/INSTALL REAR TINTED FILM	~ 145.00	X
TOTAL LABOUR CHARGES			4585.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY26Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE R OBKFHI	57704AL130	Bu	594.00	✓	
2	BRKT SD R OBK RH	57707AL320	Sm	36.00	X	
3	BRKT SD R OBK LH	57707AL330		36.00	?	
4	BRKT CORNER R OBKRH	57707AL360	Sm	21.60	X	
5	BRKT CORNER R OBK LH	57707AL370	Dis	21.60	✓	
6	BEAM COMPL R OBK EU	57719AL020		396.00	?	
7	COVER HOOK R OBK FHI	57731AL390NN	Net	10.80	✓	
8	REAR RESIN UNDER GUARD OBK	57734AL050	Net	270.00	✓	
9	PANEL COMPL R GAT	60809AL0109P	R	1072.80	X	
10	GLASS ASSY R G	LV5B9 3PC 63019AL140	ru	1861.20	X	
11	RUBBER DAM GLS	63232AL020	ru	7.20	X	
12	SEAL GLS RG A	63242AL000	ru	4.40	X	
13	LENS & BODY COMPROUL	84912AL060	Sm	300.00	X	
14	LENS & BODY COMPLRH	84913AL161	Sm	61.20	X	
15	LENS & BODY COMPL LH	84913AL171	Sm	64.80	X	
16	GARNISH	91111AL000NN		262.80	?	
17	PROTECTOR-REAR GARNISH	91713AG040		14.10	?	
18	PROTECTOR UPR	91713AL000		21.60	?	
19	PROTECTOR LWR SD	91713AL150		2.20	?	
20	PROTECTOR LWR	91713AL190		2.20	?	
21	PROTECTOR SD	91713SG020		8.80	?	
22	ORNAMENT R OBK 6KA	93033AL040	ru	72.00	✓	
23	LETTER MK HOYO	93079AL000	ru	50.40	✓	
24	LETTER MK HOYO	93079AL020	ru	72.00	✓	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY26Y

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
SUB TOTAL		5263.70	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		1052.74	0.00	0.00	0.00
GRAND TOTAL		4210.96	0.00	0.00	0.00
OVERALL TOTAL		4210.96			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDY26Y

TOTAL LABOUR CHARGES	4585.00
TOTAL SPARE PARTS CHARGES	4210.96
GRAND TOTAL	8795.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

*Not Authorized
I-B.I
Resurvey B4 paint
4 days*

*Kenneth Kong
HP 96910663
KennethKong@lkkauto.com*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: