

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0756/2018
DATE : 04-MAY-2018

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#05-00
IOB BUILDING S(049711)
TEL : 63476100
FAX : 62244174

OWNER'S NAME : CHEONG YI MEI GILLINA
ADDRESS : 66 TANAH MERAH KECHIL AVENUE
#10-32
S(465532)
TELEPHONE NO : 9656 9293

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100440183
VEHICLE NO : SDY26Y
MODEL CODE : BS9AKLC
MODEL/YEAR : OUTBACK 2.5I-S AWD CVT
ENGINE NO : FB25Y091185
CHASSIS NO : JF2BS9KC2FG015106
MILEAGE : 1 KM
DATE IN : 04/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 04/05/2018

Print Date : 04/05/2018
Print Time : 12:19:12

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDY26Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM INDIA LOCATION:ECP TERDS AIRPORT DATE:03/05/2018 TIME:1845HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER,PANEL AND TAILGATE	1680.00	
4	ZZ/003	RESPRAY REAR BUMPER,PANEL AND TAILGATE	1260.00	
5	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	100.00	
6	ZZ/005	TRANSFER REAR TAILGATE MACHANISM	150.00	
7	ZZ/006	REMOVE/INSTALL REAR WINDSCREEN	300.00	
8	ZZ/007	TO CONDUCT REAR LIGHTING TEST	50.00	
9	ZZ/008	TO CONDUCT REAR PROTECTANT COATING	500.00	
10	ZZ/009	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	
11	ZZ/011	SUNDRIES	100.00	
12	ZZ/10	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	
		TOTAL LABOUR CHARGES	4585.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY26Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE R OBKFHI	57704AL130	594.00			
2	BRKT SD R OBK RH	57707AL320	36.00			
3	BRKT SD R OBK LH	57707AL330	36.00			
4	BRKT CORNER R OBKRH	57707AL360	21.60			
5	BRKT CORNER R OBK LH	57707AL370	21.60			
6	BEAM COMPL R OBK EU	57719AL020	396.00			
7	COVER HOOK R OBK FHI	57731AL390NN	10.80			
8	REAR RESIN UNDER GUARD OBK	57734AL050	270.00			
9	PANEL COMPL R GAT	60809AL0109P	1072.80			
10	GLASS ASSY R G	LV5B9 3PC 63019AL140	1861.20			
11	RUBBER DAM GLS	63232AL020	7.20			
12	SEAL GLS RG A	63242AL000	4.40			
13	LENS & BODY COMPL OUL	84912AL060	300.00			
14	LENS & BODY COMPL RH	84913AL161	61.20			
15	LENS & BODY COMPL LH	84913AL171	64.80			
16	GARNISH	91111AL000NN	262.80			
17	PROTECTOR-REAR GARNISH	91713AG040	14.10			
18	PROTECTOR UPR	91713AL000	21.60			
19	PROTECTOR LWR SD	91713AL150	2.20			
20	PROTECTOR LWR	91713AL190	2.20			
21	PROTECTOR SD	91713SG020	8.80			
22	ORNAMENT R OBK 6KA	93033AL040	72.00			
23	LETTER MK HOYO	93079AL000	50.40			
24	LETTER MK HOYO	93079AL020	72.00			

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY26Y

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
SUB TOTAL		5263.70	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		1052.74	0.00	0.00	0.00
GRAND TOTAL		4210.96	0.00	0.00	0.00
OVERALL TOTAL		4210.96			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDY26Y

TOTAL LABOUR CHARGES 4585.00
TOTAL SPARE PARTS CHARGES 4210.96

GRAND TOTAL 8795.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.