

Kw

MYTORDIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0756/2018
DATE : 04-MAY-2018

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#05-00
IOB BUILDING S(049711)
TEL : 63476100
FAX : 62244174

OWNER'S NAME : CHEONG YI MET GILLINA
ADDRESS : 66 TANAH MERAH KECIL AVENUE
#10-32
S(465532)
TELEPHONE NO : 9656 9293

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100440183
VEHICLE NO : SDY26Y
MODEL CODE : BS9AKLC
MODEL/YEAR : OUTBACK 2.5I-S AND CVT
ENGINE NO : FB25Y091185
CHASSIS NO : JF2BS9RC2FG015106
MILEAGE : 49552 KM
DATE IN : 04/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 04/05/2018

Print Date : 05/06/2018
Print Time : 15:18:38

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDY26Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SHC3783T - INDIA INT'L		
2	ZZ/001	CONDUCT TP CLAIM INDIA LOCATION: ECP TERDS AIRPORT DATE: 03/05/2018 TIME: 1845HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER, PANEL AND TAILGATE	1680.00	1120.00 ✓
4	ZZ/003	RESPRAY REAR BUMPER, PANEL AND TAILGATE	1260.00	1260.00 ✓
5	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	100.00	50.00 ✓
6	ZZ/005	TRANSFER REAR TAILGATE MACHANISM	150.00	.00
7	ZZ/006	REMOVE/INSTALL REAR WINDSCREEN	300.00	.00
8	ZZ/007	TO CONDUCT REAR LIGHTING TEST	50.00	30.00 ✓
9	ZZ/008	TO CONDUCT REAR PROTECTANT COATING	500.00	250.00 ✓
10	ZZ/009	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	.00 X
11	ZZ/011	SUNDRIES	100.00	20.00 ✓
12	ZZ/012	REMOVE ALIGN & REPLACE EXHAUST SYSTEM (SUPP)	150.00	150.00 ✓
13	ZZ/013	RESPRAY REAR FLOOR PAN (SUPP)	420.00	420.00 ✓
14	ZZ/10	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	.00
TOTAL LABOUR CHARGES			5155.00	3300.00

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY26Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	GASKET (SUPP)	44011SG000	7.20			<i>me</i> OK ✓
2	EXH PIPE ASSY R (SUPP)	<i>B1</i> 44200AL031	720.00			OK ✓ ✓
3	MUFFLER ASSY LH (SUPP)	<i>B1</i> 44300AL020	540.00			OK ✓ ✓
4	BUMPER FACE R OBKPHI	57704AL130	594.00			OK ✓
5	BRKT SD R OBK RH	57707AL320	36.00			<i>R</i> X
6	BRKT SD R OBK LH	57707AL330	36.00			X
7	BRKT CORNER R OBKRH	57707AL360	21.60			X
8	BRKT CORNER R OBKLE	57707AL370	21.60			OK ✓
9	BEAM COMPL R OBK EU	57719AL020	396.00			<i>R</i> X X
10	COVER HOOK R OBK FHI	57731AL390NN	10.80			OK ✓
11	REAR RESIN UNDER GUARD OBK	57734AL050	270.00			OK ✓
12	PANEL COMPL R GAT	60809AL0109P	1072.80			X
13	GLASS ASSY R G	LV5B9 3PC 63019AL140	1861.20			X
14	RUBBER DAM GLS	63232AL020	7.20			X
15	SEAL GLS RG A	63242AL000	4.40			X
16	LENS & BODY COMPL OUL	84912AL060	300.00			X
17	LENS & BODY COMPL RH	84913AL161	61.20			X
18	LENS & BODY COMPL LH	84913AL171	64.80			<i>CM</i> OK ✓
19	GARNISH	91111LAL000NN	262.80			<i>Sm</i> X
20	PROTECTOR-REAR GARNISH	91713AG040	14.10			<i>Sm</i> X
21	PROTECTOR UPR	91713AL000	21.60			<i>Sm</i> X
22	PROTECTOR LWR SD	91713AL150	2.20			<i>nn</i> X
23	PROTECTOR LWR	91713AL190	2.20			<i>nn</i> X
24	PROTECTOR SD	91713SG020	8.80			<i>nn</i> X
25	ORNAMENT R OBK 68A	93033AL040	72.00			OK ✓

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY26Y

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 LETTER MK HOYO	93079AL000	50.40			OK ✓
27 LETTER MK HOYO	93079AL020	72.00			OK ✓
SUB TOTAL		2422.80	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		484.56	0.00	0.00	0.00
GRAND TOTAL		1938.24	0.00	0.00	0.00
OVERALL TOTAL		1938.24			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

