

SMRT Accident Vehicle Repair Estimates



Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1146B
 Ref. No : TAX/05/18/2014
 Reg. Date : 12/10/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : TAN PUAY LONG
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 03/05/2018 02:15:00 PM
 Accident Reported Date / Time : 03/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095877
 Special Instruction to ARC, if any :
 SHC8123R(COMFORT) - III
 Prepared Date : 03/05/2018 04:57:28 PM



Sebastian.
 7/5/18.

- Part by part repair.
- Question Mark Item
- Photo.
- Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU203573057

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 507.00	0.00
Total Spray Painting Charges	: 738.00	0.00
Total Material Charges	: 1,577.45	1,577.45
Other Charges	: 360.00	0.00
TOTAL	: 3,182.45	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 4.00	0.00
Prepared / Adjusted By	:	2 days.
Arc / Surveyor Sign Off Date	: 04/05/2018 10:02:21 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/05/2018 10:02:21 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 5/4/2018 10:03:44 AM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	507.00	0.00 300
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 X
TO RESPRAY BUMPER BEAM	180.00	0.00 7.
Total Spray Painting & Panel Beating	738.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
Total Other Costs	360.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace R	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓	No
5246247030			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace ?	No
5246247020			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace ?	No
5246247010			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace ?	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace ?	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace ✓	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace R	No
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace ?	No
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace ?	No
5256547900			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace X	No
5259147050			SEAL, RR BUMPER , RH	1	85.20	25.00	63.90	Replace	Replace X	No
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace X	No
7539235220			RETAINER, OUTSIDE , RH & LH	1	3.30	25.00	2.47	Replace	Replace X	No
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ?	No
TOTAL MATERIALS								1,577.48	1,577.45	
TOTAL MATERIALS(Discounted)							1,577.45	1,577.45		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									