


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1146B
Ref. No : TAX/05/18/2014
Reg. Date : 12/10/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : TAN PUAY LONG
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 03/05/2018 02:15:00 PM
Accident Reported Date / Time : 03/05/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095877
Special Instruction to ARC,if any :
SHC8123R(COMFORT) - III
Prepared Date : 03/05/2018 04:57:28 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU203573057

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	507.00	0.00
Total Spray Painting Charges :	738.00	0.00
Total Material Charges :	1,577.45	1,577.45
Other Charges :	360.00	0.00
TOTAL :	3,182.45	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	4.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	04/05/2018 10:02:21 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/05/2018 10:02:21 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/4/2018 10:03:44 AM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	507.00	0.00
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00
TO RESPRAY BUMPER BEAM	180.00	0.00
Total Spray Painting & Panel Beating	738.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
Total Other Costs	360.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No
5256547900			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace	No
5259147050			SEAL, RR BUMPER , RH	1	85.20	25.00	63.90	Replace	Replace	No
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No
7539235220			RETAINER, OUTSIDE , RH & LH	1	3.30	25.00	2.47	Replace	Replace	No
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No
TOTAL MATERIALS							1,577.48	1,577.45		
TOTAL MATERIALS(Discounted)							1,577.45	1,577.45		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									