

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	676.00	400.00 ✓
<b>Total Labour</b>	<b>676.00</b>	<b>400.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00 ✓
TO RESPRAY FRONT FENDER RH	378.00	200.00 ✓
TO RESPRAY RIM	180.00	50.00 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>936.00</b>	<b>450.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>580.00</b>	<b>120.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	No ✓
8121047020			LAMP ASSY, FOG, RH	1	910.20	10.00	819.18	Replace	Replace	No ✓
5311247240			GRILLE, RADIATOR	1	165.00	25.00	123.75	Replace	Check	No X
5380147080			FENDER SUB-ASSY, FR, RH	1	933.10	100.00	0.00	Replace	Repair	No R
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No ✓
5387547070			LINER, FR FENDER, RH	0	198.40	25.00	0.00	Replace	Not given	No X
42611-47450			WHEEL, DISC FRONT	1	1,555.10	100.00	0.00	Replace	Repair	No R
5211547050			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.68	Replace	Replace S	No ✓
8114547691			UNIT, HEADLAMP, RH	1	2,558.90	10.00	2,303.01	Replace	Check	No X
<b>TOTAL MATERIALS</b>								<b>3,714.92</b>	<b>1,288.15</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>3,714.90</b>	<b>1,288.14</b>	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

1288.14 ✓  
 + 400.00 ✓  
 + 570.00 ✓  


---

 2258.14 ✓

Sebastian  
 16/5/18

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU403577708 Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	400.00
Total Spray Painting Charges	: 936.00	450.00
Total Material Charges	: 3,714.90	1,288.14
Other Charges	: 580.00	120.00
<b>TOTAL</b>	<b>: 5,906.90</b>	<b>2,258.14</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 5.00	4.00 ✓
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 02/05/2018 01:47:30 PM	03/05/2018 02:48:29 PM

M

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/05/2018 01:47:30 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1805-0158 Invoice No :

Quotation Date : 10/5 Invoice Date :

Invoice Amount : Prepared Date :