

## SMRT Accident Vehicle Repair Estimates

AK

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF390Y  
 Ref. No : TAX/05/18/2004  
 Reg. Date : 19/12/2017  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS4  
 Name of Driver : ARUNAJALAM RAMACHANDRA  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 01/05/2018 01:45:00 PM  
 Accident Reported Date / Time : 02/05/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024095842  
 Special Instruction to ARC, if any :  
 SLX2344B - AIG - LKK  
 Prepared Date : 02/05/2018 12:53:05 PM



Sebastian  
 3/5/18.  
 - Part by part repair.  
 - Question Made Item  
 Photo -  
 - Photo Before Paint.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU403577708

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 936.00	0.00
Total Material Charges	: 5,729.84	5,729.84
Other Charges	: 580.00	0.00
<b>TOTAL</b>	<b>: 7,921.84</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 5.00	<i>0.00</i>
Prepared / Adjusted By	:	<i>3 days</i>
Arc / Surveyor Sign Off Date	: 02/05/2018 01:47:30 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/05/2018 01:47:30 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : Prepared Date :

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	676.00	<del>0.00</del> 400
<b>Total Labour</b>	<b>676.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	<del>0.00</del> 200
TO RESPRAY FRONT FENDER RH	378.00	<del>0.00</del> 200
TO RESPRAY RIM	180.00	0.00 50
<b>Total Spray Painting &amp; Panel Beating</b>	<b>936.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	<del>0.00</del> 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	<del>0.00</del>
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	<del>0.00</del> 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	<del>0.00</del> 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>580.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119479 62			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	✓ No CRK
81210470 20			LAMP ASSY, FOG, RH	1	910.20	10.00	819.18	Replace	Replace	✓ No CRK
53112472 40			GRILLE, RADIATOR	1	165.00	25.00	123.75	Replace	Replace	? No
53801470 80			FENDER SUB-ASSY, FR, RH	1	933.10	25.00	699.82	Replace	Replace	R No
75374471 40			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	✓ No NREC
53875470 70			LINER, FR FENDER, RH	1	198.40	25.00	148.80	Replace	Replace	X No
42611- 47450			WHEEL, DISC FRONT	1	1,555.10	25.00	1,166.32	Replace	Replace	R No
52115470 50			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.67	Replace	Replace	? No
81145476 91			UNIT, HEADLAMP, RH	1	2,558.90	10.00	2,303.01	Replace	Replace	? No
<b>TOTAL MATERIALS</b>								<b>5,729.87</b>	<b>5,729.84</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>5,729.84</b>	<b>5,729.84</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									