

Trans-cab Auto Services Pte Ltd

No: 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHB 9869X

AAD1805-016

*Not Authorised
 L1 Sing @*

Vehicle No.:	SHB 9869X
Chassis No.:	VF1ABL15AUC273126
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	30.4.2018
Third Party Insurer :	AlG

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 <u> </u>
2	1 BUMPER LOWER REAR	\$	<i>Du</i> 768.84 <u> </u>
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 <u> </u>
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95
13	1 BOOT REAR	\$	<i>N</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>un</i> 225.36
19	1 BOOT BADGE	\$	<i>un</i> 225.36
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
22	1 BOOT HINGE LH	\$	<i>N</i> 367.84
23	1 BOOT HINGE RH	\$	<i>N</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13
26	1 BOOT LOCK	\$	<i>N</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>N</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81

X

Trans-cab Auto Services Pte Ltd

AAD1805-016

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9869X

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	}
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	
32	1 FENDER PANEL REAR LH	\$	R	3,299.13	
33	1 WHEELARCH REAR LH	\$	Sn	543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
35	1 FENDER PANEL REAR RH	\$	R	3,299.13	
36	1 WHEELARCH REAR RH	\$	Sn	543.47	
37	1 TAILLAMP RH	\$	Sn	552.55	
38	1 TAILLAMP PANEL RH	\$	R	986.70	
39	1 TAILLAMP LH	\$	Sn	552.55	
40	1 TAILLAMP PANEL LH	\$	R	986.70	
41	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
44	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	
45	1 EXHAUST REAR	\$	R	7,489.05	
46	1 EXHAUST CAP REAR	\$	R	230.49	
47	1 FUEL FLAP L70Y	\$	Sn	343.57	
TOTAL		\$		39,057.17	
10%		\$		3,905.72	
		\$		35,151.45	

Special Nett

1	1SET PARKING AID	\$	Sn	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMERPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMERPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMERPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	X
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	X
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X

Trans-cab Auto Services Pte Ltd

AAD1805-016

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9869X

16 1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00	}
17 1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00	
18 1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00	
19 1 TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	
20 1 TAILLAMP CLIP LH	\$	<i>nn</i>	5.00	
21 2 REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00	
22 1 WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sm</i>	385.00	
25 1 SPARE TYRE	\$	<i>Sm</i>	330.00	
TOTAL		\$	2,225.02	
TOTAL PARTS		\$	37,376.47	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	<i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		4,200.00	<i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i>	170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i>	170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1805-016

No: 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9869X

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>170</i>	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>4</i>	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>4</i>	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>4</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>4</i>	220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>4</i>	380.00	X

TOTAL \$ 11,040.00

Over All Total \$ 48,416.47

(LUMP SUM)

Repair Days

15 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: