

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

1716

Name : Sri Haryani Binte Samad

Accident Date : 27-Apr-18

Vehicle No : FT 7859 S

Vehicle Model : Honda NSR150

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Top cowling / Dis	\$ 165.00
1	Windshield / Dis	\$ 75.00
1	Headlamp / Dis	\$ 165.00
1	Front fender / Cut	\$ 68.00
2	Fork inner tubes / BT	\$ 420.00
2	Fork outer tubes / BT	\$ 430.00
1	Fork under bracket /	\$ 175.00
1	Front brake disc X	\$ 155.00
1	Front sport rim / Cut	\$ 280.00
1	Front rim shaft / Cut	\$ 38.00
2	Side mirrors / Cut	\$ 70.00
2	Handle bars / BT	\$ 210.00
1	Hand grip (1 set) / Cut	\$ 80.00
1	Clutch lever / Cut	\$ 15.00
1	Brake lever / Cut	\$ 18.00
2	Front signals / Dis.	\$ 84.00
2	Centre fairings / Dis	\$ 170.00
2	Lower fairings / Dis	\$ 230.00
2	Air intake tubes / RL	\$ 76.00
1	Centre inner fairing / Dis.	\$ 75.00
1	Meter / CAA	\$ 380.00
1	Radiator X	\$ 210.00
1	Lamp stay X	\$ 75.00
1	Front footrest -R/H / BT	\$ 40.00
1	Front footrest bracket / BT	\$ 65.00
1	Brake pedal / BT	\$ 36.00
1	Horn X	\$ 48.00
1	Rear footrest -R/H / Cut	\$ 40.00
1	Exhaust pipe / Cut	\$ 380.00
1	Rear tailboard -R/H X / CAA	\$ 125.00
1	Rear taillamp X	\$ 75.00
1	Rear centre cowling X	\$ 28.00
2	Rear signals / LH - CAA	\$ 84.00
1	Rear seat / TV Rnd X NN	\$ 95.00
		\$ 4,680.00
	Less 10%	\$ 468.00
		\$ 4,212.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Sri Haryani Binte Samad

Accident Date : 27-Apr-18

Vehicle No : FT 7859 S

Vehicle Model : Honda NSR150

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set) ✓	\$	28.00
2	Fork oils ✓	\$	30.00 ✓
2	Fork oil seals ✓	\$	56.00 ✓
1	Steering cone (1 set) ✓	\$	75.00 ✓
1	ERP IU ✓	\$	170.00
1	Coolant ✗	\$	15.00
1	Front tyre ✗	\$	120.00
		\$	494.00

S/No. Labour

1	To provide towing service.	\$	45.00 40
2	To check wiring and reset headlamp focusing.	\$	80.00 ✗
3	To provide labour.	\$	380.00 250
		\$	505.00

Guo Qiang - 82880782
lumpsum repair
After repair photos
07/5/18
SDans

LKK Auto Consultants hence notify
the repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Grand Total

\$ 5,211.00

Dollars: Five Thousand Two Hundred And Eleven Dollars Only.

EROFIA MOTOR TRADING PTE LTD