

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0530/2018/GW
Date	:	5-May-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no : SGG 9899 U

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ooi Soo Kar
Address	:	89 Thomson Green Singapore 574956
Telephone	:	(HP) 98288779
Type of Claim	:	Own damage claims
Policy No.	:	2100468895-01000
Vehicle No	:	SGG 9899 U
Model Code	:	Audi A3 Sedan 1.4 TFSI
Model / Year	:	May-18
Engine No	:	CZC 519113
Chassis No	:	WAUZZZ8v0G1074327
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	30-Apr-18
Place of Accident	:	Filter lane between AMK Ave 2 and AMK Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGG 9899 U.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid . Check function.	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper assy. Inspect rhs rear fender for damage. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00	SSO
3	To respray rear bumper.	\$ 800.00	SSO
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGG 9899 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>deformed</i>	\$ 1,619.00	✓
2	REAR BUMPER FIXING PARTS	\$ 166.00	+
3	REAR BUMPER GUIDE SECTION-LH/RH <i>given</i>	2 \$ 28.00	+
4	REAR BUMPER LOCKING MECHANISM ?	2 \$ 50.00	?
5	REAR LIGHT REFELCTOR-LH/RH <i>new</i>	2 \$ 52.00	+
6	REAR SENSOR INNER/OUTER <i>outer damaged</i>	2 \$ 421.00 210.50	
7	REAR BUMPER SENSOR SEAL RING ?	4 \$ 14.00	?
8	REAR BUMPER SIDE REINFORCEMENT ?	\$ 501.00	?
9	REAR BUMPER BRACKET-LH/RH <i>new</i>	2 \$ 22.00	+
10	REAR BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 114.00	+
11	LED TAIL LIGHT-RH <i>lit</i>	\$ 946.00	✓
12	TAIL LIGHT TRIM-RH <i>new</i>	\$ 26.00	+
13	VENT TRIM <i>new</i>	\$ 60.00	+
15	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 4,419.00	
TOTAL LABOUR CHARGES		: \$ 2,172.00	
GRAND TOTAL		: \$ 6,591.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 07/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OB pays.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant