

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0546/2018/PH
Date : 10-May-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : **SKH 2521 C**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Gelene Ong Siew Moi
Address : 186 Depot Road
: #09-13
Singapore 109687
Telephone : HP +65 90110080
Type of Claim : Third Party Claim
Policy No. : 2100508891
Vehicle No : **SLD 6742 P**
Model Code : Audi A8 2.0 TFSI QU
Model / Year : Jun-16
Engine No : CNC 142851
Chassis No : WAUZZZ8R6GA059432
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-May-18
Place of Accident : Brownstone Condo Multi-storey carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLD 6742 P.

S/N	Nature of Jobs	Estimated Charges
1	To remove & transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid .	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper assy . Re-organise front crash management components. Reinstall all parts removed.	\$ 1,050.00 500
3	To respray front bumper and lower spoiler	\$ 1,500.00 900
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u><u>3,222.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 6742 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER <i>Rejis</i>	\$ 2,237.00	<i>x</i> .
2	FRONT AIR GUIDE GRILLE -RH <i>cont'd</i>	\$ 307.00	<i>✓</i>
3	FRONT BUMPER SPOILER <i>Rejis</i>	\$ 540.00	<i>x</i> .
4	CLOSING ELEMENT <i>Re a</i>	\$ 180.00	<i>x</i>
5	FRONT BUMPER SECURING STRIP - RH <i>Re a</i>	\$ 32.00	<i>x</i>
6	FRONT BUMPER GUIDE SECTION - RH <i>Re a</i>	\$ 32.00	<i>x</i> .
7	SUNDRIES	\$ 200.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 3,528.00
TOTAL LABOUR CHARGES		:	\$ 3,222.00
GRAND TOTAL		:	\$ 6,750.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 10/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant