

Not withash
1-B1
Resurvey by pain



ESTIMATE TO REPAIR

VEHICLE NO. : SLV 6571 X
MAKE : HONDA
MODEL : SJUTTLE 1.5G CVT
YEAR : 2017
CHASSIS NO : GK81200133

SURVEYOR NAME	:
DATE OF SURVEY	: 08 MAY 2018
TIME OF SURVEY	:

DATE : 7-May-18
DATE OF ACCIDENT : 2-May-18
THIRD PARTY REF : SKV 9199 E / FWD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			Bu	\$ 1,150.60
2 pcs	Rear Bumper Retainer		\$ 26.50	Sm	\$ 53.00
1 pc	Rear End Panel			R	\$ 560.85
1 pc	Tailgate			M	\$ 1,193.00
1 pc	Tailgate Centre Emblem			m	\$ 38.00
1 pc	Tailgate Shuttle Emblem			m	\$ 55.00
					\$ 3,050.45
	Less 20%				\$ 610.09
					\$ 2,440.36
1 set	Rear Bumper Sensor	S.Nett		m	\$ 200.00
1 tube	Rear Windscreen Sealant	S.Nett		m	\$ 40.00
1 pc	Rear Windscreen Moulding	S.Nett		m	\$ 120.00
	To putty & spray painting.			609	\$ 700.00
	To transfer tailgate fittings.			601	\$ 80.00
	To remove and refix rear windscreen glass.				\$ 120.00
	To anti-rust.				\$ 50.00
	Labour Charges.			509	\$ 600.00
TG-RA/-	TOTAL				\$ 4,350.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520893 Fax: 65-64589127

Website: www.LTM.sg

Co.Reg No. 199307277D

GST Reg No. M2-0019086-0