

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G8D1498X Yr Regn: 2014 JulyType: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Hiace cc 2982Colour: White A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 83677 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: JTFHT02P300141282Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 195/80R15R: 195/80R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 01/05/18Survey held at ModernDes. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

1/6/18 Confirm LIS \$ 7100.00 with 9 working days

MV: 50K

PV: 16.3K

Net: 33.7K

(2nd = #6704-86
49.1)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

____ \$ + RS ____ \$

Photos _____

Others _____

TOTAL: _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18008337/Awb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 07-05-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-----------|----------------|------------|
| Insured Veh. | SKZ 2219G | Veh. Inspected | GBD 1498X |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 07/05/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| | |
|--|--|
| | |
|--|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 03/05/2018 | Inspection Date | 07/05/2018 |
| Survey held at | MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Quotation

DATE : 07.05.2018
VEH NO : GBD1498X
MODEL : Toyota Hiace
D O A : 03.05.2018
YR REF : SKZ2219G

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBD1498X (Toyota Hiace)

| Item | Description | Qty | Amt |
|-----------|--|-------|----------------------------|
| NO | LIST ITEMS | | |
| 1 | Rear Bumper <i>Distorted</i> | 1 | 465.10 ✓ |
| 2 | Rear Bumper Clips <i>new</i> | 1 set | 30.00 ✓ |
| 3 | Rear Bumper Side Holder - LH & RH <i>new</i> | 2 | 130.20 ✓ |
| 4 | Rear Bumper Lower Bracket <i>Best</i> | 4 | 140.40 ✓ |
| 5 | Rear End Panel Outer <i>Dented</i> | 1 | 581.80 ✓ |
| 6 | Rear End Panel Inner <i>Dented</i> | 1 | 591.30 ✓ |
| 7 | Rear End Panel Top Metal Strip <i>Best</i> | 1 | 299.50 ✓ |
| 8 | Taillamp - LH & RH <i>LH Cut</i> | 2 | 704.80 352.30 |
| 9 | Taillamp Panel - LH & RH <i>LH Dented</i> | 2 | 1,462.20 561.10 |
| 10 | Taillamp Lower Apron - LH & RH <i>LH Del</i> | 2 | 122.20 86.10 |
| 11 | Tailgate <i>Distorted</i> | 1 | 1,755.30 ✓ |
| 12 | Tailgate Lock <i>Del</i> | 1 | 281.30 ✓ |
| 13 | Tailgate Weatherstripe <i>Del</i> | 1 | 387.30 ✓ |
| 14 | Tailgate Inner Trim Board <i>Del</i> | 1 | 196.50 ✓ |
| 15 | Tailgate Inner Trim Board Clips <i>new</i> | 1 set | 30.00 ✓ |
| 16 | Tailgate Outer Garnish <i>new</i> | 1 | 281.10 ✓ |
| 17 | Tailgate Glass Moulding <i>new</i> | 1 | 172.50 ✓ |
| 18 | Toyota Logo <i>new</i> | 1 | 70.50 ✓ |
| 19 | Toyota Hiace Sticker <i>new</i> | 1 | 40.00 ✓ |
| 20 | Rear Body Panel - LH <i>Repair</i> | 1 | 1,712.85 X |
| 21 | Rear Body Panel Air Vent - LH <i>Del</i> | 1 | 48.50 ✓ |
| 22 | Floor Panel <i>Repair</i> | 1 | 1,972.50 X |
| 23 | Spare Tyre Carrier <i>Best</i> | 1 | 263.50 ✓ |
| | | | 11,489.15 |
| | | | (2,872.29) |
| | | | \$ 8,616.86 |
| | | | 6503.20 Less 25% |
| | | | 4877.40 |

RE : ESTIMATE FOR ACCIDENT REPAIR GBD1498X (Toyota Hiace)

S/NET ITEMS

| | | | |
|---|---|---|-------------------------|
| 1 | Rear Number Plate <i>Best</i> | 1 | 3.00 ✓ |
| 2 | Rear End Panel Sealant <i>in</i> | 1 | 60.00 ✓ |
| 3 | Reverse Sensor <i>Best</i> | 1 | 280.00 200 ✓ |
| 4 | Tailgate Glass Sealant <i>in</i> | 1 | 60.00 ✓ |
| 5 | 70km/h Sticker <i>in</i> | 1 | 15.00 ✓ |
| 6 | Rear Body Panel Stickers - LH <i>in</i> | 1 | 280.00 180 ✓ |

Total Parts \$ 9,314.86

LABOUR CHARGE

| | | | |
|---|---|----|----------------------------|
| 1 | To knocking & pull out rear portion & renew above parts | \$ | 1,800.00 1500 ✓ |
| 2 | To putty & spray up paint works | \$ | 1,600.00 1400 ✓ |
| 3 | To check wiring | \$ | 50.00 30 ✓ |
| 4 | To underseal | \$ | 180.00 80 ✓ |
| 5 | To remove upholstery | \$ | 150.00 50 ✓ |
| 6 | To remove reverse sensor | \$ | 100.00 50 ✓ |
| 7 | To remove tailgate glass | \$ | 180.00 120 ✓ |
| 8 | To transfer tailgate fittings | \$ | 150.00 80 ✓ |
| 9 | To remove rear furniture | \$ | 280.00 150 ✓ |

Total Labour \$ 4,490.00

Grand Total \$ 13,804.86

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 8882.40
L/S: 7.1K
09 Days

View Received Message

This mail is associated with :

***GBD1498X (4918799951SG)
[5KZ2219G]**

TP

SERANGOON CATHOLIC CHURCH ST JOSEPH DYING AID ASSO

May 3 2018 8:00PM

[SEET ZHENG YEUNG]

Modern Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 07/06/2018 08:56 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8250.00) - GBD1498X - Claim Handler: Syed-Yusoff, Saliha

Approved:8250.00:LOU to offer at \$70 X 9 days

DOCUMENTS SUMMARY

There are no documents.

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6745-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SKZ2219G

Our Ref : GBD1498X

Date : 04.06.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING GBD1498X & SKZ2219G ON 03.05.2018

AT SLIP RD OF UPPER SERAGOON RD & HOUGANG AVE 8


We refer to the above matter.

We have been authorized by our client M/s Serangoon Catholic Church St Joseph Dying Aid Association to make claim against your insured vehicle No. SKZ2219G in respect of the above accident for the following :

| | |
|-------------------------------|------------------------------------|
| Repair Cost | \$ 7,597.00 (Incl GST) |
| Loss of use (\$120 x 10 days) | \$ 1,200.00 (9 Repair days, 1 Sun) |
| Search fee | \$ 2.00 |
| Total : | \$ 8,799.00 |

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully


Modern Automotive Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18008337/Awb3

24 May 2018

Wee Jiok Lin

3 Paya Lebar Crescent

#04-21

Singapore 534239

Dear Sir/Madam,

ACCIDENT INVOLVING SKZ 2219G AND GBD 1498X ON 03/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORIZATION

Date:4/5/18.....

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

.....G8D1498 X & SKZ2219 G.....

ON3/5/18.....ALONG.....Slip Rd of Upp Serangoon.....

.....Rd & Hougang Ave 8.....

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully 后港天主堂聖若瑟助終社

Serangoon Catholic Church

ST. JOSEPH DYING AID ASSOCIATION

CHURCH OF THE NATIVITY OF THE BVM

1250, UPPER SERANGOON ROAD

SINGAPORE 534795

TEL: 6280 3163 FAX: 6288 0191

Signature of Owner

.....
Name / NRIC

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, MODERN AUTOMOTIVE PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 7597.00 (repair cost), S\$ 630.00 (loss of rental/use), S\$ 2.00 (disbursement), for vehicle no. GBD 1498X that was damaged pursuant to the accident which occurred on 03/05/2018 (date) along HOUGANG AVE 8 (location) involving vehicle no/s SKZ 2219G.

This is pursuant to the inspection conducted on 07/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SERANGOON CATHOLIC CHURCH ST JOSEPH DYING AID ASSO (the third party claimant") of vehicle no. GBD 1498X make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBD 1498X (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 08 (day) of Oct (month) 2018 (year)

Lwf.


Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 #01-58/61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department
Contact : 6415-3727 6419-3000

Tax Invoice : TP001207

Date : 01/06/2018
Vehicle Num. : GBD 1498X
Make/Model : TOYOTA HIACE
Chassis/Eng# :
Accident Date : 03/05/2018
Claim No. :
Reference :
Policy No. : AVCPSB0072491703

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|---------------------------|------------|------------|
| | | LABOUR : | | |
| | | ACCIDENT REPAIR (LUMPSUM) | | 7,100.00 |
| | | Labour Total S\$: | | 7,100.00 |

| | |
|------------------|----------|
| Total S\$: | 7,100.00 |
| GST @ 7% S\$: | 497.00 |
| Amount Due S\$: | 7,597.00 |


MODERN AUTOMOTIVE PTE LTD



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-067282
Date of Request: 04/05/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date: 04/05/2018
Enquiry By: Chin Soi Shong
TP Vehicle No.: SKZ2219G
Accident Date: 03/05/2018

Enquiry Result

| TP Vehicle No. | Insurer | Period of Insurance | Insurer Tel. No. |
|----------------|--------------------------------------|-----------------------|------------------|
| SKZ2219G | AIG Asia Pacific Insurance Pte. Ltd. | 14/01/2018-13/01/2019 | 65-6419-3000 |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-067282
Date of Request: 04/05/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-68
Singapore 408717

Dear Sir/Madam,

Enquiry Date 04/05/2018
Enquiry By Chin Soi Shong
TP Vehicle No. SKZ2219G
Accident Date 03/05/2018

| DESCRIPTION | AMOUNT (S\$) |
|----------------------------------|--------------|
| TP Insurer Enquiry | 1.87 |
| GST Amount | 0.13 |
| Total Amount Due (GST Inclusive) | 2.00 |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 08 May 2018 Edit Reg | | 07 May 2018 00:00 Edit Adj Rpt | \$57,100.00 Edit Estimates | \$57,100.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

CLAIM SUBFOLDER DETAILS [Created by adjuster]

| | | | |
|-----------------------------|---|------------------------|--|
| Insured: | WEE JIOK LIN , ID: S1098354A | | |
| Main Claimant: | SERANGOON CATHOLIC CHURCH ST JOSEPH DYING AID ASSO , Co. Reg. No.: - | | |
| Vehicle Reg. No.: | GBD1498X | Date of Loss: | 03/05/2018 20:00 - :59 [45 Months and 26 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 4918799951SG | Policy/Cover Note No.: | 2100498390 (Comprehensive) Coverage: 14/01/2018 - 13/01/2019 |
| Vehicle Reg. No. (Insured): | SKZ2219G | Policy No. (Claimant): | AVCPB0072491703 |
| | | Excess: | |
| Repairer: | Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422 | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com | | |
| Claimant's Insurer: | Allied World Assurance Company, Ltd (HQ) - Tel: 62201188 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 16/05/2018] | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (07/06/2018): Alert - Adj Mandate Approved (\$8250.00) - GBD1498X - Claim Handler: Syed-Yusoff...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

*GBD1498X (4918799951SG)

[SKZ2219G]

TP

SERANGOON CATHOLIC CHURCH ST JOSEPH DYING AID ASSO

May 3 2018 8:00PM


















































[WEE JIOK LIN]



















Modern Automotive Pte Ltd

| | | | | | | | |
|----------------------------------|--|-------------------------------|------------------------------------|------------------------------|------------------------------|---|--|
| Upload Documents | | Upload Photos | Compose New Letter | Upload Video | Upload Audio | View View in Browser | |
|----------------------------------|--|-------------------------------|------------------------------------|------------------------------|------------------------------|---|--|

| Letters/Correspondences | | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|--------------|--|---|------------|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | (Draft) | Third Party Express Settlement – Payment Breakdown | 1 | Edit | |

| Photos/Images | | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|---|------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 29 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 31 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 32 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 33 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 34 | 22/05/18 09:22 | General View | 1 | Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| | | | | <input checked="" type="checkbox"/> |
| 35 | 22/05/18 09:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 22/05/18 09:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 22/05/18 09:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 22/05/18 09:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 22/05/18 09:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 22/05/18 09:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 22/05/18 09:22 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|---|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 84 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 22/05/18 09:23 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 07/05/18 19:22 | TP GIA REPORT |  Load PDF | |
| 2 | 05/06/18 15:53 | LETTER TO OI |  Load PDF | |
| 3 | 05/06/18 15:53 | GIA SEARCH |  Load PDF | |
| 4 | 06/06/18 16:58 | Email to AIG to seek mandate GBD 1498X |  Load PDF | |
| 5 | 10/10/18 10:21 | WORKSHOP INVOICE |  Load PDF | |
| 6 | 10/10/18 10:21 | Release Voucher |  Load PDF | |
| 7 | 10/10/18 10:21 | AUTHORISATION TO ACT FORM |  Load PDF | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 08/05/18 13:02 | OI GIA REPORT |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

| | | | |
|-------------------|---------------------|--------|----------------------|
| Vehicle No: | SKZ2219G (Insd veh) | Model: | TOYOTA HIACE 2.0 (M) |
| | GBD1498X (TP veh) | | |
| Date of Accident: | 03/05/2018 | | |

| | | | |
|-----------------------|---|------------------------------|--|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Repair Estimate | : | \$ | 14,771.20 |
| Final Repair Cost | : | \$ | 7,597.00 |
| Loss of Use | : | \$ | 630.00 |
| Rental (if any) | : | \$ | 0.00 |
| LTA / GIA Search Fee | : | \$ | 2.00 |
| Others: | : | \$ | 0.00 |
| | : | \$ | |
| Final Settlement Sum | : | \$ | 8,229.00 |

9.00 days at \$70.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

| Payment Instruction: Payee's Breakdown | | | |
|--|---------------------------|---|-------------|
| 1) | Modern Automotive Pte Ltd | : | \$ 8,229.00 |
| 2) | | : | \$ |
| 3) | | : | \$ |

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

10 Oct
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18008337/AWB3Q2

Date: 10/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100498390

Claimant Vehicle No: GBD1498X

Insured Vehicle No: SKZ2219G

Date of Loss: 03/05/2018

Nature of Claim: TP

Claim No: 4918799951SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD1498X

Make & Model: TOYOTA HIACE, 2.0 (M)

Engine No: 1KD2405324

Reg. Date: 07/07/2014 (Man. Year: 2014)

Chassis No: JTFHT02P300141222

Colour: White

Odometer: 83677 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15

Rear Tyre Size: 195/80 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|-----------------|-----------------|--------------|
| Parts | 9,314.86 | 5,395.40 | 3,919.46 | 42.08 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,490.00 | 3,460.00 | 1,030.00 | 22.94 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 13,804.86 | 8,855.40 | 4,949.46 | 35.85 |
| Approved Total (Overridden) (S\$) | | 7,100.00 | | |
| (S\$) | 13,804.86 | 7,100.00 | 6,704.86 | 48.57 |
| + GST 7.00/7.00% (S\$) | 966.34 | 497.00 | 469.34 | 48.57 |
| Nett Amount (S\$) | 14,771.20 | 7,597.00 | 7,174.20 | 48.57 |
| + Loss of Use (9.0 x S\$70.00/day) (S\$) | | 630.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 8,229.00 | | |

INSPECTION

Date of Assignment: 07/05/2018

Date Inspected: 07/05/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Distorted | 465.10 FL | *465.10 FL |
| 2 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 30.00 FL | *30.00 FL |
| 3 | 2 | | *REAR BUMPER SIDE HOLDER -LH & RH | Necessary | 130.20 FL | *130.20 FL |
| 4 | 4 | | *REAR BUMPER LOWER BRACKET | Bent | 140.40 FL | *140.40 FL |
| 5 | 1 | | *REAR END PANEL OUTER | Dented | 581.80 FL | *581.80 FL |
| 6 | 1 | | *REAR END PANEL INNER | Dented | 591.30 FL | *591.30 FL |
| 7 | 1 | | *REAR END PANEL TOP METAL STRIP | Bent | 299.50 FL | *299.50 FL |
| 8 | 1 | | *TAILLAMP -LH & RH | N/S Crumpled | 704.60 FL | *352.30 FL |
| 9 | 1 | | *TAILLAMP PANEL -LH & RH | N/S Dented | 1,162.20 FL | *581.10 FL |
| 10 | 1 | | *TAILLAMP LOWER APRON -LH & RH | N/S Deformed | 172.20 FL | *86.10 FL |
| 11 | 1 | | *TAILGATE | Distorted | 1,755.30 FL | *1,755.30 FL |
| 12 | 1 | | *TAILGATE LOCK | Damaged | 281.30 FL | *281.30 FL |
| 13 | 1 | | *TAILGATE WEATHERSTRIPE | Cut | 387.30 FL | *387.30 FL |
| 14 | 1 | | *TAILGATE INNER TRIM BOARD | Deformed | 196.50 FL | *196.50 FL |
| 15 | 1 | | *SET TAILGATE INNER TRIM BOARD CLIPS | Necessary | 30.00 FL | *30.00 FL |
| 16 | 1 | | *TAILGATE OUTER GARNISH | Not Necessary | 281.10 FL | *- FL |
| 17 | 1 | | *TAILGATE GLASS MOULDING | Necessary | 172.50 FL | *172.50 FL |
| 18 | 1 | | *TOYOTA LOGO | Necessary | 70.50 FL | *70.50 FL |
| 19 | 1 | | *TOYOTA HIACE STICKER | Necessary | 40.00 FL | *40.00 FL |
| 20 | 1 | | *REAR BODY PANEL -LH | Repair | 1,712.85 FL | *- FL |
| 21 | 1 | | *REAR BODY PANEL AIR VENT -LH | Deformed | 48.50 FL | *48.50 FL |
| 22 | 1 | | *FLOOR PANEL | Repair | 1,972.50 FL | *- FL |
| 23 | 1 | | *SPARE TYRE CARRIER | Bent | 263.50 FL | *263.50 FL |
| 24 | 1 | | *REAR NUMBER PLATE | Bent | 3.00 FS | *3.00 FS |
| 25 | 1 | | *REAR END PANEL SEALANT | Necessary | 60.00 FS | *60.00 FS |
| 26 | 1 | | *REVERSE SENSOR | Damaged | 280.00 FS | *200.00 FS |
| 27 | 1 | | *TAILGATE GLASS SEALANT | Necessary | 60.00 FS | *60.00 FS |
| 28 | 1 | | *70KM/H STICKER | Necessary | 15.00 FS | *15.00 FS |
| 29 | 1 | | *REAR BODY PANEL STICKER -LH | Necessary | 280.00 FS | *180.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 12,187.15 | 7,021.20 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 2,872.29 | 1,625.80 |
| Total Parts (\$\$) | 9,314.86 | 5,395.40 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS | New | 1,800.00 | 1,500.00 |
| 2 | TO PUTTY & SPRAY UP PAINT WORKS | New | 1,600.00 | 1,400.00 |
| 3 | TO CHECK WIRING | New | 50.00 | 30.00 |
| 4 | TO UNDERSEAL | New | 180.00 | 80.00 |
| 5 | TO REMOVE UPHOLSTERY | New | 150.00 | 50.00 |
| 6 | TO REMOVE REVERSE SENSOR | New | 100.00 | 50.00 |
| 7 | TO REMOVE TAILGATE GLASS | New | 180.00 | 120.00 |
| 8 | TO TRANSFER TAILGATE FITTINGS | New | 150.00 | 80.00 |
| 9 | TO REMOVE REAR FURNITURE | New | 280.00 | 150.00 |
| Gross Labour Cost (S\$) | | | 4,490.00 | 3,460.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >