

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel: 6419 - 3000
 Fax : 6835 - 7416

Quotation
 DATE : 08.05.2018
 VEH NO : GY7923B
 MODEL : Toyota Hiace
 D O A : 04.05.2018
 YR REF : GBG897T

Thin Thin

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GY7923B (Toyota Hiace)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Am't</u>
NO	LIST ITEMS		
1	Sliding Door - LH <i>Distorted</i>	1	1,462.80 ✓
2	Sliding Door Lock - LH <i>Damaged</i>	1	282.50 ✓
3	Sliding Door Outer Handle - LH <i>ut</i>	2132.3 1	163.50 ✓
4	Sliding Door Lower Roller - LH <i>Best</i>	1599.224 1	223.50 ✓
5	Sliding Door Weatherstripe - LH <i>He m</i>	1	298.00 ✓
			<hr/>
			2,430.30
Less 25%			(607.58)
			<hr/>
			\$ 1,822.73
Total Parts			<hr/>
			\$ 1,822.73

LABOUR CHARGE

1	To knocking & pull out side door & renew above parts	\$	400.00 200
2	To putty & spray up paint works	\$	400.00 250
3	To transfer door fittings	\$	150.00 80
Total Labour			<hr/>
			\$ 950.00

Grand Total

\$ 2,772.73

NOTE : -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 2129.22
L/S: 17K
03 bump