

12/03/2001

ASS. REC. BY:

REF: C/TPD18008361/Z

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Kamalish Kamte

of SPP

Date/Time: 12/2/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 4888Y

Insured:

at Workshop m/s

Tel:

of

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 27/1/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ( ) Estimate
	SLQ 4888Y - X
	Report issued to i.o. Manil on 8th May 2018 @ 9 am
	closed on 20th June 2018
	S307

① To: Celine - to open file

SAH pending R.O. from Gebiz  
Report complete

**Rohaizal (LKKAuto)**

**From:** Bryan Ang (LKKAuto)  
**Sent:** Monday, 12 February 2018 3:08 PM  
**To:** Kamaliah KAMIS (SPF); Rohaizal (LKKAuto)  
**Cc:** Jefferson GERARD (SPF); SPF-TP FAIT  
**Subject:** Re: Mechanical Inspection Report Request

Dear Kamaliah

Acknowledge your request for the mechanical inspections. Will carry out the necessary.

Dear Rohaizal

Please follow up on these new cases.

Bryan Ang  
LKK Auto Consultants Pte Ltd

Report completed but still pending for R.O. - completed on 27th Feb 18

On 12 Feb 2018, at 11:35, Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg> wrote:

Dear Sir,

May I seek your assistance to perform a detailed mechanical inspection of the vehicles below.

**Case IAFP-IB-20180131-Mechanical Inspection of vehicle SLQ4888Y (SIO Vilton Hia - FAIT)**

On 27 January 2018 at about 4.44 pm, the deceased (pedestrian) was crossing the road along Tiong Bahru Road towards Outram Road when the accused driving his motor car SLQ4888Y had collided onto his right side on the 1<sup>st</sup> lane of 2 lanes road. The deceased was conveyed to SGH by the ambulance, succumbed to his injuries and was pronounced dead in SGH on the same day.

**Case IAFP-IB-20180131-Mechanical Inspection of vehicle FBH8186G (SIO Yazid - FAIT)**

On 28 January 2018 at about 5.34 am, the deceased (motorcyclist) was believed to have lost control of his motorcycle while negotiating a left bend along Seletar West Link towards Seletar North Link. The deceased sustained serious injury and was pronounced dead at the scene.

**Case IAFP-IB-20180131-Mechanical Inspection of vehicle JSC1471 (SIO Yazid - FAIT)**

On 28 January 2018 at about 6.53 am, the deceased (motorcyclist) had lost control of his motorcycle by veering to his left and collided onto the road kerb along Ang Mo Kio Avenue 5 towards Buangkok Green. The deceased was conveyed to TTSH by the ambulance, succumbed to his injuries and was pronounced dead in TTSH on the same day.

2. These request have been approved by my management.
3. Thank you Sir.