

INSURANCE

INS. CASE OWNER:

Myx | CC 3 / III 18008382, K1ea3

LKK:

IDAC:

Surveyor:

Ank

DOI:

ASSIGNMENT

7/5/18

Date / Time:

7/5/18

Registered in Meriten:

8/1/18

Pre-assign / CCU / FTE

SHC 3785 m



Insured Vehicle No.:

SHC 3785 m

Claim No.:

MCT1805084

Name of Insured:

CPL

Policy No.:

MCM0015

Insured Tel No.:

HP:

6/5/18

Make / Model:

H. 140

Excess Sec II :SS

D.O.A.:

6/5/18

Place of Accident:

GOLDEN MILE COMPLEX TAXI STATION

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

750 504 766

OJ GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

9148765

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

SHB 8701C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premier



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

15/5

Ank

SHB 8701C - X;

SHC 3785 m - NBR/DAM 14002326/41; 0007/1/1

21.5.18

SEEK MOTORS FOR LIABILITY.

22.5.18

MOTORS APPROVE LIABILITY.

8.6.18

FILE PASS TO TYPIST TO PREPARE REPORT.

RECEIVED 08 JUN 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time: 7.5.18

Confirm with:

Confirm by: PAK

Repair Cost:

SS 150

(2 days)

Reduction:

82 %

Email

Call

FINAL SETTLEMENT

Date/Time: 10.07.18

Confirm with: GAR

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

N/A

If NO or B 28, Ass. Lia:

Repair Cost:

SS 100.00

OID REVERSED HT 79

Loss of Rental (LOR):

SS 248.25

(2.5 days)

x 99.30

Loss of Use (LOU):

SS -

(S

x days)

Loss of Income (LOI):

SS 100.00

(S 40

x 2.5 days)

LOR only ☐ LOU only ☐

LOR + LOU ☐

LOR + LO ☐

[Tick only one]

GIA/LTA Search:

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

T1

3) Survey fee:

350

Total:

SS 1,150.75

Global Sum SS:

FINAL PAYMENT

Date/Time: 23.7.18

Confirm with: GAR

Email

Call

Payee 1:

SS 1,150.75

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Surveys: Kelvin

ASSIGNMENT

Veh No: SHB 8701 C Yr Regn: 25 Mar, 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c 1.685

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading 358245 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAG 41X ME5451823

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order ~~to~~ Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / S/D A/Rim or

Tyre Size: F: 205/65R16

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO of

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. f mm L/Bal. f mm

D.O.A. 6/5/18 D.O.I. 7/5/18

Survey held at Premier

Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]☐: Prell. Report

☐: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$) S + RS SI

Report Format :

Lump Sum / I.B.I: (\$)

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

_____ S + RS, _____ SI

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC3/III18008382/K1ea3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 08-05-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3785M	Veh. Inspected	SHB 8701C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/05/2018	Inspection Date	07/05/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

7-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8701 C

1 pc	Bonnet grille	X see	\$	385.00
1 pc	Front bumper	Manual	\$	531.00
1 pc	Front bumper emblem	see	\$	44.00
1 pc	Front bumper centre grille	X see	\$	174.00
1 pc	Front bumper tow hook cover	X repair	\$	14.00
1 pc	Front bumper lip	X see	\$	52.00
1 pc	Front bumper inner sponge	X see	\$	110.00
1 pc	Front bumper reinforcement	X see	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	X see	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	X see	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	X see	\$	32.00
1 pc	o/s headlamp	X see	\$	1,028.00
1 pc	Front bumper o/s fog lamp cover	X see	\$	66.00
1 pc	Front bumper o/s protector	X see	\$	51.00
			\$	2,879.00
		Less 10%	\$	287.90
			\$	2,591.10

S/NETT

1 pc	Front no. plate with casing	see - see	\$	50.00
1 pc	Front bumper clips	see	\$	48.00
1 set	Front o/s head lamp lower clips	X see	\$	6.00
1 set	Front o/s head lamp side clips	X see	\$	3.00
	Sundry		\$	50.00
	To check for wiring and to focus head lamps		\$	80.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel, etc.		\$	200.00
	To putty and spray painting on front bumper, bonnet grille		\$	180.00
	To apply rustproofing on the repaired and replaced panels.		\$	120.00
			\$	4,148.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

16/5/18 and 4/5/18 2018

Kalish rck

7/5/18 1535h

2018 4/5 After Repair

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8701 C

1 pc	Bonnet grille	X	\$	385.00
1 pc	Front bumper	/	\$	531.00
1 pc	Front bumper emblem	/	\$	44.00
1 pc	Front bumper centre grille	X	\$	174.00
1 pc	Front bumper tow hook cover	X <i>Myel</i>	\$	14.00
1 pc	Front bumper lip	X	\$	52.00
1 pc	Front bumper inner sponge	X	\$	110.00
1 pc	Front bumper reinforcement	X	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer	@ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket	@ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket	@ \$16.00 X	\$	32.00
1 pc	o/s headlamp	X	\$	1,028.00
1 pc	Front bumper o/s fog lamp cover	X	\$	66.00
1 pc	Front bumper o/s protector	X	\$	51.00
			\$	2,879.00
			Less 10%	\$ 287.90
			\$	2,591.10

S/NETT

1 pc	Front no. plate with casing	X	\$	50.00 35
1 pc	Front bumper clips	/	\$	48.00
1 set	Front o/s head lamp lower clips	X	\$	6.00
1 set	Front o/s head lamp side clips	X	\$	3.00
Sundry			\$	50.00 +
To check for wiring and to focus head lamps			\$	80.00 +
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel, etc.			\$	200 650.00
To putty and spray painting on front bumper, bonnet grille.			\$	180 550.00
To apply rustproofing on the repaired and replaced panels.			\$	120.00 +
			\$	4,148.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kalish RKK
7/5/18 1535h
207r
45 Adh Repair photo

Claim Audit

AUDIT TRAIL					
No.	On	Audit	Remarks	By	
1	08 May 2018 14:23	Clim Veh Model Changed	(204023) KIA OPTIMA 1.7 D (A).	[A] HOW MEI KWAN	
2	08 May 2018 14:23	Clim Created	Reg No: SHB8701C, Acct Date: 2018/05/06, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Premier Automotive Services Pte Ltd (HQ)	[A] HOW MEI KWAN	
3	08 May 2018 14:23	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN	
4	08 May 2018 14:23	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/17	[A] HOW MEI KWAN	
5	08 May 2018 14:23	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN	
6	08 May 2018 14:23	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN	
7	08 May 2018 14:23	Adj Adjuster Assigned	[None] -> KALVIN ANG WEI KUN	[A] HOW MEI KWAN	
8	21 May 2018 12:48	Adj Mandate Request	Cur,Req:0.00:PODS: LIABILITY: 100% REMARK: B:NIL OID REVERSED HIT TP	[A] Asher Sng Rong Yi	
9	21 May 2018 14:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/17	[I] Priya	
10	21 May 2018 14:36	Adj Mandate Set	Approved:0.00.	[I] Priya	
11	20 Jun 2018 16:48	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN	
12	20 Jun 2018 16:48	Clim Dtl Modified	Insured Name: -> -.	[A] JOANNE LEE KHANG MIN	
13	20 Jun 2018 16:48	Clim Dtl Modified	Claimant's Name: -> -, Claimant's ID: -> -.	[A] JOANNE LEE KHANG MIN	
14	20 Jun 2018 16:48	Clim Dtl Modified	JPJ Reg. Date: -> 2013/11/25.	[A] JOANNE LEE KHANG MIN	
15	20 Jun 2018 16:48	Clim Details Notified		[A] JOANNE LEE KHANG MIN	
16	10 Jul 2018 10:37	Adj Mandate Request	Cur,Req:1150.75:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST : \$802.50 + (b) LOR : \$248.25 (2.5days x \$99.30) + LOI : \$100.00 (2.5days x \$40) Total: a+b+c = \$1,150.75 VEH MODEL: KIA OPTIMA 1685cc PLEASE REVERT WITH YOUR APPROVAL / MAN DATE / INSTR	[A] Asher Sng Rong Yi	

Date From Date To Audit Type None Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1837350	20/06/2018 16:48	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHB8701C	SHC3785M	10.70

Print Received Message

This mail is associated with :

***SHB8701C (MCT18050184)**
[SHC3785M]

TP

PREMIER TAXIS PTE LTD


May 6 2018 1:00AM

[-]

Premier Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/07/2018 10:06 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1150.75) - SHB8701C - Claim Handler: Priya

Approved:1150.75.

 PREMIER TAXIS	HIRERY RELIEF / SUPER RELIEF
VEHICLE NO.	SHB 8701C
CONTACT NO.	9450 5385
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7312008Z**



Name

**YEO KIAN LOK
(YANG JIANLU)**

杨健禄

Race

CHINESE

Date of birth

31-03-1973

Sex

M

Country of birth

SINGAPORE

410213*

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **S7312008Z**

Name

**YEO KIAN LOK
(YANG JIANLU)**

Birth Date: **31 Mar 1973**

Issue Date: **27 May 2004**



NRIC No. **S7312008Z**



Date of issue

22-03-2008

APT BLK 587A CHOA CHU KANG DRIVE #03-400
SINGAPORE 681687

NRIC No: **S7312008Z**

Date: **01/07/2011**

No: **6816768**

410213* YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(E)

PASS DATE

Class 20

MOTORCYCLES NOT EXCEEDING 250 CC

21 Jul 2011

Class 7

MOTOR CARS AND MOTOR TRACTORS THE WEIGHT OF WHICH UNLOADED DOES NOT EXCEED 2500 KILOGRAMS

25 May 2006

S7312008Z

S / No. 9000227583

NP 423A



Licence No: **S7312008Z**

Land Transport Authority

VOCATIONAL LICENCE

Licence No : **S7312008Z**

Name : **YEO KIAN LOK**

Issue Date : **24/4/2010**

Please visit www.lta.gov.sg to check the status of this vocational licence



Enquire Transaction History**Transaction History Details**

Log Date/Time:	25 Nov 2013 / 09:56:47	Receipt No.:	AACCK001-AX239-131125-000004
Asset Type:	Vehicle	Transaction Amount:	\$75,658.00
Asset ID:	SHB8701C	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131125095647990723		

Vehicle No.:	SHB8701C
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	25 Nov 2013
Original Registration Date:	25 Nov 2013
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5451893
Engine No.:	D4FDDH308752
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,721.00
Minimum PARF Benefit:	\$7,332.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	25 Nov 2013 09:56:47
COE No.:	2013112501000898H
COE Expiry Date:	24 Nov 2021
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$63,297.00
Lifespan Expiry Date:	24 Nov 2021
Owner ID Type:	Company

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: SHB8701C

Chassis Number

: KNAGM414ME5451893

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 19 Oct 2018

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I) : N/A

EXCESS (SECTION II) : S\$3,500

INSURE WITH COE : N/A

HIRE PURCHASE COMPANY : N/A

SUM INSURED : N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02
SINGAPORE 486443
TEL:65446671 FAX:62141511
CO. REG:200707743D GST REG:200707743D

Our Ref: SHB8701C/GS

WITHOUT PREJUDICE

23rd May 2018

(By Email Only)

Attn: The Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Dear Sir/Madam

ACCIDENT INVOLVING SHB8701C & SHC3785M ALONG GOLDEN MILE COMPLEX TAXI STAND ON 06.05.18

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHB8701C, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SHC3785M at the material time of the accident with the driver of our client's vehicle, Mr Yeo Kian Lok

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SHC3785M, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$ 802.50 (Incl. GST)
(2) Loss of Rental - 3Days @\$99.30per day	\$ 297.90
(3) Loss of Income – 3Days @\$100.00per day	\$ 300.00
	<u>\$ 1400.40</u>

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHB8701C
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher & Scene video

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511

CO. REG:200707743D GST REG:200707743D

Our Ref: SHB8701C/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,



Claims Department – Gary Shi

Email: gary.shi@premiertaxi.com

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client – Premier Taxis Pte Ltd


AUTHORIZATION TO ACT

I, **PREMIER TAXIS PTE LTD** (the third party claimant") of **23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443** (address), owner of **SHB 8701C** (vehicle no.) hereby authorize **PREMIER AUTOMOTIVE SERVICES PTE LTD** ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no **SHB 8701C** that was damaged pursuant to the accident which occurred on **06/05/2018** (date) along **GOLDEN MILE COMPLEX TAXI STAND – BEACH ROAD** (location) involving vehicle no/s **SHC 3785M** ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 14 (day) of Aug (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT16050184
Claimant Ref: SHB8701C/GS

We/I, PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 802.50 (repair cost), S\$ 348.25 (loss of use/rental), S\$ (search fee), vehicle no. SHB 8701C that was damaged pursuant to the accident which occurred on 06/05/2018 (date) at GOLDEN MILE COMPLEX TAXI STAND - BEACH ROAD (location) involving vehicle no. SHC 3785M (insured vehicle). This is pursuant to the inspection conducted on 07/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PREMIER TAXIS PTE LTD ("the third party claimant") of vehicle no. SHB 8701C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHB 8701C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,150.75 to PREMIER AUTOMOTIVE SERVICES PTE LTD

Dated this 14 day of August 2018

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Gary Shi

NRIC:

S8648684

Address:

23 CHANGI SOUTH AVENUE 2 #01-03

SINGAPORE 486443

Nationality:

Singaporean

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

189607198R

Address:

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

Nationality:

Occupation:



AWK

TAX INVOICEDATE 23-May-2018
PAGE 1 OF 1PREMIER TAXIS PTE LTD
23 CHANGI SOUTH AVENUE 2 #03-02
SINGAPORE 486443

ITEM	Description	QTY	U.PRICE	AMOUNT
	FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8701 C			\$ 750.00
TOTAL LUMP SUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR				\$ 750.00
GST @ 7%				\$ 52.50
GRAND TOTAL				\$ 802.50


for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



11 May 2018

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Yeo Kian Lok (Yang Jianlu) of NRIC Number S7312008Z is a registered driver of SHB8701C. Yeo Kian Lok (Yang Jianlu) is paying daily rental rate of \$99.30 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

A handwritten signature in black ink, appearing to read "Chin Bee Lian".

Chin Bee Lian (Ms)
Assistant Vice President
Taxis Administration

Prepared By: LL

PREMIER TAXIS PTE LTD
23 Changi South Avenue 2
#03-02
Singapore 486443
Telephone: +65 6214 8880 Fax: +65 6214 0330
www.premiertaxi.com
Co. Reg. No. 200304975H



REPLACEMENT VEH GIVEN YES / NO

VEH NO. _____

JOB NO. _____

CHECK IN / OUT VOUCHER

DRIVER'S NAME <u>YEO KIAN LOK</u>											
NRIC <u>S 731 20082</u>	HANDPHONE <u>94505385</u>										
TAXI REGN NO. <u>S HB 8701K</u>	MAKE / MODEL <u>KOL</u>										
DATE IN <u>070518</u> TIME IN <u>1105</u>	DATE OUT <u>090518</u> TIME OUT <u>1545</u>										
KILOMETRES IN _____ FUEL IN <table border="1"><tr><td>E</td><td>1/4</td><td>1/2</td><td>3/4</td><td>F</td></tr></table>	E	1/4	1/2	3/4	F	KILOMETRES OUT _____ FUEL OUT <table border="1"><tr><td>E</td><td>1/4</td><td>1/2</td><td>3/4</td><td>F</td></tr></table>	E	1/4	1/2	3/4	F
E	1/4	1/2	3/4	F							
E	1/4	1/2	3/4	F							

TAXI METER DOWNLOADED

YES

NO

DATE / TIME TOWED IN TO WORKSHOP

D D M M Y Y H H M M

DATE / TIME CALL TO DRIVER FOR VEHICLE COLLECTION

D D M M Y Y H H M M

I ACKNOWLEDGE AND CONFIRM THAT I HAVE EXAMINED THE ABOVE SAID VEHICLE AND THAT THE SAME IS IN GOOD CONDITION AND TO MY SATISFACTION IN EVERY RESPECT TOGETHER WITH THE ACCESSORIES / ITEMS LIST ABOVE. THIS VOUCHER IS USED IN CONJUNCTION WITH THE TERM RENTAL AGREEMENT.

CHECK IN

YEO KIAN LOK X

DRIVER'S NAME

DRIVER'S SIGNATURE / DATE / TIME

CHECKED IN BY
(PREMIER'S AUTHORISED WORKSHOP)

CHECK OUT


YEO KIAN LOK X

DRIVER'S NAME

DRIVER'S SIGNATURE / DATE / TIME

CHECKED OUT BY
(PREMIER'S AUTHORISED WORKSHOP)

INDICATE AREA OF DAMAGE HERE:



BODY MARKINGS

1 - Light Dent
2 - Serious Dent
3 - Light Scratch
4 - Serious Scratch

5 - Damaged
6 - Chip
7 - Crack
8 - Peeling

SERVICE / REPAIRS DONE	DRIVER'S REMARKS																				
<table border="0"><tr><td><input type="checkbox"/> SERVICING</td><td><input type="checkbox"/> OTHERS:</td></tr><tr><td><input type="checkbox"/> T / BELT</td><td></td></tr><tr><td><input type="checkbox"/> AIRCON SYSTEM</td><td><input checked="" type="checkbox"/> ACCIDENT: DATE / TIME of ACCIDENT:</td></tr><tr><td><input type="checkbox"/> TURBO</td><td><u>060518 0120</u></td></tr><tr><td><input type="checkbox"/> BRAKE SYSTEM</td><td></td></tr><tr><td><input type="checkbox"/> CLUTCH SYSTEM</td><td></td></tr><tr><td><input type="checkbox"/> BULB</td><td></td></tr><tr><td><input type="checkbox"/> UNDER CARRIAGE</td><td></td></tr><tr><td><input type="checkbox"/> CPF</td><td></td></tr><tr><td><input type="checkbox"/> BATTERY</td><td></td></tr></table>	<input type="checkbox"/> SERVICING	<input type="checkbox"/> OTHERS:	<input type="checkbox"/> T / BELT		<input type="checkbox"/> AIRCON SYSTEM	<input checked="" type="checkbox"/> ACCIDENT: DATE / TIME of ACCIDENT:	<input type="checkbox"/> TURBO	<u>060518 0120</u>	<input type="checkbox"/> BRAKE SYSTEM		<input type="checkbox"/> CLUTCH SYSTEM		<input type="checkbox"/> BULB		<input type="checkbox"/> UNDER CARRIAGE		<input type="checkbox"/> CPF		<input type="checkbox"/> BATTERY		<p>TP / V</p>
<input type="checkbox"/> SERVICING	<input type="checkbox"/> OTHERS:																				
<input type="checkbox"/> T / BELT																					
<input type="checkbox"/> AIRCON SYSTEM	<input checked="" type="checkbox"/> ACCIDENT: DATE / TIME of ACCIDENT:																				
<input type="checkbox"/> TURBO	<u>060518 0120</u>																				
<input type="checkbox"/> BRAKE SYSTEM																					
<input type="checkbox"/> CLUTCH SYSTEM																					
<input type="checkbox"/> BULB																					
<input type="checkbox"/> UNDER CARRIAGE																					
<input type="checkbox"/> CPF																					
<input type="checkbox"/> BATTERY																					

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 May 2018 Edit Reg		07 May 2018 00:00 Edit Adj Rpt	\$750.00 Edit Estimates	\$750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	PREMIER TAXIS PTE LTD , Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHB8701C	Date of Loss:	06/05/2018 01:00 - :59 [53 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18050184	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC3785M	Policy No. (Claimant):	5095103893						
		Excess:							
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 17/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (11/07/2018): Alert - Adj Mandate Approved (\$1150.75) - SHB8701C - Claim Handler: Priya III_SG (21/05/2018): Alert - Adj Mandate Approved (\$0.00) - SHB8701C - Claim Handler: Priya 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB8701C (MCT18050184)
[SHC3785M]
TP
PREMIER TAXIS PTE LTD
May 6 2018 1:00AM
[COMFORT TRANSPORTATION PTE LTD]
Premier Automotive Services Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	08/05/18 17:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	16/05/18 08:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
23	16/05/18 08:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
24	16/05/18 08:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
25	16/05/18 08:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/05/18 00:05	TP ESTIMATE - MARKED	1	Load PDF	
2	15/05/18 00:05	TP GIA REPORT	1	Load PDF	
3	20/06/18 16:55	WORKSHOP INVOICE	1	Load PDF	
4	20/06/18 16:55	RENTAL RECEIPT	1	Load PDF	
5	20/06/18 16:55	LOD	1	Load PDF	
6	29/08/18 10:11	AUTHORISATION TO ACT FORM	1	Load PDF	
7	29/08/18 10:11	DISCHARGE VOUCHER	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	09/05/18 09:19	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18008382/K1EA3Q2

Date: 29/08/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle
No: SHB8701C

Insured Vehicle No: SHC3785M

Date of Loss: 06/05/2018

Nature of Claim: TP

Claim No: MCT18050184

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB8701C

Make & Model: KIA OPTIMA, 1.7 D (A)

Engine No: D4FDDH308752

Reg. Date: 25/11/2013 (Man. Year: 2013)

Chassis No: KNAGM414ME5451893

Colour: Silver

Odometer: 358245 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,748.10	600.50	2,147.60	78.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	380.00	1,020.00	72.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,148.10	980.50	3,167.60	76.36
Approved Total (Overridden) (S\$)		750.00		
(S\$)	4,148.10	750.00	3,398.10	81.92
+ GST 7.00/7.00% (S\$)	290.37	52.50	237.87	81.92
Nett Amount (S\$)	4,438.47	802.50	3,635.97	81.92
+ Loss of Use (2.5 x S\$40.00/day) (S\$)		100.00		
+ Car Rental (2.5 x S\$99.30/day) (S\$)		248.25		
Nett Liability (S\$)		1,150.75		

INSPECTION

Date of Assignment: 07/05/2018

Date Inspected: 07/05/2018 Inspected At:

Premier Automotive Services Pte Ltd (HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2018)
Parts: 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB8701C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET GRILLE	Serviceable	385.00 FL	*- FL
2	1		*FRONT BUMPER	Deformed	531.00 FL	*531.00 FL
3	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
4	1		*FRONT BUMPER CENTRE GRILLE	Serviceable	174.00 FL	*- FL
5	1		*FRONT BUMPER TOW HOOK COVER	Repair	14.00 FL	*- FL
6	1		*FRONT BUMPER LIP	Serviceable	52.00 FL	*- FL
7	1		*FRONT BUMPER INNER SPONGE	Serviceable	110.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Serviceable	328.00 FL	*- FL
9	2		*FRONT BUMPER O/S & N/S SIDE RETAINER	Serviceable	32.00 FL	*- FL
10	2		*FRONT BUMPER O/S & N/S UPPER BRACKET	Serviceable	32.00 FL	*- FL
11	2		*FRONT BUMPER O/S & N/S SUPPORT BRACKET	Serviceable	32.00 FL	*- FL
12	1		*O/S HEADLAMP	Serviceable	1,028.00 FL	*- FL
13	1		*FRONT BUMPER O/S FOG LAMP COVER	Serviceable	66.00 FL	*- FL
14	1		*FRONT BUMPER O/S PROTECTOR	Serviceable	51.00 FL	*- FL
15	1		*FRONT NO.PLATE WITH CASING	Bent	50.00 FS	*35.00 FS
16	1		*FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
17	1		*SET FRONT O/S HEAD LAMP LOWER CLIPS	Not Necessary	6.00 FS	*- FS
18	1		*SET FRONT O/S HEAD LAMP SIDE CLIPS	Not Necessary	3.00 FS	*- FS
19	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	3,036.00	658.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	287.90	57.50
Total Parts (\$\$)	2,748.10	600.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FOR WIRING AND TO FOCUS HEADLAMPS	New	80.00	0.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SUPPORT PANEL ,ETC	New	650.00	200.00
3	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,BONNET GRILLE	New	550.00	180.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	0.00
Gross Labour Cost (S\$)			1,400.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >