

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

7-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8701 C

1 pc	Bonnet grille	X	\$	385.00
1 pc	Front bumper	/	\$	531.00
1 pc	Front bumper emblem	/	\$	44.00
1 pc	Front bumper centre grille	X	\$	174.00
1 pc	Front bumper tow hook cover	X <i>Myel</i>	\$	14.00
1 pc	Front bumper lip	X	\$	52.00
1 pc	Front bumper inner sponge	X	\$	110.00
1 pc	Front bumper reinforcement	X	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer	@ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket	@ \$16.00 X	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket	@ \$16.00 X	\$	32.00
1 pc	o/s headlamp	X	\$	1,028.00
1 pc	Front bumper o/s fog lamp cover	X	\$	66.00
1 pc	Front bumper o/s protector	X	\$	51.00
				\$ 2,879.00
Less 10%				\$ 287.90
				\$ 2,591.10

S/NETT

1 pc	Front no. plate with casing	X	\$	50.00 35
1 pc	Front bumper clips	/	\$	48.00
1 set	Front o/s head lamp lower clips	X	\$	6.00
1 set	Front o/s head lamp side clips	X	\$	3.00
Sundry				\$ 50.00 +
To check for wiring and to focus head lamps				\$ 80.00 +
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel, etc.				\$ 650.00 200
To putty and spray painting on front bumper, bonnet grille.				\$ 550.00 180
To apply rustproofing on the repaired and replaced panels.				\$ 120.00 +
				\$ 4,148.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kalish RKK
7/5/18 1535h
207p
45 After Repair photo