

SS REC. BY:

REF: CS/TCL18008383/Urbn2

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person): CWS Karen Tan of FCL Date/Time: 08052018 959am

Estimated Cost: Bill to:

OD / ~~TH~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 7707S Insured: SHB 6286Y

at Workshop m/s Pegasus Tel: 6858 1946

of 51 Delta Lane 10

Policy No: Claim No: D18003542 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 04052018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 08052018 1002am Person Contacted: Sharon Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 7707S - X
	SHB 6286Y - CS3/TCL16004961 / mldbr2
	Revert thru email.

Rea: 151316

SJ29873
(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Kul

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 77075

at Workshop m/s _____

of _____

Insured: SH/1362864

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$72

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: 1 Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ 77075 Yr Regn: 7 117

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Mazda 3 c.c. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 77573 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8H015-2973

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60216

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 4/5/18 D.O.I. 23/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

274 49887

23/5/18 confirmed n/s \$2100 mlt herman.

Red: \$2468.80, 541.

RECEIVED 24 MAY 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TP

Lump Sum / L.B.T: (\$ 2100)

135

50

39

224



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003542MFSH

Our Ref: CS/FCI18008383/Urb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 7707S

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.05.2018 at the premises of M/s PEGASUS ENGINEERING & TRADING PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,568.80</u>
Revised Estimate Amount	: S\$ <u>2,631.20</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at rear portion.



Yours faithfully
MARCUS
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-05-2018	Our Ref No. D18003542MFSH
Accident Date	04-05-2018	Claim Type. Third Party
Insured Vehicle	SHB6286Y	Third Party Vehicle. SLQ7707S
Survey Location	51 DEFU LANE 10	
Contact Person.	ALVIN LOW	
Contact No.	68581846/ 68581846	Fax No. 64876070
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1345N

Vehicle Details

Vehicle No.:	SLQ7707S
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 May 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520444648
Chassis No.:	JM6BN22A8H0152973
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,761.00
Original Registration Date:	21 Jul 2017
First Registration Date:	21 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$9,761.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2027
PARF Rebate Amount:	\$7,320.00

Intended COE Rebate Details

COE Expiry Date:	20 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,489.00
COE Rebate Amount:	\$37,191.00
Total Rebate Amount:	\$44,511.00

The information contained herein is correct as at 04 May 2018

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1345N
Vehicle Details	
Vehicle No.:	SLQ7707S
Vehicle to be Exported:	No
Intended De-registration Date:	23 May 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520444648
Chassis No.:	JM6BN22A8H0152973
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,761.00
Original Registration Date:	21 Jul 2017
First Registration Date:	21 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$9,761.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2027
PARF Rebate Amount:	\$7,320.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,489.00
COE Rebate Amount:	\$42,567.00
Total Rebate Amount:	\$49,887.00

The information contained herein is correct as at 23 May 2018

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216
Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax :

Quotation No : QO18/05-1049	Quotation Date : 05/05/2018	Terms : 30 DAYS
Vehicle No : SLQ7707S	Chassis No : JM6BN22A8H0152973	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: MS First Capital, TP INSURED VEHICLE NO: SHB6286Y, DOA: 04.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000	538.00
3	REAR BUMPER SIDE RETAINER	2	92.0000	184.00
4	REAR BUMPER REFLECTOR	2	51.0000	102.00
5	REAR BUMPER SIDE HOLDER	2	74.0000	148.00
6	REAR BUMPER SIDE HOLDER RIVETS	8	6.0000	48.00
7	REAR BUMPER TOW COVER	2	17.0000	34.00
8	REAR BUMPER CLIPS	10	5.0000	50.00
9	REAR END PANEL	1	506.0000	506.00
10	REAR END PANEL INNER TRIM	1	86.0000	86.00
11	REAR END PANEL INNER TRIM CLIPS	2	5.0000	10.00
12	BOOTLID WEATHERSTRIP	1	130.0000	130.00
13	LESS 20% (ITEM 1 - 12)	1	-582.2000	-582.20
14	REAR BUMPER PARKING SENSOR	1 set	450.0000	450.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	80.0000	80.00
16	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	80.0000	80.00
17	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	80.0000	80.00
18	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	120.0000	120.00
19	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	680.0000	680.00
20	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	750.0000	750.00

C/F 0.00

Page 1 of 2

7-1864
202
1491.2
2641.2

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/05-1049	Quotation Date : 05/05/2018	Terms : 30 DAYS
Vehicle No : SLQ7707S	Chassis No : JM6BN22A8H0152973	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: MS First Capital, TP INSURED VEHICLE NO: SHB6286Y, DOA: 04.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	4,568.80
GST(7.00%)	319.82
Total (SGD)	4,888.62

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18008383/Urbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6286Y	Veh. Inspected	SLQ 7707S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003542MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	08/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0152973	Colour	BLUE	
Odometer	77573	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOYO	6 mm	
L/H Front Tyre	205/60 R16	TOYO	6 mm	
R/H Rear Tyre	205/60 R16	TOYO	6 mm	
L/H Rear Tyre	205/60 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/05/2018	Inspection Date	23/05/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 7707S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	1,075.00	1,075.00
1	REAR BUMPER REINFORCEMENT	DENTED	538.00	538.00
2	REAR BUMPER SIDE RETAINER @\$92.00	NECESSARY	184.00	184.00
2	REAR BUMPER REFLECTOR @\$51.00	NOT NECESSARY	102.00	-
2	REAR BUMPER SIDE HOLDER @\$74.00	NOT NECESSARY	148.00	-
8	REAR BUMPER SIDE HOLDER RIVETS @\$6.00	NOT NECESSARY	48.00	-
2	REAR BUMPER TOW COVER @\$17.00	O/S TORN	34.00	17.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	506.00	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	86.00	-
2	REAR END PANEL INNER TRIM CLIPS @\$5.00	NOT NECESSARY	10.00	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	130.00	-
	LESS 20% DISCOUNT		-582.20	-372.80
			2,328.80	1,491.20
SPECIAL NETT ITEMS				
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	450.00	200.00
			450.00	200.00
LABOUR				
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		80.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		80.00	60.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		80.00	50.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	120.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME INCLUSIVE OF THE REPAIR OF REAR END PANEL.		680.00	300.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		750.00	500.00
			1,790.00	940.00
GRAND TOTAL			4,568.80	2,631.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS/FC118008383/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.