

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8064X

DATE 7/5/2018 11:32

MAKE :

Fauzy

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Revised</i>			\$ 578.40
	Rear Bumper Reinforcement <i>Xsu</i>			\$ 483.30
	Rear Bumper Clip <i>new</i>			\$ 22.00
	Rear Bumper Sponge <i>Xsu</i>			\$ 137.40
	Rear Bumper Under Cover <i>Xsu</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X 4 p.c</i>		\$ 38.00	\$ 76.00
	SUB TOTAL			\$ 1,482.90
	LESS 20%			\$ 296.58
	DISCOUNTED TOTAL			\$ 1,186.32
	Rear Bumper Reverse Sensor <i>shorted</i>			\$ 135.70
				\$ 135.70
	Labour Charge			
	Panel Beating			\$ 280.00 <i>200</i>
	Spray Painting Charge			\$ 200.00 <i>180</i>
	Wiring Charge			\$ 50.00 <i>X 47</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>
	TOTAL LABOUR			\$ 650.00
	ESTIMATE TOTAL			\$ 1,972.02

Nett

16/11/14
 7/5/18 1350 hr.
 2 Pys.
 4/5
 After Repair p LKK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.