



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

ERGO INSURANCE PTE LTD		Ref: CS3/EG118008389/Gz4bs2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 17-08-2018	
FIVESINGAPORE 038985		Code: EGI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	XD 9916T	Veh. Inspected	SKE 5505X
Policy No.		Coverage (\$)	0.00
Claim No.	XD 9916T	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	08/05/2018
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN GOLF	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WVWZZZ1KZCK021978	Colour	WHITE
Odometer	104588 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55ZR16	HANKOOK	6 mm
L/H Front Tyre	205/55ZR16	HANKOOK	6 mm
R/H Rear Tyre	205/55ZR16	HANKOOK	6 mm
L/H Rear Tyre	205/55ZR16	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
5. General Information			
Accident Date	02/05/2018	Inspect Date / Time	10/05/2018 (12:20 PM)
Survey held at	SOON KIANG MOTOR BLK 13 DEFU LANE 10 #01-430 SINGAPORE 539194		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000- \$6,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

Report Ref No. CS3/EG118008389/Gz4bs2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.