

ASS. REC. BY:

REF: CS/CTU8008390/K63b/L

Special Instruction:

Supervisor
Merrin

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTL

Date/Time:

08/05/2018 1:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SG6 45256

Insured:

SLD 42080

at Workshop m/s

Complete vms

Tel:

of

176 Sin Ming Dr # D3-14

Policy No:

DMPCSH3076421701

Claim No:

SNM18D02301002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05052018

CA / REV / REP. / REV 24 HRS

09/05/2018

H.O.D. Endorsement:

Date/Time:

08/05/2018 1:26pm

Person Contacted:

Litui

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SG6 45256 - (M/R/D 170)1375/K63b/L RA: 061117
	SLD 42080 - X
21/6	Litui @ 305ol email & confirm

ASSIGNMENT

From: _____ Date: 9/5

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: 866 4525 G.

at Workshop m/s: Complete VMS

of H/G SM # 03-14

Insured: _____

Policy No: _____

Clidrvs No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 219k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No


Lum Sum: 20 % 3 Val: Yes or No

5191

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: 866 4525 G. Regn: 05 06.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toy Vios cc: 1497

Colour: M. Gray A/C: _____ Insured / Std / NI / NA

Sp. Reading: 226288 Tr/Radio: Insured / Std / NI / NA

Eng/No: _____

Ci/No: NR05314Y4204185903

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45ZR16

R: _____

BS: BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal: <u>3</u> mm	R/Bal: <u>2</u> mm
L/Bal: <u>3</u> mm	L/Bal: <u>2</u> mm
D.O.A: <u>5/5/18</u>	D.O.I: <u>9/5/18</u>

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

10/5 File path to Catherine

(\$ 3,324.75 Red. 52%)

RECEIVED 21 JUN 2018

Date/Time: File Pass to? 21/06/18

1) 7/23

Date/Time: File Return to? _____

2) _____

Report Format: _____

Lump Sum / I.B.I.: 45 \$ 3,050/-

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

Site Insp: \$ _____

Interview: \$ _____

Tech. Insp: \$ _____

W/ck-up: \$ _____

TOTAL: _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 May 2018		08 May 2018 13:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	DAMIEN KOH CHWEE HUAT, ID: 57007155Z								
Main Claimant:	LIANG WEI XIANG, ID: S8022919D								
Vehicle Reg. No.:	SGG4525G	Date of Loss:	05/05/2018 19:00 - :59						
Claim Type:	TP / SNM18D02301C02	Policy/Cover Note No.:	DMPCSN3076421701 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLD4208D	Policy No. (Claimant):	5020753767-10						
		Excess:	S\$0.00						
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/05/2018]								
Driver/Custodian (Insured):	DAMIEN KOH CHWEE HUAT (48 / Male), NRIC: S7007155Z								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2919D
Vehicle Details	
Vehicle No.:	SGG4525G
Vehicle to be Exported:	No
Intended De-registration Date:	10 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1NZX425955
Chassis No.:	MR053HY4204185903
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,707.00
Original Registration Date:	11 May 2006
First Registration Date:	11 May 2006
Transfer Count:	0
Actual ARF Paid:	\$13,978.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,789.00
COE Rebate Amount:	\$13,673.00
Total Rebate Amount:	\$13,673.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 May 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2919D
Vehicle Details	
Vehicle No.:	SGG4525G
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1NZX425955
Chassis No.:	MR053HY4204185903
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,707.00
Original Registration Date:	11 May 2006
First Registration Date:	11 May 2006
Transfer Count:	0
Actual ARF Paid:	\$13,978.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,789.00
COE Rebate Amount:	\$13,162.00
Total Rebate Amount:	\$13,162.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/05/2018 12:31
Date Of Accident	05/05/2018 19:50
Exact Location Of Accident	UPP BUKIT TIMAH RD TRAFFIC LIGHT NEAR HUME PARK 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG4525G
Insured/Policyholder	
Name Of Registered Owner	LIANG WEI XIANG
NRIC No	S8022919D
Email Address	SHAWNLIANGWX@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-92396548
Alternative Phone No	OTHERS-92396548

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident.	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5020753767-10
Cover Note Number	

Driver

Name of Driver	LIANG WEI XIANG
NRIC No	S8022919D
Date Of Birth	25/07/1980
Occupation	OUTDOOR
Date Of Driving Pass	20/05/2003
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92396548
Fax Number	
Contact Number	OTHERS-92396548
Email Address	SHAWNLIANGWX@HOTMAIL.COM




Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



(A) SGG 45256 NVE.
 (B) SLD 4208 D.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

All vehs was stationary at the traffic light junction.
 Suddenly I felt an impact. Veh B had hit the rear
 of my veh. No one was injured. I am filing this report
 for insurance claims.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

LIANG WEI XIANG
 101 KITCHENER ROAD #08-01
 SINGAPORE 208511

Attention : THE OWNER
 Contact : 92396548

NOT Authorized
LI Sup @ 3050p
Resurvey After Paint
.5 days

Estimate : ES006343

Date : 07/05/2018
 Vehicle Num. : SGG4525G
 Make/Model : TOYOTA VIOS 1.5E A-2006
 Chassis/Eng# : MR053HY4204185903/1NZX425955
 Accident Date : 05/05/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BOOT LID <i>680.80</i>		741.80 ✓
2.	1	BOOT LID LOCK		131.70 X
3.	2	BOOT LID HINGES		132.60 ✓
4.	2	TAIL LAMP	66.30	603.20 ✓
5.	2	TAIL LAMP GASKET	28.00	56.00 ✓
6.	1	REAR BUMPER <i>451.90</i>		571.80 ✓
7.	2	REAR BUMPER SIDE RETAINER	57.40	114.80 ✓
8.	2	REAR BUMPER BRACKET	99.40	198.80 ✓
9.	1	BOOT LID RUBBER		117.00 ✓
10.	1	REAR END PANEL <i>595.85</i>		720.00 ✓
11.	1	REAR END PANEL TOP GARNISH		181.40 ✓
12.	1	REAR END PANEL LATCH		69.00 ✓
13.	1	REAR EXHAUST PIPE		524.80 ✓
14.	1	REAR EXHAUST CHROME		185.00 ✓
15.	1	TAIL LAMP PANEL R/H		186.30 ✓
16.	8	REAR BUMPER CLIP	6.00	48.00 ✓
List Total S\$:				4,582.20
25.00% Discount S\$:				1,145.55
				3,436.65
SPECIAL NETT ITEMS :				
1.	1	REAR NUMBER PLATE		25.00 X
2.	1	VIOS EMBLEM		54.30 ✓
3.	1	1.5 E EMBLEM		48.00 ✓
4.	1	VVTI EMBLEM		45.80 ✓
5.	1	REVERSE SENSOR		280.00 ✓
Special Nett Total S\$:				453.10

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

LIANG WEI XIANG
 101 KITCHENER ROAD #08-01
 SINGAPORE 208511

Attention : THE OWNER
 Contact : 92396548

Estimate : ES006343

Date : 07/05/2018
 Vehicle Num. : SGG4525G
 Make/Model : TOYOTA VIOS 1.5E A-2006
 Chassis/Eng# : MR053HY4204185903/1NZX425955
 Accident Date : 05/05/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
 RUST PROOFING TREATMENT
 CHANGE TAIL LAMP AND CHECK LIGHTING
 REMOVE & REINSTALL EXHAUST SILENCER BOX
 SPRAY PAINT DAMAGED AREA AFFECTED
 TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR
 CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS

	30l	
20l	100.00	
	65.00	60.
	120.00	
600l	1,100.00	
	1,100.00	600.
	<u>2,485.00</u>	

Labour Total S\$:

SingDollars : Six Thousand Three Hundred Seventy-Four & Cents Seventy-Five Only

Total S\$: 6,374.75
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 May 2018		08 May 2018 13:27 Edit Adj Rpt	S\$3,050.00 Edit Estimates	S\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DAMIEN KOH CHWEE HUAT , ID: S7007155Z								
Main Claimant:	LIANG WEI XIANG , ID: S8022919D								
Vehicle Reg. No.:	SGG4525G	Date of Loss:	05/05/2018 19:00 - :59 [143 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02301C02	Policy/Cover Note No.:	DMPCSN3076421701 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLD4208D	Policy No. (Claimant):	5020753767-10						
		Excess:	S\$0.00						
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/05/2018]								
Driver/Custodian (Insured):	DAMIEN KOH CHWEE HUAT (48 / Female), NRIC: S7007155Z								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGG4525G (SNM18D02301C02)
[SLD4208D]
TP
LIANG WEI XIANG
May 5 2018 7:00PM
[DAMIEN KOH CHWEE HUAT]
COMPLETE VMS PTE LTD

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	07/05/18 12:48	Accident Statement	 Load HTML	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
15	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
16	07/05/18 12:43	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
2	21/06/18 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
3	21/06/18 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
4	21/06/18 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
5	21/06/18 10:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
6	21/06/18 10:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
7	21/06/18 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
8	21/06/18 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
9	21/06/18 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
10	21/06/18 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>
11	21/06/18 10:33	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
12	21/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
13	21/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
14	21/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
15	21/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
16	21/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
17	21/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
18	21/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
19	21/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
20	21/06/18 10:33	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
21	21/06/18 10:33	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/05/18 13:27	PRS	Load PDF	
2	08/05/18 13:27	OI GIA REPORT	Load PDF	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	07/05/18 12:45	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 12:45	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	07/05/18 12:46	Common Statement [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	07/05/18 12:48	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	07/05/18 12:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	07/05/18 12:45	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 12:45	Sketch Plan #2	Load TIF	
3	07/05/18 12:46	Common Statement	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118008390/KSBQ2

Date: 25/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3076421701	
Claimant Vehicle No: SGG4525G	Insured Vehicle No: SLD4208D	
Date of Loss: 05/05/2018	Nature of Claim: TP	Claim No: SNM18D02301C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGG4525G	Engine No: 1NZX425955
Make & Model: TOYOTA VIOS, 1.5 (A)	Chassis No: MR053HY4204185903
Reg. Date: 11/05/2006 (Man. Year: 2006)	Odometer: 226288 km
Colour: Metallic Grey	
Engine Capacity: 1497 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/45Z R16	Rear Tyre Size:	205/45Z R16
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,889.75	2,554.86	1,334.89	34.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,485.00	1,310.00	1,175.00	47.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,374.75	3,864.86	2,509.89	39.37
Approved Total (Overridden) (S\$)		3,050.00		
	(S\$) 6,374.75	3,050.00	3,324.75	52.15
	+ GST 7.00/7.00% (S\$)	446.23	213.50	52.15
	Nett Amount (S\$)	3,263.50	3,557.48	52.15

INSPECTION

Date of Assignment:	08/05/2018	
Date Inspected:	09/05/2018 Inspected At:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex Singapore 575721
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2018)
Parts: 143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGG4525G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	741.80 FL	*680.80 FL
2	1		*BOOT LID LOCK	Repair	131.70 FL	*- FL
3	2		*BOOT LID HINGES	Repair	132.60 FL	*- FL
4	1		*TAIL LAMP	O/S Mtg Cracked	603.20 FL	*301.60 FL
5	1		*TAIL LAMP GASKET	O/S Necessary	56.00 FL	*28.00 FL
6	1		*REAR BUMPER	Buckled	571.80 FL	*451.90 FL
7	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	114.80 FL	*57.40 FL
8	2		*REAR BUMPER BRACKET	Repair	198.80 FL	*- FL
9	1		*BOOT LID RUBBER	Serviceable	117.00 FL	*- FL
10	1		*REAR END PANEL	Bent	720.00 FL	*595.85 FL
11	1		*REAR END PANEL TOP GARNISH	Serviceable	181.40 FL	*- FL
12	1		*REAR END PANEL LATCH	Bent	69.00 FL	*69.00 FL
13	1		*REAR EXHAUST PIPE	Bent	524.80 FL	*524.80 FL
14	1		*REAR EXHAUST CHROME	Missing	185.00 FL	*185.00 FL
15	1		*TAIL LAMP PANEL R/H	Repair	186.30 FL	*- FL
16	8		*REAR BUMPER CLIP	Necessary	48.00 FL	*48.00 FL
17	1		*REAR NUMBER PLATE	Serviceable	25.00 FS	*- FS
18	1		*VIOS EMBLEM	Necessary	54.30 FS	*54.30 FS
19	1		*1.5E EMBLEM	Necessary	48.00 FS	*48.00 FS
20	1		*VVTI EMBLEM	Necessary	45.80 FS	*45.80 FS
21	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,035.30	3,290.45
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,145.55	735.59
Total Parts (\$\$)	3,889.75	2,554.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING TREATMENT	New	100.00	30.00
2	CHANGE TAIL LAMP AND CHECK LIGHTING	New	65.00	20.00
3	REMOVE & REINSTALL EXHAUST SILENCER BOX	New	120.00	60.00
4	SPRAY PAINT DAMAGED AREA AFFECTED	New	1,100.00	600.00
5	TO CUT OFF REAR END PANEL ,KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	New	1,100.00	600.00
Gross Labour Cost (S\$)			2,485.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >