

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : ASHISH KAPAH
 , BLK 3 BEDOK RESERVOIR VIEW #01-02

SINGAPORE 478927

ATTN:

Your Ref No: 18/FC/T- (05)

Claim Type: Third Party

Accident Date: 05/05/2018

TP Veh Reg No: SHA8215U

Estimate No: EST0004114

Date: 13 Jun 2018

Policy No: 2100378263

Veh Reg No: SKA2368R

Make/Model: BMW 318I

Chasis No: WBAPF720X0A793995

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :SKA2368R

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
List Price			
1 FRT HEADREST	2 PC	849.60	
		849.60	
	Less 10%	84.96	764.64
Total			S\$ 764.64
GST Amount			S\$ 53.52
Total Amount Payable			S\$ 818.16

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

L- 2545.30

- 10% = 2290.77

LC = 1140

3430.77 ✓

13/06/2018