

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9550P

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

*Not Authorized
Lay Book***AAD1804-267****SHB 9550P**

KL1LA69RJB122574

CHEVROLET

EPICA 2.0

26.4.2018

AXA

PART			LIST	
1	1	Front Bumper	\$	1,202.00
2	1	Front Bumper Lower Absorber	\$	180.00
3	1	Front Bumper Reinforcement	\$	356.00
4	1	Front Bumper Retainer RH	\$	102.00
5	1	Front Bumper Retainer LH	\$	102.00
6	1	Front Bumper Lower Grille	\$	78.00
7	1	Front Bumper Lower Stiffener	\$	134.37
8	1	Front Bumper Bracket LH	\$	10.00
9	1	Front Bumper Bracket RH	\$	10.00
10	1	Bumper Fog Lamp Cover RH	\$	32.40
11	1	Bumper Fog Lamp Cover LH	\$	32.40
12	1	Headlamp LH	\$	816.00
13	1	Headlamp LH inner panel	\$	611.16
14	1	Front Fender LH	\$	837.60
15	1	Front Fender Liner LH	\$	47.00
16	1	Front Fender Inner Wheel House Panel LH	\$	1,437.00
17	1	Front Shock Absorber Assy LH	\$	216.17
18	1	Front Shock Absorber Top Mounting LH	\$	48.32
19	1	Front Lower Arm LH	\$	283.00
20	1	Front Knuckle Arm LH	\$	230.00
21		Front Hub Unit	\$	376.00
22	1	Front Disc Brake LH	\$	157.55
23	1	Front Strut Bar Bracket LH	\$	235.01
24	1	Front Stabilizer Bar	\$	234.00
25	1	Front Stabilizer Bar Link LH	\$	51.79
26	1	Front Stabilizer Bar Bracket LH	\$	105.75
27	1	Front Stabilizer Bar Bush LH	\$	66.00
28	1	Front Beam A - Impact LH	\$	214.00

X

Trans-cab Auto Services Pte Ltd

AAD1804-267

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9550P

TOTAL	\$	8,205.52
10%	\$	820.55
	\$	7,384.97

Specical Nett

1	1 Set	Front Fender Liner clip LH	\$	na	30.00	X
2	1 Set	Louver Cowl Top clip	\$	na	30.00	X
3	1	Front right tyre rim	\$	SL	380.00	X
TOTAL			\$		440.00	

TOTAL PARTS	\$	7,824.97
--------------------	-----------	-----------------

LABOUR

To Check Electrical Lighting Concerned.	\$	na	170.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		3,500.00	2001
Putty and spray painting of the affected portion.	\$		3,200.00	4001
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	na	440.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na	380.00	X

TOTAL	\$	8,450.00
--------------	-----------	-----------------

Over All Total	\$	16,274.97
-----------------------	-----------	------------------

Repair Days7 Days
1 1/2 day

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: