



Mercedes-Benz

LKK Survey

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR ER3388H

Chen Meng Yan

33 Swiss View
Singapore 288039

96269965

Vehicle & Document Information

WIP No **23453**
Reg No/Reg Date **ER3388H / 12/03/2015**
Date In/Mileage **/ 0**
Chassis No **WDD2120362B086251**
Engine No **27492030289250**
Make/Model **MB/E 250 2.0 CGI SEDAN (W212**
Colour/Trim **025 526 Dolomite Br/ 042 211 Leather Ant**

Account No	Terms	Date/Time Printed	CSE	Operator
WCV18516	CRDVCH	08/05/2018/ 09:51	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : B27894023QMY // 07/05/2018 DRIVE IN/EXCESS : 07/05/2018 // TP VEH NO YN3454J AXA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				960 1200.00
A BPIRES RESPRAY REAR BUMPER				600 750.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT				120.00
M REAR CROSS MEMBER	1.00	789.45	00.00	789.45
M REAR BUMPER SWITCHING BRACKET	1.00	46.06	00.00	46.06
M RIGHT REAR BUMPER BOTTOM BRACKET	1.00	17.36	00.00	17.36
M LEFT REAR BUMPER BOTTOM BRACKET	1.00	17.36	00.00	17.36
M REAR BUMPER LOWER CHROME MOULDING	1.00	158.78	00.00	158.78
M REAR BUMPER LOWER	1.00	241.49	00.00	241.49
M RIGHT REAR BUMPER CHROME MOULDING	1.00	128.17	00.00	128.17
M LEFT REAR BUMPER CHROME MOULDING	1.00	128.17	00.00	128.17
M REAR BUMPER	1.00	1630.57	00.00	1630.57

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarrage.com.sg

Resu
Ap 90010068
3 days
18/06/18 @ 1030
Resu by paint

Confirmed & accepted by

Authorized signatory and company stamp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Nett **5,607.41**
7% GST on **5607.41** **392.52**
Total Payable **5,999.93**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg