

Taufik

REF

CS/FCI 18008417/T1 sbc2

ASSIGNMENT

From: Date: 9/5/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBJ 4763D

at Workshop: Wearnas

45 Leng Kee Rd.

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record):

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 420K

IDAC Accident Report Consistent? Yes or No

GIA PR Seen Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Burgam

Vehicle No: FBJ 4763D Date: 2018 Feb

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ducati Multistrada 1198

Colour: Red Insured / Std / NI / NA

Sp. Reading: - T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No: ZDM A200A C A B 005829

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70R17
R: 190/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: mm L/Bal: mm

D.O.A.: D.O.I: 9/5/18 @ 120

Survey held at: Wearnas 45 Leng Kee

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time: Action / Instruction: 6430 4933

460K new bike To check repairs limit

05/07/18 Pending Spare Part, Submit preli. report

11/10/18 To re-open case for finalization

03/12/18 Confirmed P/P \$19,120/- @ 5 days with Taufik.

(\$16,420/- Red - 46%)

15/10/18 reopen ref only (1st close date 18/7/18)

RECEIVED 12 JUL 2018

Sub Type: Preli. Report

05/07/18

Typist

Final Report

Days Of Repair: 5

Resurvey No. of Trip: /

Add Fee: Site Insp. \$

Inter. Insp. \$

Tech. Insp. \$

Superv. \$

Report Format:

Lump Sum / LB

24x15 = 360

170 + 360

50

92

672

MV - \$20K.

Netate: \$764

ppm.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7548F
Vehicle Details	
Vehicle No.:	FBJ4763D
Vehicle to be Exported:	No
Intended De-registration Date:	10 May 2018
Vehicle Make:	DUCATI
Vehicle Model:	MULTISTRADA 1200 M
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	ZDM1198WC005641
Chassis No.:	ZDMA200ACAB005629
Maximum Power Output:	-
Open Market Value:	\$29,507.00
Original Registration Date:	01 Oct 2010
First Registration Date:	27 Feb 2012
Transfer Count:	1
Actual ARF Paid:	\$4,427.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,012.00
COE Rebate Amount:	\$764.00
Total Rebate Amount:	\$764.00

The information contained herein is correct as at 10 May 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 3 October 2018 10:07 AM
To: 'Tony Alfred Desire Devaux'
Cc: 'Taufikh (LKKAuto)'; 'Bryan Ang (LKKAuto)'; 'SUR'; 'Benjamin Ong Ban Su'
Subject: RE: SURVEYOR APPOINTED; OUR REF : D18002866MFSH ; YOUR REF: FBJ4763D

Dear Tony,

Confirmed final fig of \$19,120.00 (part by part) @ 5 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tony Alfred Desire Devaux [mailto:tony.deviaux@wearnes.com]
Sent: Tuesday, 2 October 2018 6:41 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>; 'Bryan Ang (LKKAuto)' <bryanang@lkkauto.com>; 'SUR' <sur@lkkauto.com>; Benjamin Ong Ban Su <benjamin.ong@wearnes.com>
Subject: RE: SURVEYOR APPOINTED; OUR REF : D18002866MFSH ; YOUR REF: FBJ4763D

Dear Shirley,

We confirm that the
Final figure is 19,120.00 (parts by parts) and @ 5 days of repairs before GST.

Kind regards

Tony Devaux
Service Consultant



Wearnes Automotive Pte Ltd
45 Leng Kee Road Singapore 159103
F (65) 6474 0853 D (65) 6430 4934
www.wearnesauto.com tony.deviaux@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 2 October 2018 4:27 PM
To: Tony Alfred Desire Devaux <tony.deviaux@wearnes.com>
Cc: 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>; 'Bryan Ang (LKKAuto)' <bryanang@lkkauto.com>; 'SUR'

<sur@lkkauto.com>; Benjamin Ong Ban Su <benjamin.ong@wearnes.com>

Subject: RE: SURVEYOR APPOINTED; OUR REF : D18002866MFSH ; YOUR REF: FBJ4763D

Hi Tony,

Please Confirm final fig of \$18,120.00 (part by part) @ 5 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bryan Ang (LKKAuto) [<mailto:bryanang@lkkauto.com>]

Sent: Tuesday, 25 September 2018 9:47 AM

To: Tony Alfred Desire Devaux <tony.devaux@wearnes.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Benjamin Ong Ban Su <benjamin.ong@wearnes.com>

Subject: RE: SURVEYOR APPOINTED; OUR REF : D18002866MFSH ; YOUR REF: FBJ4763D

Dear Shirley

Please get surveyor to follow up on this finalization.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tony Alfred Desire Devaux <tony.devaux@wearnes.com>

Sent: Tuesday, 25 September 2018 9:34 AM

To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Benjamin Ong Ban Su <benjamin.ong@wearnes.com>

Subject: RE: SURVEYOR APPOINTED; OUR REF : D18002866MFSH ; YOUR REF: FBJ4763D

Dear Bryan,

Please find in attach the supplementary and finalized invoice regarding FBJ4763D

Kind regards

Tony Devaux

Service Consultant



Wearnes Automotive Pte Ltd

45 Leng Kee Road Singapore 159103

F (65) 6474 0853 D (65) 6430 4934

www.wearnesauto.com tony.devaux@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Bryan Ang (LKKAuto) [mailto:bryanang@lkkauto.com]

Sent: Friday, 1 June 2018 9:49 AM

To: Tony Alfred Desire Devaux <tony.devaux@wearnes.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SURVEYOR APPOINTED; OUR REF : D18002866MFSH ; YOUR REF: FBJ4763D

Dear Tony

Insurer will be liable only for damages that are consistent and related to the accident.

At this moment, the amount indicated as unconfirm by our surveyor is relatively high. Without the benefit of parts being dismantled, we cannot be sure that all these parts are damaged.

Regardless of whether the owner decides to repair the bike or not, insurer will be liable for the amount that is lower ie if repair cost is lower than value of bike than insurer will reimburse your client on the repair cost. However if the repair cost exceed the value of the bike, than insurer will reimburse the value of the bike.

At this moment, we are not able to recommend to the insurer or advice your client how much is the reimbursement as the cost of repair to the bike cannot be ascertain at the moment due to the many unconfirm parts that would require dismantling for verifications on whether damaged or not.

As this is a third party claim, insurer and our involvement is on a without prejudice basis and hence we are unable to authorize any dismantling of the bike. To move this matter, you may want to advice your client to authorize the dismantling and from there we can ascertain the true cost of repair.

Ultimately, do note that our recommendation will be subjected to insurer's approval.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tony Alfred Desire Devaux [mailto:tony.devaux@wearnes.com]

Sent: Thursday, 31 May 2018 3:54 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SURVEYOR APPOINTED; OUR REF : D18002866MFSH ; YOUR REF: FBJ4763D

Dear Shirley,

The owner would like to know how much will you pay him in case he decide not to repair the bike?

From there he will take a decision to repair or not the bike.

Looking forward for your prompt reply

Regards

Tony Devaux

Service Consultant



Wearnes Automotive Pte Ltd
45 Leng Kee Road Singapore 159103
F (65) 6474 0853 D (65) 6430 4934
www.wearnesauto.com tony.devaux@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Friday, 25 May 2018 3:00 PM
To: Tony Alfred Desire Devaux <tony.devaux@wearnes.com>; 'Taufikh (LKK Auto)' <taufikh@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>
Subject: SURVEYOR APPOINTED; OUR REF : D18002866MFSH ; YOUR REF: FBJ4763D

Dear Tony,

Please be informed that the repair limited for FBJ 4763D is not more than \$18,000.00

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SERVICE ESTIMATE

92087 - C00018 SL: SERVICE/PARTS SALES - DUCATI
 Mr Douglas Robert Lawson
 5C Thomson View Bright Hill Drive
 Thomson View Condominium

Singapore 379597

Closed by : Ong Ban Su Benjamin
 Svc Consultant : Ong Ban Su Benjamin
 Remarks : Mr Douglas Robert La

Inv.No. . . : D 0 Page 1
 Inv.date . . : 24/04/2018
 WIP No. . . : 56770
 Veh. In/Out:
 *Tel.No. . . : Mobile: 98373751
 Reg.No. . . : FBJ4763D / MS
 Reg.date . . : 22/07/2011
 Mileage . . : 0
 Chassis No.: ZDMA200ACAB005629
 Variant... : MTS1200

Op.No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount	G
NOTES	Third Party Claim against SHC insured with First Motor			0.00	0		S
		\$800 / day				4000 3000	
DUCO-1	To replace damaged parts caus		5600.00	0		5600.00	S
212	Rear Number Plate \$30 cut		40.00	0		✓ 40.00	S
	Front Number plate \$10 cut						
	R.H. PANNIER CO	1.0 EA	998.40			nyx 998.40	S
	L.H. PANNIER CO	1.0 EA	998.40			cut 998.40	S
	BRACKET BOTTOM	1.0 EA	140.50			or 140.50	S
	BRACKET BOTTOM	1.0 EA	140.50			nyx 140.50	S
	PLATE HOLDER	1.0 EA	121.70			ny 121.70	S
	MUDFLAP	1.0 EA	77.70			77.70	S
	NUMBER PLATE HO	1.0 EA	26.70			26.70	S
	FLASHER LIGHT F	1.0 EA	59.40			59.40	S
	FLASHER LIGHT F	1.0 EA	59.40			59.40	S
	SPACER	2.0 EA	17.50			35.00	S
	QUICK FASTENING	5.0 EA	4.30			21.50	S
	QUICK FASTENING	5.0 EA	4.30			21.50	S
	SCREW TCEIF M5X	2.0 EA	2.40			4.80	S
	SCREW	9.0 EA	1.00			9.00	S
	SCREW	1.0 EA	1.00			1.00	S
	SCREW	10.0 EA	6.90			69.00	S
	BRACKET, REFLEC	1.0 EA	20.00			20.00	S
	REFLEX REFLECTO	1.0 EA	7.20			7.20	S
	TAIL GUARD BOT	1.0 EA	296.40			dis 296.40	S

Tan Jhm 97495749 62563561
 wp
 Catherine

2/5/18 2120

* Reasoning check items
 * Reasoning new parts

5 days

See @ / khamf.com

M

SERVICE ESTIMATE

92087 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Douglas Robert Lawson
5C Thomson View Bright Hill Drive
Thomson View Condominium

Singapore 579597
Singapore 579597

Closed by : Ong Ban Su Benjamin
Svc Consultant : Ong Ban Su Benjamin
Remarks : Mr Douglas Robert La

Inv.No. . . : D 0 Page 2
Inv.date . . : 24/04/2018
WIP No. . . : 56770
Veh. In/Out:
*Tel.No. . . : Mobile: 98373751
Reg.No. . . : FBJ4763D / MS
Reg.date . . : 22/07/2011
Mileage . . : 0
Chassis No.: ZDMA200ACAB005629
Variant... : MTS1200

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	TAIL GUARD BOTT	1.0	EA		296.40			296.40	S
	REAR WHEEL RIM	1.0	EA		2433.60			2433.60	S
	VALVE, TUBELESS	1.0	EA		12.80			12.80	S
	NUT	1.0	EA		62.10			62.10	S
	WASHER 48.5X65X	1.0	EA		3.40			3.40	S
	SPACER	1.0	EA		94.90			94.90	S
	GEARBOX POSITIO	1.0	EA		234.00			234.00	S
	REAR WHEEL SPIN	1.0	EA		1474.80			1474.80	S
	LEVA FRIZIONE B	1.0	EA		209.80			209.80	S
	PLUG	2.0	EA		13.70			27.40	S
	REAR-VIEW MIRRO	1.0	EA		234.00			234.00	S
	HUB	1.0	EA		1145.10			1145.10	S
	STEERING CROWN	1.0	EA		858.00			858.00	S
	STEERING HEAD	1.0	EA		624.00			624.00	S
	HANDLEBAR	1.0	EA		299.60			299.60	S
	SEAL RING	2.0	EA		10.80			21.60	S
	BEARING, CONICA	2.0	EA		100.10			200.20	S
	R.H. FORK LEG A	1.0	EA		4648.80			4648.80	S
	L.H. FORK LEG A	1.0	EA		4648.80			4648.80	S
	FRONT WHEEL RIM	1.0	EA		2508.50			2508.50	S
	FRONT WHEEL SPI	1.0	EA		262.30			262.30	S
	VALVE, TUBELESS	1.0	EA		27.90			27.90	S
	MATT CARB.FRONT	1.0	EA		730.90			730.90	S
	CARBON REAR MUD	1.0	EA		569.50			569.50	S

SERVICE ESTIMATE

92087 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Douglas Robert Lawson
5C Thomson View Bright Hill Drive
Thomson View Condominium

Singapore 579597
Singapore 579597

Closed by : Ong Ban Su Benjamin
Sve Consultant : Ong Ban Su Benjamin
Remarks : Mr Douglas Robert La

Inv.No. ... : D 0 Page 3
Inv.date ... : 24/04/2018
WIP No. ... : 56770
Veh. In/Out:
*Tel.No. ... : Mobile: 98373751
Reg.No. ... : FBJ4763D / MS
Reg.date ... : 22/07/2011
Mileage ... : 0
Chassis No.: ZDMA200ACAB005629
Variant... : MTS1200

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	HEADLIGHT			1.0 EA	1244.90		nt X n7	1244.90	S
	LEFT COVER /			1.0 EA	11.00		nt ✓	11.00	S
	COWLING /			1.0 EA	932.90		nt ✓	932.90	S
	WINDSHIELD			1.0 EA	468.00		nt ✓	468.00	S
	HALF-FAIRING FR /			1.0 EA	25.00		nt ✓	25.00	S
	FAIRING, RH			1.0 EA	135.00		nt ✓	135.00	S
	FAIRING, LH			1.0 EA	135.00		nt ✓	135.00	S
	GEARCHANGE LEVE			1.0 EA	111.40		nt ✓	111.40	S
	BUSH			1.0 EA	5.30		nt ✓	5.30	S
	RUBBER PAD			2.0 EA	5.30		nt ✓	10.60	S
	PIN PEDAL			1.0 EA	9.40		nt ✓	9.40	S
	COVER, RADIATOR /			1.0 EA	374.40		nt ✓	374.40	S
	CAP L.H. RED /			1.0 EA	202.80		nt ✓	202.80	S
	CAP R.H. RED /			1.0 EA	202.80		nt ✓	202.80	S

Amount 34,245.00 35,542/-
Amount 34,245.00
GST @ 7 % 2,397.15
Total Amount 36,642.15
Less Amt Paid 0.00
Nett Amount 36,642.15

Labour Total 5,640.00
Parts Total 28,605.00
Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Service Estimates are valid for 10 days from the above date.

This is a computer generated invoice, no signature is required.

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 T +65 6430 4930 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X



WEARNES AUTOMOTIVE PTE LTD

45 LENG KEE ROAD SINGAPORE 159103

Tel: +65 64304930 Fax: +65 6474 0853 www.ducatisingapore.com

Repair Estimate

Date	24 Sep 2018
Bike Number	FBJ4763D
Chassis No.	ZDMA200ACAB05629
Customer	Mr Douglas Robert Lawson
Address	5C Thomson View Bright Hill Drive
Email	

Model	MTS1200
Mileage	56,770
Contact	
Svc. No.	
Youtech	
Technician	

No.	Labour Code	Description	Qty	Unit Price	Amount
		Sub-Total			

No.	Part Number	Description	Qty	Unit Price	Amount
		* WINDSHIELD <i>cut</i>	1	\$468.00	\$468.00
		* FAIRING, RH <i>cut</i>	1	\$135.00	\$135.00
		* FAIRING, LH <i>cut</i>	1	\$135.00	\$135.00
		* GEARCHANGE LEVER <i>bt</i>	1	\$111.40	\$111.40
		* PIN PEDAL <i>new</i>	1	\$8.00	\$8.00
		FRONT FENDER RED <i>cut one</i>	1	\$356.50	\$356.50
		STAY, WINDSHIELD <i>bt</i>	1	\$53.40	\$53.40
		RUBBER PAD <i>new</i>	1	\$3.30	\$3.30
		SCREW, SPECIAL <i>new</i>	1	\$2.70	\$2.70
		COVER, TANK RH <i>cut</i>	1	\$838.80	\$838.80
		QUICK FASTENING M5 <i>new</i>	1	\$1.20	\$1.20
		QUICK FASTENING <i>new</i>	2	\$2.70	\$5.40
		SCREW <i>new</i>	2	\$4.00	\$8.00
		BUSH <i>new</i>	2	\$1.10	\$2.20
		SCREW, SPECIAL <i>new</i>	1	\$14.60	\$14.60
		HOSE GUIDE <i>new</i>	1	\$6.00	\$6.00
		RUBBER PAD <i>new</i>	1	\$4.90	\$4.90
		Sub-Total			\$2,154.40

1. This estimate is compiled with visual inspection on the above mentioned motorcycle.

2. During the repair process, additional parts and labour may be required to complete the repairs works. A supplementary estimate shall be created accordingly.

3. The undersigned signature represents the acceptance of this estimate and the permission to proceed with repair works.

Signature: _____

Total Labour:	\$0.00
Total Parts:	\$2,154.40
GST:	\$150.81
Grand Total:	\$2,305.21

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01, CITY HOUSE
SINGAPORE

Singapore 068877

Closed by : Tony Alfred Desire D
Svc Consultant : 0648
Remarks : Mr Douglas Robert La

Inv.No. . . : D 0 Page 1
Inv.date . : 25/09/2018
WIP No. . . : 56770
Veh. In/Out: 16/07/2018 10/09/2018
*Tel.No. . . :
Reg.No. . . : FBJ4763D / MS
Reg.date . : 22/07/2011
Mileage . . : 1
Chassis No.: ZDMA200ACAB005629
Variant... : MTS1200

Op.No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount	G
NOTES	Third Party Claim against SHC insured with First Motor		0.00	0			S
DUCO-1	To replace damaged parts caus	Ch	4000.00	0		4000.00 2000	S
212	Rear Number Plate \$30		40.00	0		40.00	S
	Front Number plate \$10						
	L.H. PANNIER CO	1.0 EA	998.40			998.40	S
	BRACKET BOTTOM	1.0 EA	140.50			140.50	S
	TAIL GUARD BOTT	1.0 EA	296.40			296.40	S
	LEVA FRIZIONE B	1.0 EA	209.80			209.80	S
	REAR-VIEW MIRRO	1.0 EA	234.00			234.00	S
	R.H. FORK LEG A	1.0 EA	4648.80			4648.80	S
	L.H. FORK LEG A	1.0 EA	4648.80			4648.80	S
	LEFT COVER	1.0 EA	11.00			11.00	S
	COWLING	1.0 EA	932.90			932.90	S
	HALF-FAIRING FR	1.0 EA	25.00			25.00	S
	COVER, RADIATOR	1.0 EA	374.40			374.40	S
	CAP L.H. RED	1.0 EA	202.80			202.80	S
	CAP R.H. RED	1.0 EA	202.80			202.80	S
	D48710471A/WIND	1.0 EA	468.00			468.00	S
	D48011501A/FAIR	1.0 EA	135.00			135.00	S
	D48011511A/FAIR	1.0 EA	135.00			135.00	S
	D45612041A/GEAR	1.0 EA	111.40			111.40	S
	PIN PEDAL	1.0 EA	8.00			8.00	S
	FRONT FENDER RE	1.0 EA	356.50			356.50	S

SERVICE ESTIMATE

O - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877
 Singapore 068877

Inv.No. . . : D 0 Page 2
 Inv.date . . : 25/09/2018
 WIP No. . . : 56770
 Veh. In/Out: 16/07/2018 10/09/2018
 *Tel.No. . . :
 Reg.No. . . : FBJ4763D / MS
 Reg.date . . : 22/07/2011
 Mileage . . : 1
 Chassis No.: ZDMA200ACAB005629
 Variant... : MTS1200

Closed by : Tony Alfred Desire D
 Svc Consultant : 0648
 Remarks : Mr Douglas Robert La

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	STAY, WINDSHIEL			1.0 EA	53.40			53.40	S
	RUBBER PAD			1.0 EA	3.30			3.30	S
	SCREW, SPECIAL			1.0 EA	2.70			2.70	S
	COVER, TANK RH			1.0 EA	838.80			838.80	S
	QUICK FASTENING			1.0 EA	1.20			1.20	S
	VQUICK FASTENIN			2.0 EA	2.70			5.40	S
	SCREW			2.0 EA	4.00			8.00	S
	VBUSH			2.0 EA	1.10			2.20	S
	VSCREW, SPECIA			1.0 EA	14.60			14.60	S
	VHOSE GUIDE			1.0 EA	6.00			6.00	S
	RUBBER PAD			1.0 EA	4.90			4.90	S

				=====	
				Amount	19,120.00
				Amount	19,120.00
				GST @ 7 %	1,338.40
				Total Amount	20,458.40
				Less Amt Paid	0.00
				Nett Amount	20,458.40
Labour Total	3,040.00				
Parts Total	15,080.00				
Package Total	0.00				

GST: S=StdRated; O=OutOfScope; Z=ZeroRated
 Service Estimates are valid for 10 days from the above date.
 This is a computer generated invoice, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 4763D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR NUMBER PLATE \$30 (SN)	CRACKED	30.00	30.00
1	FRONT NUMBER PLATE \$10 (SN)	NECESSARY	10.00	10.00
1	R.H. PANNIER CO (SN)	NOT NECESSARY	998.40	-
1	L.H. PANNIER CO (SN)	CUT	998.40	998.40
1	BRACKET BOTTOM (SN)	BENT	140.50	140.50
1	BRACKET BOTTOM (SN)	NOT NECESSARY	140.50	-
1	PLATE HOLDER (SN)	NOT NECESSARY	121.70	-
1	MUDFLAP (SN)	NOT NECESSARY	77.70	-
1	NUMBER PLATE HO (SN)	NOT NECESSARY	26.70	-
1	FLASHER LIGHT F (SN)	NOT NECESSARY	59.40	-
1	FLASHER LIGHT F (SN)	NOT NECESSARY	59.40	-
2	SPACER @\$17.50 (SN)	NOT NECESSARY	35.00	-
5	QUICK FASTENING @\$4.30 (SN)	NOT NECESSARY	21.50	-
5	QUICK FASTENING @\$4.30 (SN)	NOT NECESSARY	21.50	-
2	SCREW TCEIF M5X @\$2.40 (SN)	NOT NECESSARY	4.80	-
9	SCREW @\$1.00 (SN)	NOT NECESSARY	9.00	-
1	SCREW (SN)	NOT NECESSARY	1.00	-
10	SCREW @\$6.90 (SN)	NOT NECESSARY	69.00	-
1	BRACKET, REFLEC (SN)	NOT NECESSARY	20.00	-
1	REFLEX, REFLECTO (SN)	NOT NECESSARY	7.20	-
1	TAIL GUARD BOTT (SN)	DISTORTED	296.40	296.40
1	TAIL GUARD BOTT (SN)	NOT NECESSARY	296.40	-
1	REAR WHEEL RIM (SN)	NOT NECESSARY	2,433.60	-
1	VALVE, TUBELESS (SN)	NOT NECESSARY	12.80	-
1	NUT (SN)	NOT NECESSARY	62.10	-
1	WASHER 48.5X65X (SN)	NOT NECESSARY	3.40	-
1	SPACER (SN)	NOT NECESSARY	94.90	-
1	GEARBOX POSITIO (SN)	NOT NECESSARY	234.00	-
1	REAR WHEEL SPIN (SN)	NOT NECESSARY	1,474.80	-
1	LEVA FRIZIONE B (SN)	BENT	209.80	209.80
2	PLUG @\$13.70 (SN)	NOT NECESSARY	27.40	-

Report Ref No. CS/FCI18008417/T1sbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR-VIEW MIRRO (SN)	CUT	234.00	234.00
1	HUB (SN)	NOT NECESSARY	1,145.10	-
1	STEERING CROWN (SN)	NOT NECESSARY	858.00	-
1	STEERING HEAD (SN)	NOT NECESSARY	624.00	-
1	HANDLEBAR (SN)	NOT NECESSARY	299.60	-
2	SEAL RING @\$10.80 (SN)	NOT NECESSARY	21.60	-
2	BEARING, CONICA @\$100.10 (SN)	NOT NECESSARY	200.20	-
1	R.H. FORK LEG A (SN)	BENT	4,648.80	4,648.80
1	L.H. FORK LED A (SN)	BENT	4,648.80	4,648.80
1	FRONT WHEEL RIM (SN)	NOT NECESSARY	2,508.50	-
1	FRONT WHEEL SPI (SN)	NOT NECESSARY	262.30	-
1	VALVE, TUBELESS (SN)	NOT NECESSARY	27.90	-
1	MATT CARB, FRONT (SN)	NOT NECESSARY	730.90	-
1	CARBON REAR MUD (SN)	NOT NECESSARY	569.50	-
1	HEADLIGHT (SN)	NOT NECESSARY	1,244.90	-
1	LEFT COVER (SN)	CUT	11.00	11.00
1	COWLING (SN)	CUT	932.90	932.90
1	WINDSHIELD (SN)	CUT	468.00	468.00
1	HALF-FAIRING FR (SN)	CUT	25.00	25.00
1	FAIRING, RH (SN)	CUT	135.00	135.00
1	FAIRING, LH (SN)	CUT	135.00	135.00
1	GEARCHANGE LEVE (SN)	BENT	111.40	111.40
1	BUSH (SN)	NOT NECESSARY	5.30	-
2	RUBBER PAD @\$5.30 (SN)	NOT NECESSARY	10.60	-
1	PIN PEDAL (SN)	NECESSARY	9.40	8.00
1	COVER, RADIATOR (SN)	CUT	374.40	374.40
1	CAP L.H. RED (SN)	CUT	202.80	202.80
1	CAP R.H. RED (SN)	CUT	202.80	202.80
1	STAY, WINDSHIELD (SN) (ADDITIONAL)	BENT	53.40	53.40
1	RUBBER PAD (SN) (ADDITIONAL)	NECESSARY	3.30	3.30
1	SCREW, SPECIAL (SN) (ADDITIONAL)	NECESSARY	2.70	2.70
1	COVER, TANK RH (SN) (ADDITIONAL)	CUT	838.80	838.80
1	QUICK FASTENING M5 (SN) (ADDITIONAL)	NECESSARY	1.20	1.20

Report Ref No. CS/FCI18008417/T1sbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	VQUICK FASTENING (SN) (ADDITIONAL)	NECESSARY	5.40	5.40
2	SCREW (SN) (ADDITIONAL)	NECESSARY	8.00	8.00
2	BUSH (SN) (ADDITIONAL)	NECESSARY	2.20	2.20
1	SCREW, SPECIAL (SN) (ADDITIONAL)	NECESSARY	14.60	14.60
1	HOSE GUIDE (SN) (ADDITIONAL)	NECESSARY	6.00	6.00
1	RUBBER PAD (SN) (ADDITIONAL)	NECESSARY	4.90	4.90
1	FRONT FENDER RED (SN) (ADDITIONAL)	CRACKED	356.50	356.50
			29,942.00	15,120.00
	LABOUR			
	TO REPLACE DAMAGED PARTS CAUS.		5,600.00	4,000.00
			5,600.00	4,000.00
	GRAND TOTAL		35,542.00	19,120.00
RECOMMENDED COST OF REPAIRS				19,120.00

Report Ref No. CS/FCI18008417/T1sbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.