



QUOTATION

Customer :

NO. : 32588

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
MOTOR CLAIMS DEPT

not authorized
Take photo. After repair
PIP \$ 2507.20
Hony

DATE : 07/05/2018
CLAIM NO. : 11140
POLICY NO. : 5050486199-06

FROM : RAYMOND

VEHICLE NO. : FBL7254B
MAKE/MODEL : SYM / MAXSYM 400I CVT

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX FR-INNER P/N: 55078	REPLACE	1.00	\$68.00	68.00
2	BOX REAR (GIVI) V56N MAXIA 4 P/N: 54026	REPLACE	1.00	\$875.00	875.00
3	COVER GARNISH FRONT RH P/N: 55474	REPLACE	1.00	\$10.00	10.00
4	COVER TAIL REAR RH P/N: 56665	REPLACE	1.00	\$10.00	10.00
5	DAMPER BOX INNER LID P/N: 56666	REPLACE	1.00	\$12.00	12.00
6	DAMPER COVER TAIL RH P/N: 56673	REPLACE	2.00	\$5.00	10.00
7	EXH.MUFFLER ASSY P/N: 55107	REPLACE	1.00	\$2,548.00	2,548.00
8	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	6.00	\$35.00	210.00
9	LEVER BRAKE RH P/N: 55472	REPLACE	1.00	\$80.00	80.00
10	METER PANEL BK-001U P/N: 55090	REPLACE	1.00	\$35.00	35.00
11	PANEL RH- FLOOR P/N: 55065	REPLACE	1.00	\$42.00	42.00
12	SPRAY PAINTING (Whole Bike)	Spray	1.00	\$910.00	910.00
13	STICKER (ORANGEFORCE) BOX REAR NEW P/N: 54254	REPLACE	1.00	\$50.00	50.00



S/N	Description	Action	Qty	Unit Price	Amount
14	STICKER (ORANGEFORCE) COVER SIDE NEW P/N: 54256	REPLACE	2.00	\$70.00	140.00
15	STICKER(ORANGEFORCE) WINDSHIELD NEW P/N: 54253	REPLACE	1.00	\$70.00	70.00
16	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835 - TOW BIKE BACK FOR ACCIDENT REPAIR.		1.00	\$60.00	60.00
17	WIND SCREEN ASSY P/N: 57424	REPLACE	1.00	\$230.00	230.00

SUB TOTAL	\$5,360.00
GST @ 7 %	\$375.20
GRAND TOTAL	\$5,735.20

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1458
1312.2
lahu-1195





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 32656
Supplementary 1 To QTN: 32588

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711

DATE : 30/05/2018
CLAIM NO. : 11140
POLICY NO. : 5050486199-06
FROM : RAYMOND

VEHICLE NO. : FBL7254B
MAKE/MODEL : SYM / MAXSYM 400I CVT

S/N	Description	Action	Qty	Unit Price	Amount
1	FRONT UNDER SPOILER P/N: 55352	Replace	1.00	\$243.00 Disc %: 10.00	one 218.70 ✓
2	UPPER HANDLE COVER ASSY CY-517S P/N: 56132	Replace	1.00	\$73.00 Disc %: 10.00	cu7 65.70 ✓
SUB TOTAL					\$284.40
GST @ 7 %					\$19.91
GRAND TOTAL					\$304.31

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1.0383
ISO 9001 : 2008