


SMRT Accident Vehicle Repair Estimates

AIG

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4999G
 Ref. No : TAX/05/18/2026
 Reg. Date : 25/01/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN GEOK SUAN
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 05/05/2018 08:57:00 AM
 Accident Reported Date / Time : 05/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095908
 Special Instruction to ARC, if any :
 SJP9847J
 Prepared Date : 05/05/2018 12:13:02 PM



Sebastian.
 7/5/18 -
 - Part by part repair.
 - Question Mark Itun
 Photo
 - Photo Before Paint

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605768932

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	507.00	0.00
Total Spray Painting Charges :	558.00	0.00
Total Material Charges :	732.36	732.36
Other Charges :	240.00	0.00
TOTAL :	2,037.36	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	3.00	0.00
Prepared / Adjusted By :		2 days
Arc / Surveyor Sign Off Date :	05/05/2018 01:50:00 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/05/2018 01:50:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	507.00	0.00 300
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 100
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	240.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace R	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace R	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace X	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace ✓ OT	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace ✓ OT	No
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace X	No
TOTAL MATERIALS							718.50	718.49		
TOTAL MATERIALS(Discounted)							732.36	732.36		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									