

DATE 05/07/18 02:47 PM

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$1,052.20
	Front Bumper Bracket Top (RH) ?			\$22.40
	Front Bumper Side Bracket (RH) ?			\$24.60
	Front Fender (RH)			\$619.00
	Headlamp assy RH			\$1,388.00
	Frt Fender s/shield Rh ?			\$169.80
	SUB TOTAL			\$3,276.00
	LESS 20%			\$655.20
	DISCOUNTED TOTAL			\$2,620.80
	Labour Charge			
	Panel Beating			
	Spray Painting Charge			
	Tuff Kote			
	Check wiring			
	TOTAL LABOUR			\$1,100.00
	ESTIMATE TOTAL			\$3,720.80

Kalra LKKK
 7/5/18 1505hr
 2 Dgs.
 PIP
 Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.