

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 11 May 2018

Preliminary Advice

Insured Vehicle No	: SJQ4349K	Accident Date	: 04/05/2018
TP Vehicle No	: SJE4839B	Assignment Date	: 08/05/2018
Make	: HYUNDAI I30 (FD)	Est. Duration of Repair	: 4.00
Date of Inspection	: 09/05/2018		
Inspection At	: ALFRED AUTO SERVICES & SUPPLIES (HQ) BLK 5035, ANG MO KIO AVE 3, #01-351, ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,828.00
Revised Amount	:S\$	1,760.00
Check Items (Estimated)	:S\$	2,610.00
Total	:S\$	4,370.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.