



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



Lonpac Insurance BHD

#19-00, 100 Beach Rd,
Singapore 189702

ATTN.: MOTOR CLAIMS

FAX :

NAME : Mr Tsui Kee
ADDRESS : 5 Tanah Merah Kechil Road
#19-03
Singapore 466665

TEL :

WIP : 33864
EXCESS :
DATE: 08.05.2018

VEH NO :	SDJ3000E	DATE IN :		CONTACT PERSON :	RICK	63602445
CHASSIS NO :	WP1ZZZ95ZHLB04312	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SJH6950H	
MODEL :	Porsche Macan PDK	DATE REG.:	27.10.2016	POLICY NO. :		

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	REAR BUMPER ✓ CRK	1		\$ 856.60
2	REAR BUMPER LOWER SPOILER ✓ CRK	1		\$ 277.90
3	REAR BUMPER LOWER COVER ✓ SCR	1		\$ 185.30
4	EXPANSION RIVET ✓ NEC	6		\$ 3.00
5	TOW COVER X	1		\$ 39.30
6	SENSOR PARKASSIST ?	2		\$ 451.40
7	SENSOR GASKET ?	2		\$ 4.60
8	REAR BUMPER INSULATION LH ✓ NEC	1		\$ 32.80
9	REAR BUMPER INSULATION RH ✓ NEC	1		\$ 32.80
10	REINFORCEMENT ?	1		\$ 309.30
11	REINFORCEMENT SUPPORT RH ?	1		\$ 104.10
12	REINFORCEMENT SCREW ?	4		\$ 33.60
13	SUPPORT SCREW ?	4		\$ 25.20
14	NUT ?	4		\$ 6.40
15	LOGO "PORSCHE" REAR CHROME ✓ NEC	1		\$ 140.70
16	NAMEPLATE MACAN ✓ NEC	1		\$ 97.10
17	REFLECTOR REAR (RH) ✓ CRK	1		\$ 296.40
18	REAR MUFFLER RH ?	1		\$ 1,635.70
19	REAR MUFFLER LH ?	1		\$ 1,635.70
20	TAIL PIPE RH ?	1		\$ 295.40
21	CLAMPING SLEEVE EXHAUST ?	2		\$ 169.80
22	CENTER EXHAUST SYSTEM ?	1		\$ 1,473.00
23	CLAMPING SLEEVE EXHAUST CENTRE ?	1		\$ 80.00
24	REAR MUFFLER BOLT ?	4		\$ 4.40
TOTAL PARTS				\$ 8,190.50
LESS 10%				\$ 819.05
TOTAL PARTS COST				\$ 7,371.45
Labour Description				
1	TO REPLACE REAR BUMPER & OTHER PARTS. TO REPAIR REAR END PANEL AFFECTED BY THE ACCIDENT. 1560/day			\$ 4,680.00
2	TO RESPRAY REAR BUMPER, TAILGATE & REAR END PANEL 1300 bumper 1100 bootlid			\$ 3,800.00
				2400

3	TO CARRY-OUT BODY CAVITY PRESERVATION. ?		\$ 250.00	
4	TO REMOVE & REPLACE THE REAR EXHAUST ASSY. ?	NETT	\$ 1,560.00	
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 250.00	✓
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 600.00	✓
7	SUNDRIES.	NETT	\$ 50.00	✓
TOTAL LABOUR		\$ -	\$ 11,190.00	
TOTAL PARTS		\$ -	\$ 7,371.45	
TOTAL		\$ -	\$ 18,561.45	
LESS EXCESS		\$ -	\$ -	
TOTAL AFTER EXCESS		\$ -		
GST 7%		\$ -	\$ -	
GRAND TOTAL		\$ -	\$ -	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Sebastian
11/5/18
- Part by part repair
- Question mark Item
Photo
- Photo Before Paint.

90036121

sebastian.yang@lkk-auto.com

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: