



SLC6777U

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 08-05-18

Vehicle Reg. No. : SLC6777U
Vehicle Reg. Date: 23-May-2016
Make / Model : T. VIOS E GRADE 1.5 A/T
Engine No. : 1NZZ321573
Chassis No. : MHFBT9F3106064779

COST OF CLAIMS

Parts Cost / List Items : \$ 15,535.36
Plus/Less 25% \$ 3,883.84
Total Cost / List : \$ 11,651.52
Special Nett Items : \$ 865.00
Total Parts Amount : \$ 12,516.52
Total Labour Amount : \$ 5,280.00
Gross Total : \$ 17,796.52
GST % : 7% \$ 1,245.76
Nett Amount : \$ 19,042.28

Surveyor Name and Company :

RASUL CLKK

Date of survey : 08/05/18 @ 1645

Part by Part / Lump Sum : 8 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : 90010068

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6777U**

Vehicle Reg. Date: **23-05-16**

Make / Model : **T. VIOS E GRADE 1.5 A/T**

Engine No. : **1NZZ321573**

Chassis No. : **MHFBT9F3106064779**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Bootlid	PA ✓	\$ 960.65		
2	1	Bootlid inner trim	X	\$ 937.75		
3	1set	Bootlid inner trim clip - set	new ✓	\$ 97.05		
4	1	Bootlid lock	PA ✓	\$ 96.09		
5	1	Bootlid lock cable	X	\$ 88.30		
6	1	Bootlid lock catch	PA ✓	\$ 52.54		
7	2	Bootlid hinge LH/RH	X	\$ 162.21		
8	1	Bootlid logo	new ✓	\$ 94.01		
9	1	Bootlid emblem "VIOS"	new ✓	\$ 101.76		
10	1	Bootlid emblem "E"	new ✓	\$ 93.63		
11	1	Boot weatherstrip	new ✓	\$ 198.06		
12	1	Bootlid outer garnish	X	\$ 334.27		
13	2	Bootlid number plate lamp LH/RH	X	\$ 187.61		
14	1	Rear bumper	DE ✓	\$ 745.93		
15	1set	Rear bumper clip	new ✓	\$ 68.48		
16	2	Rear bumper side retainer LH/RH	new ✓	\$ 145.09		
17	2	Rear bumper impact bracket LH/RH	new ✓	\$ 335.66		
18	2	Rear bumper retainer short LH/ RH	new ✓	\$ 84.00		
19	2	Rear bumper reflector LH/RH	CR4 ✓	\$ 423.29		
20	2	Tail lamp LH/RH	LH-CR4/RH-?	\$ 812.92		
21	1set	Tail lamp clip - set	new ✓	\$ 53.50		
22	2	Tail lamp panel LH/RH	Repair ✓	\$ 563.25		
23	2	Tail lamp lower bracket LH/RH	new ✓	\$ 106.14		
24	1	Rear end panel	PA ✓	\$ 729.31		
25	1	Rear end panel outer bracket	PA ✓	\$ 74.90		
26	1	Rear end panel garnish	DE ✓	\$ 245.46		
27	1set	Rear end panel garnish clip - set	new ✓	\$ 44.94		
28	2	Rear fender LH/RH	Repair ✓	\$ 1,931.40		
29	1	Rear fender inner trim LH	X	\$ 916.67		
30	1	Rear fender inner trim RH	X	\$ 916.67		
31	1set	Rear fender inner trim clip - set	X	\$ 190.46		
32	2	Rear water shield LH/RH	X	\$ 248.24		
33	1	Spare tyre panel	X	\$ 941.17		
34	2	Spare tyre side panel LH/RH	X	\$ 402.04		
35	2	Spare tyre side board cover LH/RH	X	\$ 192.39		
36	1	Spare tyre top board	X	\$ 289.97		
37	1	Spare tyre top carpet	X	\$ 273.20		
38	1	Exhaust muffler	X	\$ 520.75		
39	1	Exhaust muffler mounting	X	\$ 75.60		
40	2	Rear Air duct LH/RH	X	\$ 150.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6777U**

Vehicle Reg. Date: 23-05-16

Make / Model : T. VIOS E GRADE 1.5 A/T

Engine No. : 1NZZ321573

Chassis No. : MHFBT9F3106064779

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Rear bumper reinforcement	?	\$ 650.00		
42	1	Rear number plate	X		\$ 55.00	
43	1	Bootlid sealant	m /		\$ 80.00	40
44	1	Rear end panel sealant	m /		\$ 80.00	40
45	1	Spare tyre panel sealant	X		\$ 80.00	
46	1	Tail lamp panel sealant	X		\$ 80.00	
47	2	Tail lamp pad	X		\$ 160.00	
48	1	Rear fender panel sealant	X		\$ 80.00	
49	1	Reverse sensor	m /		\$ 250.00	200
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	Z				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]