

22/03/2002

ASS. SEC. BY:

REF:

CS/CTI 1800 8464 / <sup>N</sup>8464

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Sharon Han of

CTI

Date/Time:

08/05/18

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 9211 H

Insured:

GRE 6679 C

at Workshop m/s

Wearnes Automotive

Tel:

of

249 Alexandra Road

Policy No:

DMCVSN 3015441801

Claim No:

'SNM 18D02332C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/05/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9/5

Person Contacted:

Richmond

Vehicle IN OUT

Date/Time

Action/Instruction

( )

Estimate

Part by Part \$11,464.65 (Red: 4607.78 :28%)



## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2018		08 May 2018 17:14 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

Insured:	MASTER CONSTRUCTION WORKS PTE LTD, Co. Reg. No.: 201412175G			[Created by insurer]
Main Claimant:	LIM SIEW GEK			
Vehicle Reg. No.:	SLN9211H	Date of Loss:	05/05/2018 10:00 - :59	
Claim Type:	TP / SNM18D02332C02	Policy/Cover Note No.:	DMCVSN3015441801 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBE6679C	Policy No. (Claimant):		
		Excess:	\$50.00	
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/05/2018]			
Adj Asg. Remarks:	EST \$15,260.25 , CASE WITH SJE.			

## ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

## ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
No results.									

Out Richmond.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Complete and submit this Form to Allied World's Authorised Reporting Centre ("ARC") for filing.
2. Please report correctly the details of the accident to speed up the claims process.
3. This Form must be completed by the Policyholder and/or the Authorised Driver.
4. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
6. Any false reporting may be referred to the Traffic Police Department for investigation.

## ACCIDENT STATEMENT

Date and Time of Accident

Date: 05/05/2018 Time: 1100.

Exact Location of Accident

EXIT OF PANDAN VALLEY (2) MLU PANDAN.

## DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLN92C1H.

## INSURED / POLICYHOLDER (OWN VEHICLE)

Name of Registered Owner (See Insurance Cert.)

LIM SIEN GIC.

Personal Identification - NRIC (Singaporean/PR)

S1846268J.

- FIN/Passport Number

- Not Applicable

## VEHICLE PARTICULARS (OWN VEHICLE)

Vehicle Make / Model

Manufacturer VOLW Model

Type of Vehicle\*

☒ Saloon ☐ MPV ☐ CRV ☐ Van ☐ Lorry  
☐ Bus ☐ M/cycle ☐ Others, \_\_\_\_\_

Exact Purpose for which vehicle was being used at time of accident

SOCIAL

Are you claiming under your own insurance policy for repair to your vehicle?

☐ Yes ☒ No (If No, Pls select: ☒ Third Party ☐ Reporting)

Vehicle Category\*

☒ Private ☐ Commercial ☐ Motorcycle

## INSURANCE COMPANY (OWN VEHICLE)

Name of Insurance Company \*

LIBERTY

Type of Policy

☒ Comprehensive ☐ Third Party Fire & Theft ☐ TP Only

Fleet Policy

☐ Yes ☒ No

Policy Number

SD7V0T574.

Motor CI

## DRIVER

☐ Same as Insured above

Name of Driver

LIM SIEN GIC.

Personal Identification - NRIC (Singaporean/PR)

S1846268J.

- FIN/Passport Number

Date of Birth

25 dd/03 mm/1962yy

Driving Date Pass

07 dd/05 mm/1991yy

Year of Driving Experience

Year(s)

Month(s)

Occupation

☒ Indoor ☐ Outdoor

Gender

☐ Male ☒ Female

Contact Number / Mobile Phone / Fax No.

97727246.

Address of Driver	BIC 1 PANDAN VALLEY	
	#06-105	Postcode ( 597625 )
Email Address	NO EMAIL	
Was driver an employee of the Insured's Company?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
If No, Relationship of the Driver with the Insured	OWNER	
Vehicle Registration Number of Driver's Own	<input type="radio"/> Yes <input type="radio"/> No	
Vehicle Registration Number of Driver's Own Vehicle (if applicable)		
Insurance Company of Driver's Own Vehicle (if applicable)		
<b>GENERAL INFORMATION OF THE ACCIDENT</b>		
Type of Collision (Eg. Chain collision, Head-On collision, Side Swipe, Front to Rear)	HEAD - REAR (TP -	
Weather Conditions	<input checked="" type="radio"/> Clear <input type="radio"/> Raining <input type="radio"/> Others, _____	
Road Surface	<input checked="" type="radio"/> Dry <input type="radio"/> Wet <input type="radio"/> Others, _____	
<b>OTHER INFORMATION</b>		
Was any foreign vehicle involved in this accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any body injured in the accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any other vehicle or property damaged?	<input checked="" type="radio"/> Yes <input type="radio"/> No	
Was there any video captured by Car Camera?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Number of Passengers (Including Driver)	01	
<b>DETAILS OF POLICE ACTION</b>		
Was the Accident reported to the Police?	<input type="radio"/> Yes <input type="radio"/> No (If Yes, please state which Police Station.)	
Police Station Name		
Police Station Address		
Police Station Contact	Tel No.	Fax No.
Was notice of intended Prosecution given?	<input type="radio"/> Yes <input type="radio"/> No (If Yes, against whom?)	
<b>DETAILS OF OTHER VEHICLE / PROPERTY 1</b>		
Vehicle Registration Number	GBC 6679C	
Vehicle Make/ Model/ Colour		
Details of Properties		
Name of Driver	Karthikeyan Sivaji Chakravarthi	
Personal Identification - NRIC (Singaporean/PR)	G725890821	
- FIN/Passport Number		
Contact Number		
Address		
Name of Insurance Company		
Nature of Damage		
No. of Passenger (Including Driver)		
(Note - Please use page 6 if you need to add more vehicles )		

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


*Unsinglet*

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



**Describe Circumstance of the Accident**

I was exiting my condo, inching forward & then I stopped as there was oncoming traffic. Truck behind me did not realise that I stopped & had been following closely behind me. So, his vehicle collided into the back of my car.

**IMPORTANT NOTE**

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

**Declaration**

I/We declare the foregoing particulars are true in every respect.

*Lim Siew Gek*

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre Personnel

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

<b>Name of Policyholder:</b> LIM SIEW GEK		<b>Certificate No.:</b> SD17V07574/ VPC / R00
<b>Date of Issue:</b> 20 Jun 2017	<b>Effective Date of Commencement:</b> 22 May 2017 00:00	<b>Date of Expiry:</b> 21 May 2018 23:59
<b>Registration No.:</b> SLN9211H	<b>Chassis No.:</b> YV1MV28H0H2436746	<b>Type of Certificate:</b> MX1

**Persons or Classes of Persons entitled to drive\*:**

- A) The Policyholder.
- B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

**Limitations as to use:**

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

**The Policy does not cover:**

- A) Use for hire or reward.
- B) Use for racing, pace-making, reliability trials or speed-testing.
- C) Use for the carriage of goods (other than samples) in connection with any trade or business.
- D) Use for any purpose in connection with the Motor Trade.

\*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).



For and on behalf of  
**LIBERTY INSURANCE PTE LTD**  
 Approved Insurers

**For Information Only:**

Coverage(s):	Comprehensive, Unlimited Windscreen
Sum Insured:	MARKET VALUE AT THE TIME OF LOSS
Excess:	Section I S\$800, Additional Excess for Young & Inexperienced Drivers S\$3000, Windscreen Excess S\$100
Name of Finance Company:	OVERSEA-CHINESE BANKING CORPORATION LTD
Name of Producer:	WEARNES AUTOMOTIVE PTE LTD (A1716-80)

PLES/PLES/SD17V07574/21-Jun-2017/MotorCI/v1.0





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/05/2018 12:58
Date Of Accident	05/05/2018 11:00
Exact Location Of Accident	EXIT OF PANDAN VALLEY @ ULU PANDAN
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN9211H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM SIEW GEK
NRIC No	S1846268J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97727246
Alternative Phone No	OTHERS-97727246
<b>Vehicle Particulars</b>	
Manufacturer	VOLVO
Model	V40-1.5 T2 (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V07574
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM SIEW GEK
NRIC No	S1846268J
Date Of Birth	25/03/1962
Occupation	INDOOR
Date Of Driving Pass	07/05/1991
Driving Experience	26 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	+65-97727246
Fax Number	
Contact Number	OTHERS-97727246
Email Address	NOEMAIL

Address	BLK 1 PANDAN VALLEY
	#06-105
Postcode	597625
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE6679C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KARTHIKEYAN SIVAJI CHAKRAVARTHI
NRIC/Passport Number	G7258408U
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

### SERVICE ESTIMATE

50576 - C00002 SL: SERVICE SALES - LCV

Ms Lim Lim Siew Gek  
Blk 1 Pandan Valley  
#06-105

Singapore 597625

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 07/05/2018

WIP No. : 59406

Veh.In/Out:

\*Tel.No. : Mobile: 97727246

Reg.No. : SLN9211H

Reg.date : 22/05/2017

Mileage : 0

Chassis No: YV1MV28H0H2436746

Closed by .... : Michelle Ong Siew Be

Svc Consultant :

Remarks ..... : Ms Lim Siew Gek

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR BRACKET, REAR SENSOR, REAR BOOT LID, REAR EMBLEM, ETC	0	4000.00	0		4,000.00 S	
	<i>800/day</i>					<i>2400</i>	
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, ETC	0	2100.00	0		2,100.00 S	
	<i>700/pair</i>					<i>1400</i>	
802	TO TRANSFER REAR BOOT LID	0	250.00	0		250.00 S	✓
PARTS							
802	TO REPLACE REAR WINDSCREEN	0	800.00	0		800.00 S	✓
89994	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00 S	✓
280	TO CHECK WIRING INCLUDE	0	450.00	0		450.00 S	✓
RESETTING OF ALL ELECTRICAL MODULES							

VO39814190/BUMPER CO	✓ C&K	1.0 EA	1186.50		1,186.50 S	1067.85
BUMPER BRACKET LHR V	✓ VRC	1.0 EA	88.70		88.70 S	79.83
BUMPER BRACKET RHR V	✓ NEC	1.0 EA	88.70		88.70 S	79.83
BUMPER SPOILER REAR		1.0 EA	486.40		486.40 S	X NN X

*6 days.*

*Sebastian  
14/5/18.*

*Part by part repair.  
- Question Mark Item  
Photo  
- Photo Before Paint  
90036121*

*Sebastian.yeang@lkkauto.com*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### SERVICE ESTIMATE

50576 - C00002 SL: SERVICE SALES - LCV  
 Ms Lim Lim Siew Gek  
 Blk 1 Pandan Valley  
 #06-105

Singapore 597625

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 07/05/2018

WIP No. : 59406

Veh.In/Out:

\*Tel.No. : Mobile: 97727246

Reg.No. : SLN9211H

Reg.date. : 22/05/2017

Mileage : 0

Chassis No: YV1MV28H0H2436746

Closed by .... : Michelle Ong Siew Be

Svc Consultant :

Remarks ..... : Ms Lim Siew Gek

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TOW COVER REAR V40 1 ✓ MS	1.0 EA	73.90			73.90 S	66.51
	FOG LAMP LHR V40 13- X CRK	1.0 EA	88.90			88.90 S	80.01
	FOG LAMP RHR V40 13- ✓ CRK	1.0 EA	88.90			88.90 S	80.01
	TAILGATE REAR V40 13 ✓ DT	1.0 EA	2144.10			2,144.10 S	1929.69
	WINDSCREEN REAR TINT ✓ NEC	1.0 EA	1288.90			1,288.90 S	X MN
	*D* WINDSCREEN SEALA	2.0 EA	122.10			244.20 S	219.78
	*D* PRIMER GLASS & P	1.0 EA	37.40			37.40 S	33.66
	V001161436/*D* GLASS	1.0 EA	51.30			51.30 S	46.17
	EMBLEM 'VOLVO' REAR	1.0 EA	92.00			92.00 S	82.80
	EMBLEM 'V40' 13-	1.0 EA	84.00			84.00 S	75.60
	EMBLEM 'T2' V40 16- } NEC	1.0 EA	76.60			76.60 S	68.94
	BLIND RIVET 4.0*21MM	10.0 EA	3.00			30.00 S	29.00
	BUMPER CLIP	10.0 EA	4.80			48.00 S	X MN
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40 S	X MN
	ADHESIVE TUBE CHEMIC	2.0 EA	50.00			100.00 S	136.44

Gross Total. 14,261.90

Labour Total 7,880.00  
 Parts Total 6,381.90  
 Package Total 0.00

Net..... 14,261.90  
 GST @ 7.0% 998.33  
 Total..... 15,260.25  
 Paid..... 0.00  
 Please Pay.. 15,260.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

16072.43

16108.87

# SERVICE TAX INVOICE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)  
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X  
3 ANSON ROAD Inv.No. : B&P 7013627 Page 1  
#16-00, SPRINGLEAF TOWER Inv.date. : 28/05/2018  
SINGAPORE 079909 WIP No. : 59406  
Veh.In/Out: 14/05/2018 19/05/2018

Closed by .... : Michelle Ong Siew Be  
Svc Consultant : ACC  
Remarks ..... : Ms Lim Siew Gek

\*Tel.No. : 63896111  
Reg.No. : SLN9211H  
Reg.date : 22/05/2017  
Mileage : 11,438  
Chassis No: YV1MV28H0H2436746

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER,REAR LOWER SPOLIE,REAR BRACKET, REAR SENSOR,REAR BOOT LID, REAR EMBLEM,ETC	0		2400.00	0		2,400.00	S
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,ETC	0		1400.00	0		1,400.00	S
802	TO TRANSFER REAR BOOT LID PARTS	0		250.00	0		250.00	S
802	TO REPLACE REAR WINDSCREEN	0		800.00	0		800.00	S
89994	TO INSTALL REAR WINDSCREEN FIL	0		280.00	0		280.00	S
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRCIAL MODULES	0		450.00	0		450.00	S
039820427	V039814190/BUMPER CO	1.0	EA	1186.50	10		1,067.85	S
031395091	BUMPER BRACKET LHR V	1.0	EA	88.70	10		79.83	S
031395092	BUMPER BRACKET RHR V	1.0	EA	88.70	10		79.83	S
039814200	TOW COVER REAR V40 1	1.0	EA	73.90	10		66.51	S

# **SERVICE TAX INVOICE**

O - C00010      SL: CHINA TAIPING INSURANCE (SINGAPORE)  
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD      GST Reg.No:M28920628X  
 3 ANSON ROAD      Inv.No. . : B&P 7013627 Page 2  
 #16-00, SPRINGLEAF TOWER      Inv.date. : 28/05/2018  
 SINGAPORE 079909      WIP No. . : 59406  
                                  Veh.In/Out: 14/05/2018 19/05/2018

Closed by .... : Michelle Ong Siew Be  
 Svc Consultant : ACC  
 Remarks ..... : Ms Lim Siew Gek

\*Tel.No. . : 63896111  
 Reg.No. . : SLN9211H  
 Reg.date. : 22/05/2017  
 Mileage . : 11,438  
 Chassis No: YV1MV28H0H2436746

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
031395550	FOG LAMP LHR V40 13-	1.0	EA	88.90	10		80.01	S
031395551	FOG LAMP RHR V40 13-	1.0	EA	88.90	10		80.01	S
031457727	TAILGATE REAR V40 13	1.0	EA	2144.10	10		1,929.69	S
031299177	*D* WINDSCREEN SEALA	2.0	EA	122.10	10		219.78	S
001161824	*D* PRIMER GLASS & P	1.0	EA	37.40	10		33.66	S
031375637	V001161436/*D* GLASS	1.0	EA	51.30	10		46.17	S
031213612	EMBLEM 'VOLVO' REAR	1.0	EA	92.00	10		82.80	S
031265853	EMBLEM 'V40' 13-	1.0	EA	84.00	10		75.60	S
031391662	EMBLEM 'T2' V40 16-	1.0	EA	76.60	10		68.94	S
000979878	BLIND RIVET 4.0*21MM	10.0	EA	3.00	10		27.00	S
V31670171	ADHESIVE TUBE CHEMIC	2.0	EA	75.80	10		136.44	S
031386759	WINDSCREEN REAR V40	1.0	EA	1288.90	10		1,160.01	S
031283760	BUMPER SPOILER REAR	1.0	EA	486.40	10		437.76	S
031427117	BUMPER HARNESS REAR ?	1.0	EA	105.00	10		94.50	S
031361658	BUMPER INSTALLING MT ?	1.0	EA	83.40	10		75.06	S
000988026	BUMPER CLIP	10.0	EA	4.80	10		43.20	S

JFA  
 NEC ✓  
 NEC ✓  
 NEC ✓  
 NEC ✓  
 NEC ✓

Gross Total. 11,464.65

Labour Total 5,580.00  
 Parts Total 5,984.65  
 Package Total 0.00

Net..... 11,464.65  
 GST @ 7.0% 802.53  
 Total..... 12,267.18  
 Paid..... 0.00  
 Please Pay.. 12,267.18

GST: S=StdRated; O=OutOfScope; Z=ZeroRated  
 Enquiries must be lodged within 14 days from the invoice date  
 This is a computer generated invoice. No signature is required.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	08 May 2018		08 May 2018 17:14 <a href="#">Edit Adj Rpt</a>	<b>S\$11,464.65</b> <a href="#">Edit Estimates</a>	<b>S\$11,464.65</b> <a href="#">View Rpt</a>	<b>Pending for Survey Report</b>




























Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>MASTER CONSTRUCTION WORKS PTE LTD</b> , Co. Reg. No.: 201412175G								
Main Claimant:	<b>LIM SIEW GEK</b>								
Vehicle Reg. No.:	<b>SLN9211H</b>	Date of Loss:	05/05/2018 10:00 - :59 [11 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D02332C02</b>	Policy/Cover Note No.:	DMCVSN3015441801 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBE6679C</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Wearnes Automotive Pte Ltd (Alexandra Road)</b> 249 Alexandra Road, 159935 Alexandra - Tel: 63789370								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Sharon Han</b> - 63896]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Sebastian Yeang Wai Keen</b> ] ... [Final Rpt due 17/05/2018]								
Adj Asg. Remarks:	EST \$15,260.25 , CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
• CHINA_TAIPIING (09/11/2018): Alert - Adj Mandate Revoked - SLN9211H - Claim Handler: Sharon Han									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									












## Claim Documents

\*SLN9211H (SNM18D02332C02)  
[GBE6679C]  
TP  
LIM SIEW GEK  
May 5 2018 10:00AM  
[MASTER CONSTRUCTION WORKS PTE LTD]  
Wearnes Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print					
1	07/05/18 18:10	Accident Statement		Load HTM						
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print					
1	07/05/18 18:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	07/05/18 18:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	07/05/18 18:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	07/05/18 18:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	07/05/18 18:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	07/05/18 18:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	07/05/18 18:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	07/05/18 18:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
2	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
3	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
4	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
5	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
6	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
7	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
8	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
9	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
10	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
11	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
12	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
13	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
14	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
15	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
16	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
17	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
18	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
19	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
20	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
21	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					
22	22/11/18 11:26	General View		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
23	22/11/18 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
24	22/11/18 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
25	22/11/18 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
26	22/11/18 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
27	22/11/18 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
28	22/11/18 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
29	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	22/11/18 14:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/05/18 17:13	REPAIR EST	 Load PDF	
2	08/05/18 17:14	OI GIA REPORT	 Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	07/05/18 18:08	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	07/05/18 18:09	IC,CI,DL [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/11/18 08:25	Supplementary	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	07/05/18 18:10	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	07/05/18 18:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 18:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	07/05/18 18:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	07/05/18 18:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	07/05/18 18:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	07/05/18 18:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	07/05/18 18:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	07/05/18 18:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation				

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	07/05/18 18:08	Sketch Plan	 Load TIF	
2	07/05/18 18:09	IC,CI,DL	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18008464/NTBE2

Date: 23/11/2018

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3015441801

Claimant Vehicle No: SLN9211H Insured Vehicle No: GBE6679C

Date of Loss: 05/05/2018 Nature of Claim: TP Claim No: SNM18D02332C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN9211H**

Make & Model: VOLVO V40, 1.5 T2 (A) Engine No: B4154T52038594

Reg. Date: 22/05/2017 (Man. Year: 2017) Chassis No: YV1MV28H0H2436746

Colour: Gold Odometer: 11435 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,228.87	5,884.65	2,344.22	28.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	5,580.00	2,300.00	29.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,108.87</b>	<b>11,464.65</b>	<b>4,644.22</b>	<b>28.83</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,127.62</b>	<b>802.53</b>	<b>325.09</b>	<b>28.83</b>
<b>Nett Amount (S\$)</b>	<b>17,236.49</b>	<b>12,267.18</b>	<b>4,969.31</b>	<b>28.83</b>

### INSPECTION

Date of Assignment: 08/05/2018

Date Inspected: 14/05/2018 Inspected At: Wearnes Automotive Pte Ltd (Alexandra Road)  
249 Alexandra Road  
Singapore 159935

Estimated Period of Repair: 6.0 days

**Adjuster:** Sebastian Yeang Wai Keen

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2018)
<b>Parts:</b> 144	VOLVO V40 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLN9211H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*V039814190/BUMPER CO	Cracked	1,186.50 FS	*1,067.85 FS
2	1		*BUMPER BRACKET LHR V	Necessary	88.70 FS	*79.83 FS
3	1		*BUMPER BRACKET RHR V	Necessary	88.70 FS	*79.83 FS
4	1		*BUMPER SPOILER REAR	Not Necessary	486.40 FS	*- FS
5	1		*TOW COVER REAR V40 1	Missing	73.90 FS	*66.51 FS
6	1		*FOG LAMP LHR V40 13-	Cracked	88.90 FS	*80.01 FS
7	1		*FOG LAMP RHR V40 13-	Cracked	88.90 FS	*80.01 FS
8	1		*TAILGATE REAR V40 13	Dented	2,144.10 FS	*1,929.69 FS
9	1		*WINDSCREEN REAR TINT	Not Necessary	1,288.90 FS	*- FS
10	2		**D* WINDSCREEN SEALA	Necessary	244.20 FS	*219.78 FS
11	1		**D* PRIMER GLASS & P	Necessary	37.40 FS	*33.66 FS
12	1		*V001161436/*D* GLASS	Necessary	51.30 FS	*46.17 FS
13	1		*EMBLEM VOLVO REAR	Necessary	92.00 FS	*82.80 FS
14	1		*EMBLEM V40 13-	Necessary	84.00 FS	*75.60 FS
15	1		*EMBLEM T2 V40 16-	Necessary	76.60 FS	*68.94 FS
16	10		*BLIND RIVET 4.0*21MM	Necessary	30.00 FS	*27.00 FS
17	10		*BUMPER CLIP	Not Necessary	48.00 FS	*- FS
18	1		*BUMPER INSTALLING MT	Not Necessary	83.40 FS	*- FS
19	2		*ADHESIVE TUBE CHEMIC	Necessary	136.44 FS	*136.44 FS
20	1		*WINDSCREEN REAR V40	Necessary	1,160.01 FS	*1,160.01 FS
21	1		*BUMPER SPOILER REAR	Necessary	437.76 FS	*437.76 FS
22	1		*BUMPER HARNESS REAR	Necessary	94.50 FS	*94.50 FS
23	1		*BUMPER INSTALLING MT	Necessary	75.06 FS	*75.06 FS
24	10		*BUMPER CLIP	Necessary	43.20 FS	*43.20 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **8,228.87**      **5,884.65**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER, REAR LOWER SPOLIE, REAR BRACKET, REAR SENSOR, REAR BOOT LID, REAR EMBLEM, ETC	New	4,000.00	2,400.00
2	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, ETC	New	2,100.00	1,400.00
3	TO TRANSFER REAR BOOT LID PARTS	New	250.00	250.00
4	TO REPLACE REAR WINDSCREEN	New	800.00	800.00
5	TO INSTALL REAR WINDSCREEN FIL	New	280.00	280.00
6	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	450.00	450.00
Gross Labour Cost (\$\$)			<b>7,880.00</b>	<b>5,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >