

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 8/5/2018

Reference: SLV4232M
OPEL MOKKA X
1.6 CDTI 6AT
Make: (LED)

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLV4232M
CHASSIS NO.: W0LJD7EC8HB138890
ENGINE NO.: A3163335GU7X0610

Name of insured : Alpine Car Rental Pte Ltd
Date of accident.: 03/05/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	LHF Door <i>Repair</i>	\$ 1,614.00 <i>+</i>
2	1	LHF Door Protector <i>cut</i>	\$ 175.00 <i>✓</i>
3	1	LHR Door <i>Dented</i>	\$ 1,375.00 <i>-</i>
4	1	LHR Door Protector <i>cut</i>	\$ 175.00 <i>-</i>
5	1	LHR Rocker Panel Moulding <i>cut</i>	\$ 155.00 <i>✓</i>
6	1	LHR Fender Moulding <i>cut</i>	\$ 122.00 <i>✓</i>
7	1	Rear Bumper Lower <i>cut</i>	\$ 714.00 <i>-</i>
8	1	LHR Wheel Hub w bearing <i>new</i>	\$ 446.00 <i>+</i>
9	1	LHR Shock Absorber <i>new</i>	\$ 290.00 <i>X</i>
10	1	Rear Axle <i>new</i>	\$ 2,018.00 <i>+</i>

2716
2444.40
Parts Total: \$ 7,084.00
Less 10%: \$ 708.40
Total : \$ 6,375.60

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 1,950.00 <i>1300</i>
2	Carry out spray painting on accident affected area (\$550 per panel)	\$ 2,200.00 <i>1100</i>

<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
<u>4</u>	To remove and replace LHR under carriage parts	\$ 650.00	✓
<u>5</u>	To conduct 4 wheel alignment	\$ 180.00	80
<u>6</u>	To conduct transfer front/rear door mechanism to new door panel	\$ 70.00	✓
<u>7</u>	To apply door sealant to front and rear door	\$ 80.00	✓

2580

Labour Total : \$ 5,160.00

Others

Other Description

No.	Qty		Price (SGD)	
1	10	Rear bumper lower clip <i>me</i>	\$ 65.00	30
2	10	Door protector clips <i>me</i>	\$ 65.00	30
3	5	Fender Moulding clips <i>me</i>	\$ 32.50	15
4	1	Rear wheel tyre <i>Ne m</i>	\$ 310.00	+
5	1	Rear wheel rim <i>cut</i>	\$ 450.00	✓

527

Other Total: \$ 922.50

GRAND TOTAL: \$ 12,458.10

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

 **Suhaimi Ong**

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax:6844 5185

Adrian Lj
P/P 08/05/18.
04 Pangs.
total: 5549.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: