

REPAIR ESTIMATE*

VEHICLE NO : SHA 3508H

DATE 8/5/2018 13:55

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid ✓			\$ 1,349.50	
	Boot Lid Rubber ✕			\$ 110.90	
	Boot Lid Lock Upper ✕			\$ 132.10	
	Boot Lid Lock Lower ✕			\$ 30.30	
	Boot Lid Sonata Plate ✓			\$ 43.60	
	Boot Lid Hyundai Plate ✓			\$ 24.20	
	Boot Lid 'H' Emblem ✓			\$ 26.10	
	Boot Lid CRDI Plate ✓			\$ 22.70	
	Boot Lid Lamp (LH) ✕			\$ 230.20	
	Rear Bumper ✓			\$ 578.40	
	Rear Bumper Reinforcement ✓			\$ 483.30	
	Rear Bumper Clip ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover ✕			\$ 185.80	
	Rear Bumper Protector (LH/RH) ✕ repair		\$ 38.00	\$ 76.00	
	Rear Panel ✕ repair			\$ 391.80	
	Rear Panel Garnish ✕			\$ 95.80	
	SUB TOTAL			\$ 3,940.10	
	LESS 20%			\$ 788.02	
	DISCOUNTED TOTAL			\$ 3,152.08	
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00	Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
				\$ 165.70	
	Labour Charge				
	Panel Beating			\$ 850.00 400	
	Spray Painting Charge			\$ 600.00 580	
	Wiring Charge			\$ 50.00 ✕	
	Tuff Kote			\$ 50.00 20	
	Remove/Refix Reverse Sensor			\$ 120.00 20	
	TOTAL LABOUR			\$ 1,670.00	
	ESTIMATE TOTAL			\$ 4,987.78	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

