

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 07/05/2018

TP Veh Reg No: SKS5399L

Estimate No: ES1890505/AMK

Date: 09 May 2018

Policy No: PNPV2017-00009130

Veh Reg No: SGB8798K

Make/Model: TOYOTA WISH 1.8 A

Chassis No: ZNE100273429

Engine No: 1ZZ2411387

Reg. Date: 30/12/2005

Estimate Repair Cost to Vehicle No :SGB8798K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	495.70	1 PC	495.70	✓
2 REAR BUMPER CLIP	3.50	4 PC	14.00	✓
3 REAR TAILGATE	1,273.10	1 PC	1,273.10	✓
4 TAILGATE INNER RUBBER	319.30	1 PC	319.30	50% ✓
5 TAILGATE INNER LOCK	465.60	1 PC	465.60	✓
6 TAILGATE LOGO	50.20	1 PC	50.20	✓
7 TAILGATE NUMBER PLATE LAMP GARNISH	218.68	1 PC	218.68	✓
8 TAILGATE WINDSCREEN GLASS MOULDING	79.20	1 PC	79.20	✓
9 TAILGATE INNER TRIM BOARD	328.20	1 PC	328.20	✓
10 REAR END PANEL	463.20	1 PC	463.20	✓
11 REAR END PANEL INNER TOP GARNISH	245.00	1 PC	245.00	✓
			3,952.18	
		Less 25%	988.05	2,964.14
Special Net				
12 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
13 REVERSE SENSOR	200.00	1 SET	200.00	✓
14 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
			275.00	275.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
16 REMOVE & REFIX REAR BUMPER, TAILGATE & ATTACHMENTS, TAILLAMP; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR FENDERS, REAR LUGGAGE PANEL & REALIGN THE SAME	800.00	1 LA	800.00	✓
17 PUTTY & RESPRAY REAR BUMPER, TAILGATE & SPOILER, REAR END PANEL, REAR LUGGAGE PANEL, REAR FENDERS & ALL AFFECTED AREAS	900.00	1 LA	900.00	60% ✓
18 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,880.00	1,880.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO.201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 07/05/2018
TP Veh Reg No: SKS5399L

Estimate No: ES1890505/AMK
Date: 09 May 2018
Policy No: PNPV2017-00009130
Veh Reg No: SGB8798K
Make/Model: TOYOTA WISH 1.8 A
Chassis No: ZNE100273429
Engine No: 1ZZ2411387
Reg. Date: 30/12/2005

Estimate Repair Cost to Vehicle No :SGB8798K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 5,119.14
			Add GST @ 7%	358.34
			Total Amount Payable	<u><u>S\$ 5,477.48</u></u>

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE